

Texcharge TC

Fujifilm Sericol Formulation Guide

Version 1.0

- SMS Base Colors



SERICOL
More than ink...Solutions.

FUJIFILM

Texcharge TC

Fujifilm Sericol Formulation Guide

This booklet furnishes the starting formulas to simulate colors from the PANTONE® Color Guide. The formulas used in this guide are starting formulas and simulations of PANTONE®* references using Texcharge TC inks.

Each formula was printed using a common textile mesh counts (from 110-180 threads per inch). All formulas are presented by weight. Due to variations in fabrics, inks film thickness, and print procedures, formulas will have to be checked and/or adjusted to meet print shop conditions.

Each Base Color has been carefully selected for its cleanliness of tone, resistance to fading, and suitability for intermixing.

Although every care is taken in producing these formulations, variations in fabrics and printing conditions may affect the color achieved. Fujifilm Sericol Inc. assumes no responsibility for actual color achieved versus the PANTONE®* standard print. For this reason, all formulations must be proofed prior to a production run to ensure color accuracy.

All formulations are percentages by weight using the following Texcharge TC Series colors:

DESCRIPTION	
TC-001 Black	TC-132 SMS Violet
TC-021 White	TC-153 SMS Red Blue Shade
TC-046 SMS Yellow Red Shade	TC-154 SMS Magenta
TC-057 SMS Yellow Green Shade	TC-218 SMS Blue
TC-103 SMS Orange	TC-316 SMS Green
TC-122 SMS Red Yellow Shade	TC-381 Extender Base

Fujifilm Sericol USA Inc's color mixing ink formulations for screen process printing produce only simulations of PANTONE Colors in this color reproduction method due to differences in ink film, opacity and pigment selection. The selection used in blending inks may cause metamerism. Pantone, Inc. assumes no responsibility for formula accuracy.

*PANTONE® is the property of Pantone Inc.

Texcharge TC

PANTONE Yellow 012 C	Formula
TC-057 76.52	
TC-381 17.67	
TC-046 5.81	

PANTONE Process Yellow C	Formula
TC-057 66.67	
TC-021 33.33	

PANTONE Process Magenta C	Formula
TC-154 53.85	
TC-381 42.31	
TC-021 2.30	
TC-057 1.54	

PANTONE Process Cyan C	Formula
TC-021 88.39	
TC-218 10.83	
TC-316 0.78	

PANTONE Process Black C	Formula
TC-001 75.00	
TC-046 25.00	

PANTONE 100 C	Formula
TC-057 76.52	
TC-381 17.67	
TC-046 5.81	

PANTONE 101 C	Formula
TC-021 69.03	
TC-057 29.81	
TC-046 1.16	

PANTONE 102 C	Formula
TC-021 52.59	
TC-057 45.44	
TC-046 1.97	

PANTONE Yellow C	Formula
TC-057 70.97	
TC-381 29.03	

PANTONE 103 C	Formula
TC-057 88.50	
TC-021 7.15	
TC-046 4.09	
TC-001 0.26	

PANTONE 104 C	Formula
TC-057 75.14	
TC-021 18.36	
TC-046 5.73	
TC-001 0.77	

PANTONE 105 C	Formula
TC-057 60.15	
TC-381 35.88	
TC-001 2.71	
TC-103 1.26	

PANTONE 106 C	Formula
TC-021 75.90	
TC-057 22.70	
TC-046 1.40	

PANTONE 107 C	Formula
TC-057 63.40	
TC-021 34.30	
TC-046 2.30	

PANTONE 108 C	Formula
TC-057 80.00	
TC-021 15.00	
TC-046 5.00	

PANTONE 109 C	Formula
TC-057 93.10	
TC-046 6.90	

Texcharge TC

PANTONE 110 C	Formula
TC-057	90.60
TC-046	9.00
TC-001	0.40

PANTONE 111 C	Formula
TC-057	91.00
TC-046	6.80
TC-103	1.10
TC-001	0.90
TC-316	0.2

PANTONE 112 C	Formula
TC-057	90.50
TC-046	6.80
TC-001	1.30
TC-103	1.10
TC-316	0.3

PANTONE 113 C	Formula
TC-021	88.20
TC-057	9.20
TC-046	2.60

PANTONE 114 C	Formula
TC-021	82.50
TC-057	14.60
TC-046	2.90

PANTONE 115 C	Formula
TC-021	69.30
TC-057	25.70
TC-046	5.00

PANTONE 116 C	Formula
TC-057	65.00
TC-021	25.00
TC-046	10.00

PANTONE 117 C	Formula
TC-057	58.50
TC-046	29.30
TC-021	11.80
TC-316	0.20
TC-001	0.2

PANTONE 118 C	Formula
TC-057	59.00
TC-046	39.30
TC-316	0.70
TC-103	0.50
TC-001	0.5

PANTONE 119 C	Formula
TC-046	47.60
TC-057	47.60
TC-021	2.40
TC-316	1.60
TC-103	0.8

PANTONE 120 C	Formula
TC-021	96.60
TC-057	2.10
TC-046	1.10
TC-103	0.20

PANTONE 121 C	Formula
TC-021	94.20
TC-057	3.40
TC-046	2.20
TC-103	0.20

PANTONE 122 C	Formula
TC-021	89.70
TC-046	6.80
TC-057	3.40
TC-103	0.10

PANTONE 123 C	Formula
TC-057	49.80
TC-021	30.20
TC-046	19.50
TC-103	0.50

PANTONE 124 C	Formula
TC-057	61.20
TC-046	36.80
TC-103	1.80
TC-001	0.20

PANTONE 125 C	Formula
TC-046	99.06
TC-001	0.59
TC-316	0.35

Texcharge TC

PANTONE 126 C	Formula
TC-057	49.40
TC-046	47.80
TC-316	1.40
TC-001	1.00
TC-103	0.4

PANTONE 1205 C	Formula
TC-381	65.65
TC-021	33.33
TC-057	0.80
TC-103	0.12
TC-046	0.1

PANTONE 1215 C	Formula
TC-021	96.30
TC-057	3.30
TC-103	0.40

PANTONE 1225 C	Formula
TC-021	88.50
TC-046	11.00
TC-103	0.50

PANTONE 1235 C	Formula
TC-057	96.77
TC-103	2.51
TC-122	0.72

PANTONE 1245 C	Formula
TC-057	57.60
TC-046	41.40
TC-103	0.50
TC-001	0.50

PANTONE 1255 C	Formula
TC-057	57.80
TC-046	40.80
TC-001	0.90
TC-103	0.50

PANTONE 1265 C	Formula
TC-057	58.40
TC-381	33.15
TC-103	5.37
TC-001	3.08

PANTONE 127 C	Formula
TC-021	95.40
TC-057	2.20
TC-046	2.00
TC-103	0.30
TC-316	0.1

PANTONE 128 C	Formula
TC-021	91.80
TC-057	4.60
TC-046	3.10
TC-103	0.30
TC-316	0.2

PANTONE 129 C	Formula
TC-021	79.70
TC-057	11.90
TC-046	8.00
TC-103	0.30
TC-316	0.1

PANTONE 130 C	Formula
TC-046	80.00
TC-021	20.00

PANTONE 131 C	Formula
TC-046	98.20
TC-103	1.40
TC-001	0.30
TC-316	0.10

PANTONE 132 C	Formula
TC-057	57.20
TC-046	41.30
TC-001	0.80
TC-103	0.70

PANTONE 133 C	Formula
TC-046	75.10
TC-103	18.80
TC-316	6.10

PANTONE 134 C	Formula
TC-021	96.57
TC-046	3.22
TC-103	0.21

Texcharge TC

PANTONE 135 C	Formula
TC-021	93.50
TC-046	5.56
TC-103	0.94

PANTONE 136 C	Formula
TC-021	87.08
TC-046	10.84
TC-103	2.08

PANTONE 137 C	Formula
TC-046	66.32
TC-021	28.49
TC-103	5.19

PANTONE 138 C	Formula
TC-046	76.15
TC-021	15.49
TC-103	8.11
TC-001	0.25

PANTONE 139 C	Formula
TC-046	91.00
TC-057	4.20
TC-103	4.20
TC-001	0.60

PANTONE 140 C	Formula
TC-046	88.10
TC-103	8.80
TC-316	1.80
TC-001	1.30

PANTONE 1345 C	Formula
TC-381	97.14
TC-057	1.45
TC-046	1.16
TC-122	0.25

PANTONE 1355 C	Formula
TC-021	95.70
TC-057	2.10
TC-046	1.10
TC-103	1.10

PANTONE 1365 C	Formula
TC-021	86.50
TC-046	9.00
TC-103	2.70
TC-057	1.80

PANTONE 1375 C	Formula
TC-381	52.01
TC-057	41.35
TC-046	5.34
TC-122	1.30

PANTONE 1385 C	Formula
TC-046	89.20
TC-103	10.40
TC-001	0.40

PANTONE 1395 C	Formula
TC-046	89.90
TC-103	8.80
TC-001	1.30

PANTONE 1405 C	Formula
TC-381	50.59
TC-046	24.70
TC-154	18.83
TC-316	4.12
TC-001	1.76

PANTONE 141 C	Formula
TC-021	90.90
TC-057	7.80
TC-103	1.20
TC-316	0.10

PANTONE 142 C	Formula
TC-021	81.50
TC-046	9.50
TC-057	6.80
TC-103	1.90
TC-316	0.3

PANTONE 143 C	Formula
TC-021	65.10
TC-046	16.30
TC-057	16.30
TC-103	2.10
TC-316	0.2

Texcharge TC

PANTONE 144 C	Formula
TC-046 91.80	
TC-103 8.00	
TC-001 0.20	

PANTONE 145 C	Formula
TC-046 93.50	
TC-103 6.10	
TC-001 0.40	

PANTONE 146 C	Formula
TC-046 91.20	
TC-103 7.70	
TC-001 1.10	

PANTONE 147 C	Formula
TC-046 73.90	
TC-103 19.50	
TC-316 5.90	
TC-001 0.70	

PANTONE 148 C	Formula
TC-021 97.20	
TC-103 1.30	
TC-057 0.80	
TC-046 0.70	

PANTONE 149 C	Formula
TC-021 96.20	
TC-103 1.90	
TC-046 1.50	
TC-057 0.40	

PANTONE 150 C	Formula
TC-021 81.90	
TC-046 11.70	
TC-103 6.40	

PANTONE 151 C	Formula
TC-046 76.90	
TC-103 23.10	

PANTONE 152 C	Formula
TC-046 63.40	
TC-057 18.10	
TC-103 18.10	
TC-001 0.40	

PANTONE 153 C	Formula
TC-046 82.00	
TC-103 17.00	
TC-001 1.00	

PANTONE 154 C	Formula
TC-046 73.80	
TC-103 24.60	
TC-001 1.60	

PANTONE 1485 C	Formula
TC-381 93.20	
TC-021 4.85	
TC-103 1.46	
TC-046 0.49	

PANTONE 1495 C	Formula
TC-021 86.50	
TC-103 6.70	
TC-046 3.80	
TC-057 3.00	

PANTONE 1505 C	Formula
TC-057 59.10	
TC-046 21.50	
TC-103 19.40	

PANTONE Orange 021 C	Formula
TC-057 66.19	
TC-103 28.86	
TC-122 4.95	

PANTONE 1525 C	Formula
TC-103 50.50	
TC-046 48.90	
TC-001 0.60	

Texcharge TC

PANTONE 1535 C	Formula
TC-103 55.00	
TC-046 44.00	
TC-001 1.00	

PANTONE 1545 C	Formula
TC-103 74.95	
TC-001 14.85	
TC-122 10.20	

PANTONE 155 C	Formula
TC-021 99.10	
TC-046 0.50	
TC-057 0.30	
TC-153 0.10	

PANTONE 156 C	Formula
TC-021 96.90	
TC-057 2.00	
TC-046 0.80	
TC-153 0.20	
TC-001 0.1	

PANTONE 157 C	Formula
TC-021 80.50	
TC-057 14.50	
TC-103 4.60	
TC-153 0.30	
TC-001 0.1	

PANTONE 158 C	Formula
TC-057 76.60	
TC-103 23.20	
TC-001 0.20	

PANTONE 159 C	Formula
TC-057 66.50	
TC-103 33.20	
TC-001 0.30	

PANTONE 160 C	Formula
TC-057 69.20	
TC-103 29.60	
TC-001 1.20	

PANTONE 161 C	Formula
TC-057 67.00	
TC-103 28.70	
TC-001 3.80	
TC-316 0.50	

PANTONE 1555 C	Formula
TC-021 96.20	
TC-057 1.60	
TC-103 1.60	
TC-122 0.60	

PANTONE 1565 C	Formula
TC-021 93.60	
TC-103 3.60	
TC-046 2.10	
TC-122 0.70	

PANTONE 1575 C	Formula
TC-021 87.00	
TC-103 8.70	
TC-046 3.50	
TC-122 0.80	

PANTONE 1585 C	Formula
TC-021 64.10	
TC-103 25.60	
TC-046 9.00	
TC-122 1.30	

PANTONE 1595 C	Formula
TC-046 48.80	
TC-103 41.60	
TC-057 8.80	
TC-122 0.40	
TC-001 0.4	

PANTONE 1605 C	Formula
TC-046 64.50	
TC-103 32.30	
TC-122 2.20	
TC-001 1.00	

PANTONE 1615 C	Formula
TC-103 52.20	
TC-046 43.50	
TC-122 2.60	
TC-001 1.70	

Texcharge TC

PANTONE 162 C	Formula
TC-021	78.83
TC-381	19.70
TC-122	0.59
TC-046	0.59
TC-103	0.29

PANTONE 163 C	Formula
TC-021	92.30
TC-103	3.80
TC-057	2.50
TC-122	1.40

PANTONE 164 C	Formula
TC-021	74.40
TC-046	14.00
TC-103	5.60
TC-122	5.10
TC-057	0.9

PANTONE 165 C	Formula
TC-381	70.31
TC-046	21.28
TC-122	8.12
TC-153	0.29

PANTONE 166 C	Formula
TC-046	50.70
TC-103	46.60
TC-122	2.50
TC-001	0.20

PANTONE 167 C	Formula
TC-046	56.00
TC-103	39.20
TC-122	4.20
TC-001	0.60

PANTONE 168 C	Formula
TC-381	44.48
TC-046	31.16
TC-122	13.77
TC-103	5.35
TC-001	5.24

PANTONE 1625 C	Formula
TC-021	95.90
TC-103	1.90
TC-122	1.40
TC-057	0.80

PANTONE 1635 C	Formula
TC-021	92.20
TC-103	4.20
TC-057	1.80
TC-122	1.80

PANTONE 1645 C	Formula
TC-021	80.50
TC-046	8.50
TC-122	5.90
TC-103	5.10

PANTONE 1655 C	Formula
TC-046	60.90
TC-103	30.40
TC-122	8.70

PANTONE 1665 C	Formula
TC-103	53.10
TC-046	42.50
TC-122	4.20
TC-001	0.20

PANTONE 1675 C	Formula
TC-103	58.50
TC-046	35.00
TC-122	5.80
TC-001	0.70

PANTONE 1685 C	Formula
TC-103	68.50
TC-046	22.90
TC-122	6.90
TC-001	1.70

PANTONE 169 C	Formula
TC-021	96.95
TC-057	1.40
TC-122	1.15
TC-103	0.30
TC-153	0.2

PANTONE 170 C	Formula
TC-021	93.90
TC-122	2.80
TC-103	2.30
TC-057	1.00

Texcharge TC

PANTONE 171 C	Formula
TC-021	71.40
TC-103	14.30
TC-122	14.30

PANTONE 172 C	Formula
TC-046	60.00
TC-103	20.00
TC-122	20.00

PANTONE 173 C	Formula
TC-103	56.90
TC-122	19.00
TC-021	14.20
TC-057	9.40
TC-001	0.5

PANTONE 174 C	Formula
TC-103	70.40
TC-122	28.20
TC-001	1.40

PANTONE 175 C	Formula
TC-103	88.60
TC-153	8.90
TC-001	2.10
TC-316	0.40

PANTONE 176 C	Formula
TC-381	53.07
TC-021	45.95
TC-122	0.74
TC-103	0.24

PANTONE 177 C	Formula
TC-021	93.10
TC-122	4.90
TC-057	1.50
TC-153	0.50

PANTONE 178 C	Formula
TC-021	49.40
TC-381	37.10
TC-122	12.30
TC-103	1.20

PANTONE Warm Red C	Formula
TC-381	66.52
TC-103	16.22
TC-122	14.96
TC-153	2.30

PANTONE 179 C	Formula
TC-021	35.00
TC-122	35.00
TC-103	26.30
TC-153	3.50
TC-316	0.2

PANTONE 180 C	Formula
TC-021	51.30
TC-103	32.90
TC-153	15.30
TC-316	0.50

PANTONE 181 C	Formula
TC-381	49.12
TC-122	38.39
TC-046	9.82
TC-001	2.67

PANTONE 1765 C	Formula
TC-381	51.14
TC-021	46.86
TC-122	1.20
TC-153	0.67
TC-103	0.13

PANTONE 1775 C	Formula
TC-021	95.50
TC-122	2.30
TC-057	1.10
TC-153	1.10

PANTONE 1785 C	Formula
TC-021	53.60
TC-381	29.00
TC-122	14.50
TC-153	2.90

PANTONE 1788 C	Formula
TC-103	32.50
TC-021	31.70
TC-153	19.50
TC-381	16.30

Texcharge TC

PANTONE 1795 C	Formula
TC-021	38.60
TC-103	37.60
TC-153	23.80

PANTONE 1805 C	Formula
TC-021	39.10
TC-103	37.00
TC-153	23.60
TC-001	0.30

PANTONE 1815 C	Formula
TC-021	43.20
TC-103	27.70
TC-153	27.70
TC-001	1.40

PANTONE 1767 C	Formula
TC-381	98.50
TC-122	0.79
TC-057	0.50
TC-153	0.21

PANTONE 1777 C	Formula
TC-021	86.20
TC-122	12.10
TC-153	1.70

PANTONE 1787 C	Formula
TC-021	58.00
TC-103	24.00
TC-153	18.00

PANTONE Red 032 C	Formula
TC-381	68.96
TC-122	17.24
TC-103	6.90
TC-153	6.90

PANTONE 1797 C	Formula
TC-103	37.80
TC-021	36.80
TC-153	25.20
TC-001	0.20

PANTONE 1807 C	Formula
TC-021	32.10
TC-103	30.40
TC-154	20.50
TC-153	16.40
TC-001	0.6

PANTONE 1817 C	Formula
TC-122	50.00
TC-046	25.00
TC-381	16.67
TC-001	8.33

PANTONE 182 C	Formula
TC-021	99.10
TC-153	0.80
TC-046	0.10

PANTONE 183 C	Formula
TC-021	94.80
TC-153	4.73
TC-046	0.47

PANTONE 184 C	Formula
TC-021	87.60
TC-153	10.21
TC-046	1.46
TC-122	0.73

PANTONE 185 C	Formula
TC-122	83.33
TC-153	16.67

PANTONE 186 C	Formula
TC-122	62.50
TC-153	37.50

PANTONE 187 C	Formula
TC-122	62.20
TC-153	37.30
TC-001	0.50

Texcharge TC

PANTONE 188 C	Formula
TC-122 60.97	
TC-153 36.60	
TC-001 2.43	

PANTONE 189 C	Formula
TC-021 95.09	
TC-154 3.96	
TC-103 0.95	

PANTONE 190 C	Formula
TC-021 88.56	
TC-154 8.86	
TC-103 2.58	

PANTONE 191 C	Formula
TC-021 78.40	
TC-153 19.60	
TC-103 2.00	

PANTONE 192 C	Formula
TC-122 41.67	
TC-153 33.33	
TC-021 25.00	

PANTONE 193 C	Formula
TC-122 41.58	
TC-153 33.25	
TC-021 24.93	
TC-001 0.24	

PANTONE 194 C	Formula
TC-122 41.25	
TC-153 33.00	
TC-021 24.75	
TC-001 1.00	

PANTONE 195 C	Formula
TC-122 40.65	
TC-153 32.52	
TC-021 24.40	
TC-001 2.43	

PANTONE 1895 C	Formula
TC-021 70.02	
TC-381 29.17	
TC-122 0.58	
TC-153 0.23	

PANTONE 1905 C	Formula
TC-021 94.35	
TC-154 4.71	
TC-103 0.94	

PANTONE 1915 C	Formula
TC-021 83.34	
TC-154 8.34	
TC-122 4.16	
TC-153 4.16	

PANTONE 1925 C	Formula
TC-381 72.53	
TC-153 16.48	
TC-122 10.99	

PANTONE 1935 C	Formula
TC-153 57.15	
TC-154 28.57	
TC-021 14.28	

PANTONE 1945 C	Formula
TC-153 58.70	
TC-154 23.47	
TC-021 17.60	
TC-001 0.23	

PANTONE 1955 C	Formula
TC-154 43.28	
TC-381 34.62	
TC-153 17.32	
TC-103 4.33	
TC-001 0.45	

PANTONE 196 C	Formula
TC-021 99.30	
TC-122 0.50	
TC-103 0.10	
TC-001 0.10	

Texcharge TC

PANTONE 197 C	Formula
TC-021 97.20	
TC-122 2.40	
TC-103 0.20	
TC-001 0.20	

PANTONE 198 C	Formula
TC-021 83.20	
TC-122 10.30	
TC-154 6.40	
TC-001 0.10	

PANTONE 199 C	Formula
TC-381 64.00	
TC-153 25.00	
TC-122 11.00	

PANTONE 200 C	Formula
TC-153 60.99	
TC-021 30.48	
TC-122 8.53	

PANTONE 201 C	Formula
TC-153 81.10	
TC-021 18.60	
TC-001 0.30	

PANTONE 202 C	Formula
TC-153 98.60	
TC-001 1.40	

PANTONE 203 C	Formula
TC-021 97.85	
TC-154 1.95	
TC-103 0.20	

PANTONE 204 C	Formula
TC-021 90.27	
TC-154 9.00	
TC-103 0.73	

PANTONE 205 C	Formula
TC-021 78.76	
TC-154 15.74	
TC-153 3.93	
TC-103 1.57	

PANTONE 206 C	Formula
TC-153 33.33	
TC-154 26.67	
TC-381 26.67	
TC-021 13.33	

PANTONE 207 C	Formula
TC-153 33.28	
TC-154 26.61	
TC-381 26.61	
TC-021 13.30	
TC-001 0.2	

PANTONE 208 C	Formula
TC-153 33.00	
TC-154 26.40	
TC-381 26.40	
TC-021 13.20	
TC-001 1	

PANTONE 209 C	Formula
TC-153 32.67	
TC-154 26.15	
TC-381 26.15	
TC-021 13.07	
TC-001 1.96	

PANTONE 210 C	Formula
TC-021 95.90	
TC-154 2.30	
TC-153 1.80	

PANTONE 211 C	Formula
TC-021 90.90	
TC-154 4.90	
TC-153 4.20	

PANTONE 212 C	Formula
TC-381 85.50	
TC-154 11.70	
TC-153 2.80	

Texcharge TC

PANTONE 213 C	Formula
TC-381 63.90	
TC-154 27.70	
TC-153 8.40	

PANTONE 214 C	Formula
TC-154 64.70	
TC-381 26.00	
TC-153 9.30	

PANTONE 215 C	Formula
TC-154 80.90	
TC-153 18.40	
TC-218 0.70	

PANTONE 216 C	Formula
TC-154 66.20	
TC-153 31.00	
TC-218 2.80	

PANTONE 217 C	Formula
TC-021 99.20	
TC-154 0.47	
TC-153 0.33	

PANTONE 218 C	Formula
TC-021 90.80	
TC-154 8.30	
TC-153 0.90	

PANTONE 219 C	Formula
TC-021 66.30	
TC-154 29.80	
TC-153 3.90	

PANTONE Rubine Red C	Formula
TC-154 44.55	
TC-381 39.60	
TC-153 15.85	

PANTONE 220 C	Formula
TC-154 100.00	

PANTONE 221 C	Formula
TC-154 80.90	
TC-153 15.80	
TC-132 3.30	

PANTONE 222 C	Formula
TC-154 79.80	
TC-103 15.23	
TC-218 4.97	

PANTONE 223 C	Formula
TC-021 95.00	
TC-154 4.90	
TC-153 0.10	

PANTONE 224 C	Formula
TC-021 84.30	
TC-154 15.20	
TC-153 0.50	

PANTONE 225 C	Formula
TC-021 66.80	
TC-154 32.70	
TC-153 0.50	

PANTONE 226 C	Formula
TC-381 58.50	
TC-154 41.50	

PANTONE 227 C	Formula
TC-154 71.10	
TC-381 25.10	
TC-153 3.40	
TC-218 0.40	

Texcharge TC

PANTONE 228 C	Formula
TC-154 92.10	
TC-153 4.60	
TC-218 3.30	

PANTONE 229 C	Formula
TC-154 52.60	
TC-153 34.20	
TC-132 13.20	

PANTONE 230 C	Formula
TC-381 74.43	
TC-021 23.01	
TC-154 1.95	
TC-122 0.61	

PANTONE 231 C	Formula
TC-381 54.80	
TC-021 32.00	
TC-154 13.20	

PANTONE 232 C	Formula
TC-381 51.40	
TC-021 25.40	
TC-154 23.20	

PANTONE Rhodamine Red C	Formula
TC-381 82.74	
TC-154 16.85	
TC-122 0.41	

PANTONE 233 C	Formula
TC-381 54.70	
TC-153 45.00	
TC-132 0.30	

PANTONE 234 C	Formula
TC-154 97.60	
TC-132 2.40	

PANTONE 235 C	Formula
TC-154 93.28	
TC-153 3.73	
TC-132 2.99	

PANTONE 236 C	Formula
TC-021 96.30	
TC-154 3.70	

PANTONE 237 C	Formula
TC-021 86.60	
TC-154 13.40	

PANTONE 238 C	Formula
TC-381 53.70	
TC-021 26.60	
TC-154 19.60	
TC-132 0.10	

PANTONE 239 C	Formula
TC-381 73.80	
TC-154 26.00	
TC-132 0.20	

PANTONE 240 C	Formula
TC-381 66.30	
TC-154 32.60	
TC-132 1.10	

PANTONE 241 C	Formula
TC-154 63.80	
TC-021 33.70	
TC-132 2.50	

PANTONE 242 C	Formula
TC-154 91.00	
TC-132 5.20	
TC-153 3.80	

Texcharge TC

PANTONE 2365 C	Formula
TC-021 99.18	
TC-154 0.82	

PANTONE 2375 C	Formula
TC-021 86.83	
TC-154 13.00	
TC-218 0.17	

PANTONE 2385 C	Formula
TC-021 76.70	
TC-154 23.00	
TC-218 0.30	

PANTONE 2395 C	Formula
TC-381 39.92	
TC-154 39.92	
TC-021 19.96	
TC-218 0.20	

PANTONE 2405 C	Formula
TC-154 82.37	
TC-021 16.48	
TC-218 1.15	

PANTONE 2415 C	Formula
TC-154 82.25	
TC-021 16.44	
TC-218 1.31	

PANTONE 2425 C	Formula
TC-154 81.97	
TC-021 16.40	
TC-218 1.63	

PANTONE 243 C	Formula
TC-021 98.62	
TC-154 1.38	

PANTONE 244 C	Formula
TC-021 97.08	
TC-154 2.92	

PANTONE 245 C	Formula
TC-021 91.76	
TC-154 7.33	
TC-218 0.91	

PANTONE 246 C	Formula
TC-381 55.20	
TC-021 22.07	
TC-154 22.07	
TC-132 0.66	

PANTONE 247 C	Formula
TC-381 54.94	
TC-154 21.98	
TC-021 21.98	
TC-132 1.10	

PANTONE 248 C	Formula
TC-381 59.95	
TC-154 23.98	
TC-021 12.00	
TC-132 2.87	
TC-153 1.2	

PANTONE 249 C	Formula
TC-154 70.00	
TC-021 28.00	
TC-001 2.00	

PANTONE 250 C	Formula
TC-381 99.40	
TC-154 0.50	
TC-132 0.10	

PANTONE 251 C	Formula
TC-021 95.20	
TC-154 4.30	
TC-132 0.50	

Texcharge TC

PANTONE 252 C	Formula
TC-021 50.56	
TC-381 39.33	
TC-154 8.43	
TC-132 1.68	

PANTONE Purple C	Formula
TC-381 49.50	
TC-021 25.14	
TC-154 23.68	
TC-132 1.68	

PANTONE 253 C	Formula
TC-381 49.40	
TC-154 24.30	
TC-021 23.70	
TC-132 2.60	

PANTONE 254 C	Formula
TC-381 40.40	
TC-154 33.00	
TC-021 22.40	
TC-132 4.20	

PANTONE 255 C	Formula
TC-021 46.16	
TC-154 30.77	
TC-132 15.38	
TC-153 7.69	

PANTONE 256 C	Formula
TC-021 98.35	
TC-132 1.11	
TC-122 0.34	
TC-153 0.10	
TC-001 0.1	

PANTONE 257 C	Formula
TC-021 97.80	
TC-132 1.50	
TC-153 0.70	

PANTONE 258 C	Formula
TC-021 83.80	
TC-132 7.20	
TC-153 4.50	
TC-154 4.50	

PANTONE 259 C	Formula
TC-021 47.79	
TC-154 36.76	
TC-132 10.30	
TC-153 5.15	

PANTONE 260 C	Formula
TC-154 44.40	
TC-021 23.50	
TC-132 20.80	
TC-153 11.30	

PANTONE 261 C	Formula
TC-154 43.60	
TC-132 19.70	
TC-021 18.90	
TC-153 17.80	

PANTONE 262 C	Formula
TC-154 41.00	
TC-132 34.40	
TC-153 24.60	

PANTONE 2562 C	Formula
TC-021 98.00	
TC-132 1.00	
TC-154 1.00	

PANTONE 2572 C	Formula
TC-021 93.47	
TC-154 3.73	
TC-132 2.80	

PANTONE 2582 C	Formula
TC-021 81.96	
TC-154 12.30	
TC-132 5.74	

PANTONE 2592 C	Formula
TC-381 45.45	
TC-154 27.27	
TC-021 18.18	
TC-132 9.10	

Texcharge TC

PANTONE 2602 C	Formula
TC-381 51.54	
TC-021 20.62	
TC-154 20.62	
TC-132 7.22	

PANTONE 2612 C	Formula
TC-154 53.20	
TC-021 31.90	
TC-132 14.90	

PANTONE 2622 C	Formula
TC-154 61.42	
TC-021 26.31	
TC-132 8.77	
TC-001 3.50	

PANTONE 2563 C	Formula
TC-021 95.40	
TC-154 3.00	
TC-132 1.60	

PANTONE 2573 C	Formula
TC-021 89.50	
TC-154 7.00	
TC-132 3.50	

PANTONE 2583 C	Formula
TC-021 48.00	
TC-381 28.00	
TC-154 16.00	
TC-132 8.00	

PANTONE 2593 C	Formula
TC-154 35.71	
TC-381 30.61	
TC-132 18.37	
TC-021 15.31	

PANTONE 2603 C	Formula
TC-154 57.14	
TC-381 22.86	
TC-132 20.00	

PANTONE 2613 C	Formula
TC-154 65.80	
TC-132 23.00	
TC-381 11.20	

PANTONE 2623 C	Formula
TC-154 78.00	
TC-132 22.00	

PANTONE 2567 C	Formula
TC-021 96.62	
TC-132 2.41	
TC-154 0.97	

PANTONE 2577 C	Formula
TC-021 93.47	
TC-132 4.67	
TC-154 1.86	

PANTONE 2587 C	Formula
TC-021 46.53	
TC-381 29.70	
TC-132 12.87	
TC-154 10.90	

PANTONE 2597 C	Formula
TC-381 66.20	
TC-154 16.94	
TC-132 16.86	

PANTONE 2607 C	Formula
TC-132 34.48	
TC-381 34.48	
TC-154 31.04	

PANTONE 2617 C	Formula
TC-132 35.29	
TC-154 35.29	
TC-381 29.42	

Texcharge TC

PANTONE 2627 C	Formula
TC-132 46.10	
TC-154 38.50	
TC-381 15.40	

PANTONE 263 C	Formula
TC-021 99.40	
TC-132 0.60	

PANTONE 264 C	Formula
TC-021 97.86	
TC-132 1.95	
TC-218 0.19	

PANTONE 265 C	Formula
TC-021 90.66	
TC-132 9.06	
TC-218 0.28	

PANTONE 266 C	Formula
TC-021 81.97	
TC-132 16.40	
TC-218 1.63	

PANTONE 267 C	Formula
TC-021 66.68	
TC-132 13.33	
TC-154 13.33	
TC-218 6.66	

PANTONE 268 C	Formula
TC-021 54.35	
TC-132 32.62	
TC-154 10.86	
TC-001 2.17	

PANTONE 269 C	Formula
TC-021 43.48	
TC-132 43.48	
TC-154 8.70	
TC-001 4.34	

PANTONE 2635 C	Formula
TC-021 98.68	
TC-132 0.99	
TC-218 0.20	
TC-154 0.13	

PANTONE 2645 C	Formula
TC-021 96.30	
TC-132 3.50	
TC-218 0.20	

PANTONE 2655 C	Formula
TC-021 90.20	
TC-132 9.50	
TC-218 0.30	

PANTONE 2665 C	Formula
TC-021 80.00	
TC-132 18.90	
TC-218 1.10	

PANTONE Violet C	Formula
TC-381 68.39	
TC-132 29.70	
TC-218 1.91	

PANTONE 2685 C	Formula
TC-381 56.60	
TC-132 39.00	
TC-218 4.40	

PANTONE 2695 C	Formula
TC-132 100.00	

PANTONE 270 C	Formula
TC-021 83.78	
TC-381 14.40	
TC-132 1.44	
TC-218 0.28	
TC-001 0.1	

Texcharge TC

PANTONE 271 C	Formula
TC-021	94.30
TC-132	3.73
TC-218	1.32
TC-057	0.65

PANTONE 272 C	Formula
TC-021	91.49
TC-132	5.74
TC-218	1.91
TC-057	0.86

PANTONE 273 C	Formula
TC-381	50.39
TC-132	33.53
TC-218	16.08

PANTONE 274 C	Formula
TC-381	44.22
TC-132	38.26
TC-218	16.84
TC-001	0.68

PANTONE 275 C	Formula
TC-132	42.86
TC-381	28.57
TC-218	27.14
TC-001	1.43

PANTONE 276 C	Formula
TC-132	44.18
TC-218	27.98
TC-381	22.09
TC-001	3.53
TC-021	2.22

PANTONE 2705 C	Formula
TC-021	94.25
TC-132	4.15
TC-218	1.60

PANTONE 2715 C	Formula
TC-021	84.95
TC-132	11.15
TC-218	3.90

PANTONE 2725 C	Formula
TC-021	73.07
TC-132	18.85
TC-218	8.08

PANTONE 2735 C	Formula
TC-132	46.68
TC-218	37.71
TC-021	15.61

PANTONE 2745 C	Formula
TC-132	45.74
TC-218	37.06
TC-381	14.41
TC-021	2.79

PANTONE 2755 C	Formula
TC-132	60.93
TC-218	39.07

PANTONE 2765 C	Formula
TC-132	62.76
TC-218	35.49
TC-001	1.75

PANTONE 2706 C	Formula
TC-021	98.65
TC-132	0.81
TC-218	0.41
TC-057	0.13

PANTONE 2716 C	Formula
TC-021	92.68
TC-132	3.87
TC-218	2.90
TC-057	0.55

PANTONE 2726 C	Formula
TC-021	68.42
TC-218	18.92
TC-132	12.66

Texcharge TC

PANTONE 2736 C	Formula
TC-021 45.27	
TC-218 30.57	
TC-132 24.16	

PANTONE 2746 C	Formula
TC-218 46.43	
TC-132 35.48	
TC-381 18.09	

PANTONE 2756 C	Formula
TC-218 53.88	
TC-132 40.73	
TC-021 4.76	
TC-001 0.63	

PANTONE 2766 C	Formula
TC-218 53.95	
TC-132 40.60	
TC-001 3.16	
TC-021 2.29	

PANTONE 2707 C	Formula
TC-021 98.73	
TC-218 0.72	
TC-132 0.45	
TC-001 0.10	

PANTONE 2717 C	Formula
TC-021 96.39	
TC-218 2.41	
TC-132 1.20	

PANTONE 2727 C	Formula
TC-021 61.22	
TC-381 21.63	
TC-218 12.24	
TC-132 4.91	

PANTONE Blue 072 C	Formula
TC-218 44.20	
TC-381 35.35	
TC-132 20.45	

PANTONE 2747 C	Formula
TC-218 58.83	
TC-132 34.61	
TC-381 5.92	
TC-057 0.64	

PANTONE 2757 C	Formula
TC-218 58.37	
TC-132 30.72	
TC-381 6.14	
TC-001 4.31	
TC-057 0.46	

PANTONE 2767 C	Formula
TC-218 52.63	
TC-132 31.58	
TC-001 15.79	

PANTONE 2708 C	Formula
TC-021 97.76	
TC-218 1.43	
TC-132 0.81	

PANTONE 2718 C	Formula
TC-021 83.82	
TC-218 9.94	
TC-132 6.24	

PANTONE 2728 C	Formula
TC-021 40.65	
TC-218 30.90	
TC-381 16.26	
TC-132 12.19	

PANTONE 2738 C	Formula
TC-218 37.29	
TC-381 25.42	
TC-132 20.34	
TC-021 16.95	

PANTONE 2748 C	Formula
TC-218 37.04	
TC-381 25.25	
TC-132 20.20	
TC-021 16.83	
TC-001 0.68	

Texcharge TC

PANTONE 2758 C	Formula
TC-218	34.11
TC-132	24.81
TC-381	23.26
TC-021	15.50
TC-001	2.32

PANTONE 2768 C	Formula
TC-218	43.80
TC-132	37.12
TC-021	10.60
TC-001	7.42
TC-316	1.06

PANTONE 277 C	Formula
TC-021	99.10
TC-218	0.40
TC-154	0.40
TC-316	0.10

PANTONE 278 C	Formula
TC-021	96.65
TC-218	2.36
TC-132	0.79
TC-001	0.20

PANTONE 279 C	Formula
TC-021	78.97
TC-218	17.14
TC-132	3.89

PANTONE Reflex Blue C	Formula
TC-381	58.05
TC-218	31.73
TC-132	10.22

PANTONE 280 C	Formula
TC-218	77.02
TC-132	21.96
TC-001	1.02

PANTONE 281 C	Formula
TC-218	66.43
TC-132	30.47
TC-001	3.10

PANTONE 282 C	Formula
TC-218	83.34
TC-132	11.40
TC-001	5.26

PANTONE 283 C	Formula
TC-021	97.66
TC-218	1.62
TC-132	0.54
TC-057	0.18

PANTONE 284 C	Formula
TC-021	90.15
TC-218	6.84
TC-132	2.34
TC-057	0.67

PANTONE 285 C	Formula
TC-021	69.44
TC-218	24.85
TC-132	5.25
TC-057	0.46

PANTONE 286 C	Formula
TC-381	61.00
TC-218	33.00
TC-132	5.00
TC-154	1.00

PANTONE 287 C	Formula
TC-218	81.93
TC-132	13.14
TC-021	4.56
TC-001	0.37

PANTONE 288 C	Formula
TC-218	77.99
TC-132	15.75
TC-021	5.12
TC-001	1.14

PANTONE 289 C	Formula
TC-218	69.37
TC-132	18.95
TC-001	7.62
TC-021	4.06

Texcharge TC

PANTONE 290 C	Formula
TC-381 49.80	
TC-021 49.80	
TC-218 0.40	

PANTONE 291 C	Formula
TC-021 96.36	
TC-218 2.65	
TC-132 0.69	
TC-057 0.20	
TC-001 0.1	

PANTONE 292 C	Formula
TC-021 91.96	
TC-218 7.07	
TC-132 0.87	
TC-001 0.10	

PANTONE 293 C	Formula
TC-218 51.66	
TC-381 30.51	
TC-021 14.08	
TC-132 3.75	

PANTONE 294 C	Formula
TC-218 81.01	
TC-132 9.12	
TC-021 8.66	
TC-001 1.21	

PANTONE 295 C	Formula
TC-218 72.29	
TC-021 16.21	
TC-132 8.89	
TC-001 2.61	

PANTONE 296 C	Formula
TC-218 74.77	
TC-132 11.95	
TC-057 8.03	
TC-001 5.25	

PANTONE 2905 C	Formula
TC-021 96.77	
TC-218 2.28	
TC-132 0.57	
TC-057 0.38	

PANTONE 2915 C	Formula
TC-021 92.23	
TC-218 6.66	
TC-132 0.79	
TC-057 0.32	

PANTONE 2925 C	Formula
TC-021 71.17	
TC-218 17.49	
TC-381 7.65	
TC-132 2.73	
TC-057 0.96	

PANTONE 2935 C	Formula
TC-218 55.96	
TC-021 41.10	
TC-132 2.94	

PANTONE 2945 C	Formula
TC-218 75.75	
TC-021 21.78	
TC-132 2.12	
TC-001 0.35	

PANTONE 2955 C	Formula
TC-218 79.85	
TC-021 9.29	
TC-132 4.64	
TC-316 4.46	
TC-001 1.76	

PANTONE 2965 C	Formula
TC-218 72.60	
TC-316 16.44	
TC-001 6.37	
TC-132 4.59	

PANTONE 297 C	Formula
TC-021 94.93	
TC-218 3.65	
TC-057 0.75	
TC-132 0.67	

PANTONE 298 C	Formula
TC-021 89.56	
TC-218 9.50	
TC-057 0.52	
TC-132 0.42	

Texcharge TC

PANTONE 299 C	Formula
TC-021 77.71	
TC-218 21.12	
TC-057 0.70	
TC-132 0.47	

PANTONE 300 C	Formula
TC-218 89.00	
TC-021 11.00	

PANTONE 301 C	Formula
TC-218 94.82	
TC-057 2.96	
TC-132 2.22	

PANTONE 302 C	Formula
TC-218 88.20	
TC-057 6.45	
TC-132 3.84	
TC-001 1.51	

PANTONE 303 C	Formula
TC-218 82.87	
TC-057 10.03	
TC-001 4.32	
TC-132 2.78	

PANTONE 2975 C	Formula
TC-021 98.19	
TC-218 1.45	
TC-057 0.26	
TC-001 0.10	

PANTONE 2985 C	Formula
TC-021 92.24	
TC-218 6.80	
TC-316 0.96	

PANTONE 2995 C	Formula
TC-021 75.96	
TC-218 21.41	
TC-316 2.63	

PANTONE 3005 C	Formula
TC-021 60.35	
TC-218 37.93	
TC-316 1.72	

PANTONE 3015 C	Formula
TC-218 49.52	
TC-021 47.74	
TC-316 2.50	
TC-001 0.24	

PANTONE 3025 C	Formula
TC-218 70.20	
TC-316 15.74	
TC-021 12.46	
TC-001 1.60	

PANTONE 3035 C	Formula
TC-218 59.43	
TC-316 22.02	
TC-001 12.18	
TC-021 6.37	

PANTONE 304 C	Formula
TC-021 75.59	
TC-381 23.47	
TC-218 0.59	
TC-316 0.35	

PANTONE 305 C	Formula
TC-021 95.34	
TC-218 3.85	
TC-316 0.81	

PANTONE 306 C	Formula
TC-021 89.07	
TC-218 8.56	
TC-316 2.37	

PANTONE Process Blue C	Formula
TC-381 75.53	
TC-218 23.69	
TC-316 0.78	

Texcharge TC

PANTONE 307 C	Formula
TC-021 52.97	
TC-218 41.67	
TC-316 5.36	

PANTONE 308 C	Formula
TC-218 48.76	
TC-021 42.91	
TC-316 6.91	
TC-001 1.42	

PANTONE 309 C	Formula
TC-218 48.65	
TC-381 33.34	
TC-316 16.17	
TC-001 1.84	

PANTONE 310 C	Formula
TC-021 93.96	
TC-218 3.83	
TC-316 2.11	
TC-001 0.10	

PANTONE 311 C	Formula
TC-021 88.76	
TC-218 7.99	
TC-316 3.25	

PANTONE 312 C	Formula
TC-021 79.52	
TC-218 15.55	
TC-316 4.93	

PANTONE 313 C	Formula
TC-021 64.92	
TC-218 27.89	
TC-316 7.19	

PANTONE 314 C	Formula
TC-021 50.63	
TC-218 36.73	
TC-316 12.64	

PANTONE 315 C	Formula
TC-021 39.68	
TC-218 38.99	
TC-316 20.24	
TC-001 1.09	

PANTONE 316 C	Formula
TC-218 45.83	
TC-316 22.44	
TC-021 17.20	
TC-057 10.26	
TC-001 4.27	

PANTONE 3105 C	Formula
TC-021 96.76	
TC-316 1.96	
TC-218 1.08	
TC-001 0.20	

PANTONE 3115 C	Formula
TC-021 90.09	
TC-218 5.72	
TC-316 4.19	

PANTONE 3125 C	Formula
TC-021 83.08	
TC-218 10.90	
TC-316 6.02	

PANTONE 3135 C	Formula
TC-021 75.56	
TC-218 16.68	
TC-316 7.76	

PANTONE 3145 C	Formula
TC-021 50.48	
TC-218 29.58	
TC-316 19.75	
TC-001 0.19	

PANTONE 3155 C	Formula
TC-021 51.10	
TC-218 27.28	
TC-316 20.86	
TC-001 0.76	

Texcharge TC

PANTONE 3165 C	Formula
TC-316	56.20
TC-218	41.34
TC-001	1.64
TC-021	0.82

PANTONE 317 C	Formula
TC-021	98.52
TC-218	0.79
TC-046	0.49
TC-316	0.20

PANTONE 318 C	Formula
TC-021	96.11
TC-218	2.89
TC-046	0.50
TC-316	0.50

PANTONE 319 C	Formula
TC-021	93.37
TC-316	4.30
TC-218	2.33

PANTONE 320 C	Formula
TC-381	53.17
TC-021	30.95
TC-218	9.13
TC-316	6.75

PANTONE 321 C	Formula
TC-021	41.41
TC-381	20.70
TC-316	19.05
TC-218	18.63
TC-001	0.21

PANTONE 322 C	Formula
TC-021	38.31
TC-316	24.71
TC-381	19.16
TC-218	17.24
TC-001	0.58

PANTONE 323 C	Formula
TC-021	36.43
TC-316	27.32
TC-381	18.22
TC-218	16.39
TC-001	1.64

PANTONE 324 C	Formula
TC-021	98.43
TC-218	1.05
TC-057	0.52

PANTONE 325 C	Formula
TC-021	95.62
TC-218	3.19
TC-057	1.19

PANTONE 326 C	Formula
TC-021	84.81
TC-218	10.42
TC-057	3.00
TC-316	1.77

PANTONE 327 C	Formula
TC-021	36.58
TC-218	24.39
TC-381	19.51
TC-316	13.42
TC-057	6.1

PANTONE 328 C	Formula
TC-021	45.12
TC-218	24.39
TC-316	23.17
TC-057	6.10
TC-001	1.22

PANTONE 329 C	Formula
TC-021	43.22
TC-316	25.70
TC-218	23.36
TC-057	5.84
TC-001	1.88

PANTONE 330 C	Formula
TC-021	37.00
TC-316	28.00
TC-218	20.00
TC-057	10.00
TC-001	5

PANTONE 3242 C	Formula
TC-381	98.39
TC-316	1.51
TC-057	0.10

Texcharge TC

PANTONE 3252 C	Formula
TC-021 95.54	
TC-316 3.61	
TC-218 0.85	

PANTONE 3262 C	Formula
TC-021 92.02	
TC-316 6.34	
TC-218 1.64	

PANTONE 3272 C	Formula
TC-381 79.33	
TC-316 9.91	
TC-021 5.66	
TC-218 5.10	

PANTONE 3282 C	Formula
TC-021 60.61	
TC-316 24.24	
TC-218 10.61	
TC-057 4.24	
TC-001 0.3	

PANTONE 3292 C	Formula
TC-021 51.95	
TC-316 28.57	
TC-218 10.39	
TC-057 6.49	
TC-001 2.6	

PANTONE 3302 C	Formula
TC-218 66.54	
TC-057 18.43	
TC-103 14.38	
TC-001 0.65	

PANTONE 3245 C	Formula
TC-021 97.05	
TC-316 2.53	
TC-057 0.42	

PANTONE 3255 C	Formula
TC-021 95.63	
TC-316 3.33	
TC-057 0.62	
TC-218 0.42	

PANTONE 3265 C	Formula
TC-021 89.64	
TC-316 9.96	
TC-218 0.40	

PANTONE 3275 C	Formula
TC-021 52.30	
TC-381 31.38	
TC-316 15.69	
TC-218 0.63	

PANTONE 3285 C	Formula
TC-021 67.83	
TC-316 29.46	
TC-057 1.74	
TC-218 0.58	
TC-001 0.39	

PANTONE 3295 C	Formula
TC-021 67.31	
TC-316 29.23	
TC-057 1.73	
TC-001 1.15	
TC-218 0.58	

PANTONE 3305 C	Formula
TC-021 57.58	
TC-316 30.71	
TC-057 6.72	
TC-001 4.41	
TC-218 0.58	

PANTONE 3248 C	Formula
TC-021 96.07	
TC-316 2.16	
TC-218 1.38	
TC-046 0.39	

PANTONE 3258 C	Formula
TC-021 90.29	
TC-316 6.77	
TC-218 2.26	
TC-046 0.68	

PANTONE 3268 C	Formula
TC-021 76.20	
TC-316 18.16	
TC-218 3.97	
TC-046 1.67	

Texcharge TC

PANTONE 3278 C	Formula
TC-021	46.22
TC-316	30.07
TC-381	15.42
TC-218	6.22
TC-046	2.07

PANTONE 3288 C	Formula
TC-316	46.42
TC-021	38.18
TC-218	11.50
TC-046	3.90

PANTONE 3298 C	Formula
TC-316	54.09
TC-021	40.34
TC-046	3.11
TC-001	2.46

PANTONE 3308 C	Formula
TC-316	68.27
TC-021	12.33
TC-046	11.13
TC-001	8.27

PANTONE 331 C	Formula
TC-381	66.31
TC-021	33.16
TC-316	0.33
TC-057	0.20

PANTONE 332 C	Formula
TC-381	98.40
TC-316	1.40
TC-057	0.20

PANTONE 333 C	Formula
TC-381	96.50
TC-316	3.20
TC-057	0.30

PANTONE Green C	Formula
TC-381	81.57
TC-316	17.35
TC-057	1.08

PANTONE 334 C	Formula
TC-381	68.00
TC-218	14.00
TC-057	12.00
TC-316	6.00

PANTONE 335 C	Formula
TC-381	66.00
TC-218	15.90
TC-057	11.70
TC-316	6.40

PANTONE 336 C	Formula
TC-381	64.22
TC-316	26.06
TC-103	5.41
TC-218	4.31

PANTONE 337 C	Formula
TC-021	98.60
TC-316	1.00
TC-057	0.30
TC-001	0.10

PANTONE 338 C	Formula
TC-021	97.20
TC-316	2.10
TC-057	0.60
TC-001	0.10

PANTONE 339 C	Formula
TC-021	84.80
TC-316	13.00
TC-057	1.20
TC-046	1.00

PANTONE 340 C	Formula
TC-021	66.60
TC-316	25.80
TC-057	6.80
TC-046	0.80

PANTONE 341 C	Formula
TC-021	57.40
TC-316	30.90
TC-057	10.20
TC-001	0.80
TC-046	0.7

Texcharge TC

PANTONE 342 C	Formula
TC-316 81.10	
TC-021 11.30	
TC-046 7.60	

PANTONE 343 C	Formula
TC-316 72.50	
TC-021 14.60	
TC-046 11.30	
TC-001 1.60	

PANTONE 3375 C	Formula
TC-021 98.10	
TC-316 1.30	
TC-057 0.60	

PANTONE 3385 C	Formula
TC-021 96.60	
TC-316 2.50	
TC-057 0.90	

PANTONE 3395 C	Formula
TC-021 87.50	
TC-316 8.60	
TC-057 3.90	

PANTONE 3405 C	Formula
TC-021 77.60	
TC-316 14.10	
TC-057 8.30	

PANTONE 3415 C	Formula
TC-021 56.00	
TC-316 37.00	
TC-046 7.00	

PANTONE 3425 C	Formula
TC-021 59.10	
TC-316 33.60	
TC-046 6.40	
TC-001 0.90	

PANTONE 3435 C	Formula
TC-021 48.40	
TC-316 32.50	
TC-046 13.40	
TC-001 5.70	

PANTONE 344 C	Formula
TC-021 98.70	
TC-316 0.80	
TC-057 0.50	

PANTONE 345 C	Formula
TC-021 95.90	
TC-057 2.00	
TC-316 2.00	
TC-001 0.10	

PANTONE 346 C	Formula
TC-021 92.80	
TC-316 3.80	
TC-057 3.30	
TC-001 0.10	

PANTONE 347 C	Formula
TC-021 48.00	
TC-057 26.00	
TC-316 26.00	

PANTONE 348 C	Formula
TC-021 44.00	
TC-057 29.40	
TC-316 25.70	
TC-001 0.90	

PANTONE 349 C	Formula
TC-021 38.60	
TC-057 34.60	
TC-316 24.30	
TC-001 2.50	

PANTONE 350 C	Formula
TC-057 39.10	
TC-021 33.10	
TC-316 22.60	
TC-001 5.20	

Texcharge TC

PANTONE 351 C	Formula
TC-021	58.76
TC-381	39.18
TC-057	1.47
TC-316	0.59

PANTONE 352 C	Formula
TC-021	97.30
TC-057	1.50
TC-316	1.20

PANTONE 353 C	Formula
TC-021	94.80
TC-057	3.00
TC-316	2.20

PANTONE 354 C	Formula
TC-381	67.50
TC-057	23.33
TC-316	9.17

PANTONE 355 C	Formula
TC-021	52.30
TC-057	25.20
TC-316	18.90
TC-046	3.60

PANTONE 356 C	Formula
TC-021	49.00
TC-057	28.00
TC-316	20.00
TC-046	2.00
TC-001	1

PANTONE 357 C	Formula
TC-381	73.60
TC-316	15.50
TC-046	9.40
TC-001	1.50

PANTONE 358 C	Formula
TC-021	96.92
TC-057	2.28
TC-218	0.46
TC-046	0.34

PANTONE 359 C	Formula
TC-021	94.13
TC-057	4.43
TC-218	1.11
TC-046	0.33

PANTONE 360 C	Formula
TC-021	89.61
TC-057	7.17
TC-218	2.33
TC-046	0.89

PANTONE 361 C	Formula
TC-021	70.30
TC-057	22.85
TC-218	5.27
TC-046	1.58

PANTONE 362 C	Formula
TC-021	55.87
TC-057	33.52
TC-218	7.82
TC-046	2.79

PANTONE 363 C	Formula
TC-057	44.69
TC-021	39.11
TC-218	11.17
TC-046	5.03

PANTONE 364 C	Formula
TC-057	51.59
TC-021	23.45
TC-218	14.08
TC-046	10.88

PANTONE 365 C	Formula
TC-021	98.52
TC-046	1.02
TC-218	0.46

PANTONE 366 C	Formula
TC-021	96.50
TC-057	2.00
TC-046	1.00
TC-218	0.50

Texcharge TC

PANTONE 367 C		Formula
TC-021	93.38	
TC-057	4.68	
TC-046	0.97	
TC-218	0.97	

PANTONE 368 C		Formula
TC-021	70.31	
TC-057	23.44	
TC-046	3.13	
TC-218	3.12	

PANTONE 369 C		Formula
TC-021	62.50	
TC-057	27.78	
TC-046	5.55	
TC-218	4.17	

PANTONE 370 C		Formula
TC-057	51.98	
TC-021	31.07	
TC-046	11.30	
TC-218	5.65	

PANTONE 371 C		Formula
TC-057	77.31	
TC-218	10.09	
TC-103	8.40	
TC-021	4.20	

PANTONE 372 C		Formula
TC-021	96.74	
TC-057	3.06	
TC-316	0.20	

PANTONE 373 C		Formula
TC-021	93.93	
TC-057	5.87	
TC-316	0.20	

PANTONE 374 C		Formula
TC-021	81.45	
TC-057	18.10	
TC-316	0.45	

PANTONE 375 C		Formula
TC-021	59.29	
TC-057	39.52	
TC-316	1.19	

PANTONE 376 C		Formula
TC-021	49.02	
TC-057	49.02	
TC-316	1.63	
TC-001	0.33	

PANTONE 377 C		Formula
TC-057	70.74	
TC-021	25.72	
TC-316	2.57	
TC-001	0.52	
TC-103	0.45	

PANTONE 378 C		Formula
TC-057	67.37	
TC-021	24.50	
TC-316	3.40	
TC-103	2.81	
TC-001	1.92	

PANTONE 379 C		Formula
TC-381	93.23	
TC-057	6.45	
TC-046	0.22	
TC-316	0.10	

PANTONE 380 C		Formula
TC-381	96.44	
TC-057	2.37	
TC-046	0.89	
TC-316	0.30	

PANTONE 381 C		Formula
TC-381	54.89	
TC-057	42.81	
TC-046	1.98	
TC-218	0.21	
TC-316	0.11	

PANTONE 382 C		Formula
TC-057	77.38	
TC-381	21.43	
TC-218	1.09	
TC-046	0.10	

Texcharge TC

PANTONE 383 C	Formula
TC-057 53.73	
TC-046 29.85	
TC-021 14.93	
TC-218 1.49	

PANTONE 384 C	Formula
TC-046 57.00	
TC-057 40.00	
TC-381 3.00	

PANTONE 385 C	Formula
TC-057 63.72	
TC-001 25.49	
TC-381 10.62	
TC-103 0.17	

PANTONE 386 C	Formula
TC-021 81.48	
TC-057 18.52	

PANTONE 387 C	Formula
TC-021 78.19	
TC-057 21.71	
TC-316 0.10	

PANTONE 388 C	Formula
TC-057 54.70	
TC-021 45.00	
TC-316 0.30	

PANTONE 389 C	Formula
TC-021 66.45	
TC-057 33.22	
TC-316 0.33	

PANTONE 390 C	Formula
TC-057 54.35	
TC-021 44.15	
TC-316 0.68	
TC-103 0.68	
TC-001 0.14	

PANTONE 391 C	Formula
TC-057 62.50	
TC-021 34.73	
TC-103 1.39	
TC-316 0.69	
TC-001 0.69	

PANTONE 392 C	Formula
TC-057 70.85	
TC-021 25.30	
TC-103 1.82	
TC-001 1.02	
TC-316 1.01	

PANTONE 393 C	Formula
TC-021 95.00	
TC-057 5.00	

PANTONE 394 C	Formula
TC-021 84.80	
TC-057 15.20	

PANTONE 395 C	Formula
TC-021 81.10	
TC-057 18.80	
TC-316 0.10	

PANTONE 396 C	Formula
TC-057 83.10	
TC-381 16.60	
TC-316 0.30	

PANTONE 397 C	Formula
TC-057 99.40	
TC-316 0.30	
TC-001 0.30	

PANTONE 398 C	Formula
TC-057 98.10	
TC-046 1.00	
TC-001 0.60	
TC-316 0.30	

Texcharge TC

PANTONE 399 C	Formula
TC-057 94.60	
TC-046 4.00	
TC-001 1.00	
TC-316 0.40	

PANTONE 3935 C	Formula
TC-021 93.70	
TC-057 6.00	
TC-046 0.30	

PANTONE 3945 C	Formula
TC-021 82.90	
TC-057 16.80	
TC-046 0.30	

PANTONE 3955 C	Formula
TC-021 50.00	
TC-057 49.90	
TC-218 0.10	

PANTONE 3965 C	Formula
TC-057 69.90	
TC-021 30.00	
TC-218 0.10	

PANTONE 3975 C	Formula
TC-057 99.50	
TC-001 0.50	

PANTONE 3985 C	Formula
TC-057 99.00	
TC-001 1.00	

PANTONE 3995 C	Formula
TC-057 88.40	
TC-046 8.00	
TC-001 3.60	

PANTONE 400 C	Formula
TC-021 88.17	
TC-381 10.66	
TC-057 0.56	
TC-001 0.51	
TC-122 0.1	

PANTONE 401 C	Formula
TC-021 98.60	
TC-001 0.80	
TC-046 0.50	
TC-122 0.10	

PANTONE 402 C	Formula
TC-021 98.00	
TC-001 1.20	
TC-046 0.60	
TC-122 0.20	

PANTONE 403 C	Formula
TC-021 96.30	
TC-001 2.20	
TC-046 1.30	
TC-122 0.20	

PANTONE 404 C	Formula
TC-021 93.20	
TC-001 3.40	
TC-046 3.00	
TC-122 0.40	

PANTONE 405 C	Formula
TC-021 82.50	
TC-046 8.40	
TC-001 8.00	
TC-122 1.10	

PANTONE Black C	Formula
TC-001 59.06	
TC-103 20.67	
TC-122 18.70	
TC-046 1.57	

PANTONE 406 C	Formula
TC-021 84.40	
TC-381 14.40	
TC-001 0.60	
TC-046 0.40	
TC-153 0.2	

Texcharge TC

PANTONE 407 C	Formula
TC-021 98.40	
TC-001 0.80	
TC-046 0.50	
TC-153 0.30	

PANTONE 408 C	Formula
TC-021 97.70	
TC-001 1.20	
TC-046 0.70	
TC-153 0.40	

PANTONE 409 C	Formula
TC-021 96.80	
TC-001 1.70	
TC-046 0.90	
TC-153 0.60	

PANTONE 410 C	Formula
TC-021 93.60	
TC-001 3.40	
TC-046 1.60	
TC-153 1.40	

PANTONE 411 C	Formula
TC-021 88.40	
TC-001 4.90	
TC-046 3.70	
TC-153 3.00	

PANTONE 412 C	Formula
TC-046 31.60	
TC-021 25.60	
TC-122 21.40	
TC-001 21.40	

PANTONE 413 C	Formula
TC-021 99.60	
TC-057 0.20	
TC-001 0.20	

PANTONE 414 C	Formula
TC-021 99.40	
TC-001 0.40	
TC-057 0.20	

PANTONE 415 C	Formula
TC-021 97.40	
TC-057 1.30	
TC-001 1.30	

PANTONE 416 C	Formula
TC-021 96.40	
TC-057 1.80	
TC-001 1.80	

PANTONE 417 C	Formula
TC-021 92.80	
TC-057 4.10	
TC-001 3.10	

PANTONE 418 C	Formula
TC-021 88.40	
TC-057 6.70	
TC-001 4.90	

PANTONE 419 C	Formula
TC-057 74.00	
TC-001 26.00	

PANTONE 420 C	Formula
TC-021 99.80	
TC-001 0.20	

PANTONE 421 C	Formula
TC-021 99.40	
TC-001 0.50	
TC-057 0.10	

PANTONE 422 C	Formula
TC-021 99.30	
TC-001 0.60	
TC-057 0.10	

Texcharge TC

PANTONE 423 C	Formula
TC-021 98.20	
TC-001 1.60	
TC-057 0.20	

PANTONE 424 C	Formula
TC-021 95.00	
TC-001 4.00	
TC-057 1.00	

PANTONE 425 C	Formula
TC-021 90.90	
TC-001 6.70	
TC-057 2.40	

PANTONE 426 C	Formula
TC-021 66.40	
TC-001 25.30	
TC-057 8.30	

PANTONE 427 C	Formula
TC-021 99.80	
TC-001 0.20	

PANTONE 428 C	Formula
TC-021 99.70	
TC-001 0.20	
TC-218 0.10	

PANTONE 429 C	Formula
TC-021 98.90	
TC-001 0.70	
TC-218 0.30	
TC-154 0.10	

PANTONE 430 C	Formula
TC-021 98.20	
TC-001 1.30	
TC-218 0.50	

PANTONE 431 C	Formula
TC-021 90.60	
TC-001 6.70	
TC-218 1.80	
TC-316 0.90	

PANTONE 432 C	Formula
TC-021 79.40	
TC-001 11.30	
TC-316 4.40	
TC-132 3.80	
TC-057 1.1	

PANTONE 433 C	Formula
TC-021 54.60	
TC-001 36.40	
TC-057 4.50	
TC-316 4.50	

PANTONE 434 C	Formula
TC-021 99.30	
TC-154 0.30	
TC-103 0.20	
TC-001 0.20	

PANTONE 435 C	Formula
TC-021 98.80	
TC-154 0.60	
TC-001 0.40	
TC-103 0.20	

PANTONE 436 C	Formula
TC-021 97.90	
TC-154 1.00	
TC-001 0.80	
TC-103 0.30	

PANTONE 437 C	Formula
TC-021 94.20	
TC-154 2.90	
TC-001 1.90	
TC-103 1.00	

PANTONE 438 C	Formula
TC-021 54.10	
TC-154 18.00	
TC-103 18.00	
TC-001 9.90	

Texcharge TC

PANTONE 439 C	Formula
TC-021 42.80	
TC-154 23.80	
TC-103 19.10	
TC-001 14.30	

PANTONE 440 C	Formula
TC-021 45.80	
TC-103 22.90	
TC-001 16.00	
TC-154 15.30	

PANTONE 441 C	Formula
TC-021 99.40	
TC-316 0.30	
TC-001 0.20	
TC-122 0.10	

PANTONE 442 C	Formula
TC-021 98.80	
TC-316 0.60	
TC-001 0.40	
TC-122 0.20	

PANTONE 443 C	Formula
TC-021 97.90	
TC-316 1.00	
TC-001 0.80	
TC-122 0.30	

PANTONE 444 C	Formula
TC-021 97.10	
TC-316 1.40	
TC-001 1.20	
TC-122 0.30	

PANTONE 445 C	Formula
TC-021 86.00	
TC-001 7.50	
TC-316 5.60	
TC-122 0.90	

PANTONE 446 C	Formula
TC-021 81.10	
TC-001 9.90	
TC-316 5.30	
TC-046 2.80	
TC-122 0.9	

PANTONE 447 C	Formula
TC-021 74.40	
TC-001 13.70	
TC-316 5.80	
TC-046 4.40	
TC-122 1.7	

PANTONE Warm Gray 1 C	Formula
TC-021 99.63	
TC-046 0.17	
TC-122 0.10	
TC-001 0.10	

PANTONE Warm Gray 2 C	Formula
TC-021 99.40	
TC-001 0.30	
TC-046 0.20	
TC-122 0.10	

PANTONE Warm Gray 3 C	Formula
TC-021 99.10	
TC-001 0.50	
TC-046 0.30	
TC-122 0.10	

PANTONE Warm Gray 4 C	Formula
TC-021 98.80	
TC-001 0.60	
TC-046 0.40	
TC-122 0.20	

PANTONE Warm Gray 5 C	Formula
TC-021 98.50	
TC-001 0.70	
TC-046 0.50	
TC-122 0.30	

PANTONE Warm Gray 6 C	Formula
TC-021 97.40	
TC-001 1.50	
TC-046 0.80	
TC-122 0.30	

PANTONE Warm Gray 7 C	Formula
TC-021 96.10	
TC-001 2.00	
TC-046 1.40	
TC-122 0.50	

Texcharge TC

PANTONE Warm Gray 8 C	Formula
TC-021 95.50	
TC-001 2.30	
TC-046 1.60	
TC-122 0.60	

PANTONE Warm Gray 9 C	Formula
TC-021 92.20	
TC-046 3.50	
TC-001 3.30	
TC-122 1.00	

PANTONE Warm Gray 10 C	Formula
TC-021 91.10	
TC-046 4.00	
TC-001 3.80	
TC-122 1.10	

PANTONE Warm Gray 11 C	Formula
TC-021 90.74	
TC-001 4.17	
TC-046 3.99	
TC-122 1.10	

PANTONE Cool Gray 1 C	Formula
TC-021 99.80	
TC-046 0.10	
TC-001 0.10	

PANTONE Cool Gray 2 C	Formula
TC-021 99.30	
TC-057 0.40	
TC-001 0.30	

PANTONE Cool Gray 3 C	Formula
TC-021 98.90	
TC-057 0.60	
TC-001 0.50	

PANTONE Cool Gray 4 C	Formula
TC-021 98.70	
TC-001 0.70	
TC-057 0.60	

PANTONE Cool Gray 5 C	Formula
TC-021 98.30	
TC-001 1.00	
TC-057 0.70	

PANTONE Cool Gray 6 C	Formula
TC-021 98.20	
TC-001 1.30	
TC-057 0.50	

PANTONE Cool Gray 7 C	Formula
TC-021 97.70	
TC-001 1.80	
TC-057 0.50	

PANTONE Cool Gray 8 C	Formula
TC-021 97.20	
TC-001 2.20	
TC-057 0.60	

PANTONE Cool Gray 9 C	Formula
TC-021 96.00	
TC-001 3.20	
TC-057 0.80	

PANTONE Cool Gray 10 C	Formula
TC-021 94.80	
TC-001 4.40	
TC-057 0.80	

PANTONE Cool Gray 11 C	Formula
TC-021 92.63	
TC-001 7.37	

PANTONE 448 C	Formula
TC-046 37.73	
TC-057 37.73	
TC-103 9.44	
TC-021 7.55	
TC-001 7.55	

Texcharge TC

PANTONE 449 C	Formula
TC-057 44.00	
TC-046 35.00	
TC-001 11.00	
TC-021 10.00	

PANTONE 450 C	Formula
TC-057 49.00	
TC-046 26.50	
TC-021 16.40	
TC-001 8.10	

PANTONE 451 C	Formula
TC-021 93.40	
TC-057 4.00	
TC-001 1.40	
TC-046 1.20	

PANTONE 452 C	Formula
TC-021 96.70	
TC-057 2.00	
TC-001 0.70	
TC-046 0.60	

PANTONE 453 C	Formula
TC-021 98.20	
TC-057 1.00	
TC-001 0.50	
TC-046 0.30	

PANTONE 454 C	Formula
TC-021 99.34	
TC-046 0.26	
TC-057 0.26	
TC-001 0.14	

PANTONE 4485 C	Formula
TC-046 50.80	
TC-057 35.90	
TC-001 8.00	
TC-103 5.30	

PANTONE 4495 C	Formula
TC-021 57.20	
TC-046 22.00	
TC-057 17.40	
TC-001 3.40	

PANTONE 4505 C	Formula
TC-021 83.00	
TC-046 8.40	
TC-057 6.80	
TC-001 1.80	

PANTONE 4515 C	Formula
TC-021 93.00	
TC-046 4.10	
TC-057 2.00	
TC-001 0.90	

PANTONE 4525 C	Formula
TC-021 97.70	
TC-046 1.30	
TC-057 0.60	
TC-001 0.40	

PANTONE 4535 C	Formula
TC-021 98.90	
TC-046 0.90	
TC-001 0.20	

PANTONE 4545 C	Formula
TC-021 99.30	
TC-046 0.60	
TC-001 0.10	

PANTONE 455 C	Formula
TC-057 60.20	
TC-046 33.10	
TC-001 6.70	

PANTONE 456 C	Formula
TC-057 88.30	
TC-046 10.00	
TC-001 1.70	

PANTONE 457 C	Formula
TC-057 89.00	
TC-046 10.00	
TC-001 1.00	

Texcharge TC

PANTONE 458 C	Formula
TC-021 93.70	
TC-046 3.00	
TC-057 3.00	
TC-001 0.30	

PANTONE 459 C	Formula
TC-021 96.50	
TC-046 1.70	
TC-057 1.70	
TC-001 0.10	

PANTONE 460 C	Formula
TC-021 97.40	
TC-046 1.30	
TC-057 1.30	

PANTONE 461 C	Formula
TC-021 98.65	
TC-057 0.85	
TC-046 0.40	
TC-001 0.10	

PANTONE 462 C	Formula
TC-046 68.70	
TC-103 22.00	
TC-001 9.30	

PANTONE 463 C	Formula
TC-046 53.80	
TC-021 21.90	
TC-103 19.40	
TC-001 4.90	

PANTONE 464 C	Formula
TC-046 41.60	
TC-021 38.50	
TC-103 16.60	
TC-001 3.30	

PANTONE 465 C	Formula
TC-021 93.80	
TC-046 4.70	
TC-103 0.80	
TC-001 0.70	

PANTONE 466 C	Formula
TC-021 96.70	
TC-046 2.60	
TC-001 0.40	
TC-103 0.30	

PANTONE 467 C	Formula
TC-021 98.00	
TC-046 1.50	
TC-001 0.30	
TC-103 0.20	

PANTONE 468 C	Formula
TC-021 99.20	
TC-046 0.50	
TC-103 0.20	
TC-001 0.10	

PANTONE 4625 C	Formula
TC-046 72.70	
TC-153 19.50	
TC-001 7.80	

PANTONE 4635 C	Formula
TC-046 45.40	
TC-021 44.90	
TC-122 6.90	
TC-001 2.80	

PANTONE 4645 C	Formula
TC-021 87.40	
TC-046 8.60	
TC-122 2.50	
TC-001 1.50	

PANTONE 4655 C	Formula
TC-021 93.30	
TC-046 4.50	
TC-122 1.40	
TC-001 0.80	

PANTONE 4665 C	Formula
TC-021 97.70	
TC-046 1.40	
TC-122 0.60	
TC-001 0.30	

Texcharge TC

PANTONE 4675 C	Formula
TC-021 98.70	
TC-046 0.80	
TC-122 0.30	
TC-001 0.20	

PANTONE 4685 C	Formula
TC-021 99.10	
TC-046 0.60	
TC-122 0.20	
TC-001 0.10	

PANTONE 469 C	Formula
TC-103 74.08	
TC-046 22.22	
TC-001 3.70	

PANTONE 470 C	Formula
TC-046 83.50	
TC-122 15.00	
TC-001 1.50	

PANTONE 471 C	Formula
TC-021 62.51	
TC-046 28.12	
TC-122 8.23	
TC-001 1.14	

PANTONE 472 C	Formula
TC-021 93.60	
TC-046 4.30	
TC-122 2.00	
TC-001 0.10	

PANTONE 473 C	Formula
TC-021 97.20	
TC-046 2.00	
TC-122 0.80	

PANTONE 474 C	Formula
TC-021 97.90	
TC-046 1.50	
TC-122 0.60	

PANTONE 475 C	Formula
TC-021 76.76	
TC-381 22.18	
TC-046 0.68	
TC-122 0.38	

PANTONE 4695 C	Formula
TC-046 58.40	
TC-153 33.30	
TC-001 8.30	

PANTONE 4705 C	Formula
TC-021 60.40	
TC-046 23.80	
TC-153 11.80	
TC-001 4.00	

PANTONE 4715 C	Formula
TC-021 84.30	
TC-046 8.70	
TC-153 5.00	
TC-001 2.00	

PANTONE 4725 C	Formula
TC-021 95.10	
TC-046 2.60	
TC-153 1.60	
TC-001 0.70	

PANTONE 4735 C	Formula
TC-021 97.80	
TC-046 1.00	
TC-153 0.80	
TC-001 0.40	

PANTONE 4745 C	Formula
TC-021 99.00	
TC-046 0.40	
TC-153 0.40	
TC-001 0.20	

PANTONE 4755 C	Formula
TC-021 99.50	
TC-046 0.20	
TC-153 0.20	
TC-001 0.10	

Texcharge TC

PANTONE 476 C	Formula
TC-046 59.00	
TC-021 16.40	
TC-153 13.10	
TC-001 7.40	
TC-103 4.1	

PANTONE 477 C	Formula
TC-046 61.80	
TC-153 16.30	
TC-021 13.00	
TC-103 4.50	
TC-001 4.4	

PANTONE 478 C	Formula
TC-046 62.00	
TC-153 17.70	
TC-021 12.40	
TC-103 4.40	
TC-001 3.5	

PANTONE 479 C	Formula
TC-021 91.70	
TC-046 5.30	
TC-153 1.90	
TC-001 1.10	

PANTONE 480 C	Formula
TC-021 98.40	
TC-046 0.80	
TC-153 0.40	
TC-001 0.40	

PANTONE 481 C	Formula
TC-021 99.40	
TC-046 0.30	
TC-001 0.20	
TC-153 0.10	

PANTONE 482 C	Formula
TC-021 99.60	
TC-103 0.20	
TC-046 0.10	
TC-001 0.10	

PANTONE 483 C	Formula
TC-057 62.79	
TC-154 27.13	
TC-103 7.75	
TC-001 2.33	

PANTONE 484 C	Formula
TC-046 67.30	
TC-153 31.70	
TC-001 1.00	

PANTONE 485 C	Formula
TC-122 95.24	
TC-046 4.76	

PANTONE 486 C	Formula
TC-021 92.00	
TC-057 5.00	
TC-153 2.00	
TC-103 0.90	
TC-001 0.1	

PANTONE 487 C	Formula
TC-021 97.20	
TC-057 1.40	
TC-103 0.70	
TC-153 0.70	

PANTONE 488 C	Formula
TC-021 97.80	
TC-057 1.20	
TC-103 0.50	
TC-153 0.50	

PANTONE 489 C	Formula
TC-021 77.98	
TC-381 21.27	
TC-103 0.48	
TC-153 0.17	
TC-001 0.1	

PANTONE 490 C	Formula
TC-153 59.70	
TC-103 18.30	
TC-122 14.00	
TC-001 7.00	
TC-218 1	

PANTONE 491 C	Formula
TC-153 78.50	
TC-103 18.80	
TC-001 1.70	
TC-218 1.00	

Texcharge TC

PANTONE 492 C	Formula
TC-153 78.90	
TC-103 12.30	
TC-021 7.00	
TC-218 1.80	

PANTONE 493 C	Formula
TC-021 93.50	
TC-153 4.40	
TC-103 1.80	
TC-218 0.30	

PANTONE 494 C	Formula
TC-021 98.40	
TC-153 1.00	
TC-103 0.50	
TC-218 0.10	

PANTONE 495 C	Formula
TC-021 99.00	
TC-153 0.70	
TC-103 0.30	

PANTONE 496 C	Formula
TC-021 99.50	
TC-153 0.30	
TC-103 0.20	

PANTONE 497 C	Formula
TC-153 49.70	
TC-103 31.80	
TC-021 10.00	
TC-001 8.50	

PANTONE 498 C	Formula
TC-103 35.50	
TC-153 34.00	
TC-021 15.60	
TC-381 10.60	
TC-001 4.3	

PANTONE 499 C	Formula
TC-103 40.60	
TC-153 27.10	
TC-021 16.90	
TC-381 12.70	
TC-001 2.7	

PANTONE 500 C	Formula
TC-021 94.70	
TC-153 3.10	
TC-103 1.80	
TC-001 0.40	

PANTONE 501 C	Formula
TC-021 98.30	
TC-153 1.00	
TC-103 0.50	
TC-001 0.20	

PANTONE 502 C	Formula
TC-021 99.30	
TC-103 0.30	
TC-153 0.30	
TC-001 0.10	

PANTONE 503 C	Formula
TC-021 99.50	
TC-153 0.30	
TC-103 0.10	
TC-001 0.10	

PANTONE 4975 C	Formula
TC-103 34.80	
TC-153 31.32	
TC-001 15.32	
TC-381 9.28	
TC-021 9.28	

PANTONE 4985 C	Formula
TC-021 76.60	
TC-153 12.40	
TC-103 8.20	
TC-001 2.80	

PANTONE 4995 C	Formula
TC-021 90.90	
TC-153 5.00	
TC-103 2.90	
TC-001 1.20	

PANTONE 5005 C	Formula
TC-021 96.40	
TC-153 1.80	
TC-103 1.10	
TC-001 0.70	

Texcharge TC

PANTONE 5015 C	Formula
TC-021	98.80
TC-153	0.50
TC-103	0.40
TC-001	0.30

PANTONE 5025 C	Formula
TC-021	99.40
TC-153	0.20
TC-103	0.20
TC-001	0.20

PANTONE 5035 C	Formula
TC-021	98.85
TC-153	0.42
TC-046	0.31
TC-122	0.21
TC-218	0.21

PANTONE 504 C	Formula
TC-153	45.40
TC-122	30.30
TC-154	15.20
TC-001	7.60
TC-132	1.5

PANTONE 505 C	Formula
TC-153	56.20
TC-154	31.30
TC-122	9.40
TC-001	3.10

PANTONE 506 C	Formula
TC-153	52.20
TC-154	36.50
TC-122	8.70
TC-001	1.70
TC-132	0.9

PANTONE 507 C	Formula
TC-021	92.80
TC-154	5.20
TC-103	1.70
TC-218	0.30

PANTONE 508 C	Formula
TC-021	96.30
TC-154	2.60
TC-103	0.90
TC-218	0.20

PANTONE 509 C	Formula
TC-021	98.20
TC-154	1.30
TC-103	0.40
TC-218	0.10

PANTONE 510 C	Formula
TC-021	98.90
TC-154	0.70
TC-103	0.30
TC-218	0.10

PANTONE 511 C	Formula
TC-154	65.60
TC-153	19.70
TC-132	13.90
TC-001	0.80

PANTONE 512 C	Formula
TC-154	50.00
TC-381	43.80
TC-132	6.20

PANTONE 513 C	Formula
TC-381	52.50
TC-154	40.20
TC-132	3.80
TC-021	3.50

PANTONE 514 C	Formula
TC-021	95.00
TC-154	4.00
TC-132	0.60
TC-122	0.40

PANTONE 515 C	Formula
TC-021	97.50
TC-154	2.00
TC-132	0.30
TC-122	0.20

PANTONE 516 C	Formula
TC-021	98.70
TC-154	1.10
TC-122	0.10
TC-132	0.10

Texcharge TC

PANTONE 517 C	Formula
TC-021	99.40
TC-154	0.50
TC-122	0.10

PANTONE 5115 C	Formula
TC-381	61.95
TC-132	22.12
TC-103	10.62
TC-153	5.31

PANTONE 5125 C	Formula
TC-021	79.60
TC-153	10.90
TC-132	5.50
TC-001	2.60
TC-103	1.4

PANTONE 5135 C	Formula
TC-021	91.80
TC-153	3.80
TC-132	2.40
TC-001	1.40
TC-103	0.6

PANTONE 5145 C	Formula
TC-021	97.00
TC-132	1.10
TC-153	0.90
TC-001	0.60
TC-103	0.4

PANTONE 5155 C	Formula
TC-021	98.60
TC-132	0.50
TC-153	0.30
TC-103	0.30
TC-001	0.3

PANTONE 5165 C	Formula
TC-021	99.40
TC-001	0.20
TC-132	0.20
TC-103	0.10
TC-153	0.1

PANTONE 5175 C	Formula
TC-021	99.60
TC-132	0.10
TC-103	0.10
TC-153	0.10
TC-001	0.1

PANTONE 518 C	Formula
TC-021	49.20
TC-153	23.10
TC-132	18.50
TC-057	4.60
TC-001	4.6

PANTONE 519 C	Formula
TC-154	33.00
TC-021	32.20
TC-132	22.00
TC-153	11.00
TC-001	1.8

PANTONE 520 C	Formula
TC-154	25.40
TC-132	25.40
TC-021	22.00
TC-381	20.40
TC-153	6.8

PANTONE 521 C	Formula
TC-021	91.10
TC-154	7.00
TC-218	1.40
TC-046	0.50

PANTONE 522 C	Formula
TC-021	95.60
TC-154	3.20
TC-218	0.80
TC-046	0.40

PANTONE 523 C	Formula
TC-021	97.50
TC-154	1.80
TC-218	0.40
TC-046	0.30

PANTONE 524 C	Formula
TC-021	99.00
TC-154	0.50
TC-132	0.20
TC-218	0.20
TC-046	0.1

PANTONE 5185 C	Formula
TC-132	56.20
TC-153	27.50
TC-103	14.40
TC-001	1.90

Texcharge TC

PANTONE 5195 C	Formula
TC-021	57.70
TC-153	19.20
TC-132	13.50
TC-103	4.80
TC-001	4.8

PANTONE 5205 C	Formula
TC-021	91.30
TC-153	4.00
TC-132	2.00
TC-001	1.50
TC-103	1.2

PANTONE 5215 C	Formula
TC-021	96.90
TC-132	1.00
TC-103	0.70
TC-153	0.70
TC-001	0.7

PANTONE 5225 C	Formula
TC-021	98.40
TC-132	0.60
TC-001	0.50
TC-103	0.30
TC-153	0.2

PANTONE 5235 C	Formula
TC-021	99.30
TC-132	0.30
TC-103	0.20
TC-001	0.20

PANTONE 5245 C	Formula
TC-021	99.60
TC-132	0.20
TC-103	0.10
TC-001	0.10

PANTONE 525 C	Formula
TC-021	44.30
TC-132	20.20
TC-381	20.20
TC-153	13.70
TC-001	1.6

PANTONE 526 C	Formula
TC-021	46.70
TC-154	29.80
TC-132	22.80
TC-001	0.70

PANTONE 527 C	Formula
TC-021	53.84
TC-132	23.08
TC-154	23.08

PANTONE 528 C	Formula
TC-021	83.00
TC-132	8.50
TC-154	8.50

PANTONE 529 C	Formula
TC-021	96.20
TC-132	1.90
TC-154	1.90

PANTONE 530 C	Formula
TC-021	98.60
TC-132	0.70
TC-154	0.70

PANTONE 531 C	Formula
TC-021	99.06
TC-154	0.53
TC-132	0.23
TC-001	0.18

PANTONE 5255 C	Formula
TC-132	45.11
TC-021	33.83
TC-218	7.52
TC-153	7.52
TC-001	6.02

PANTONE 5265 C	Formula
TC-021	53.70
TC-132	26.80
TC-218	11.40
TC-001	4.80
TC-153	3.3

PANTONE 5275 C	Formula
TC-021	71.40
TC-132	14.30
TC-218	7.10
TC-153	3.60
TC-001	3.6

Texcharge TC

PANTONE 5285 C	Formula
TC-021	91.60
TC-132	4.00
TC-218	2.00
TC-153	1.20
TC-001	1.2

PANTONE 5295 C	Formula
TC-021	97.60
TC-132	1.20
TC-001	0.50
TC-218	0.50
TC-153	0.2

PANTONE 5305 C	Formula
TC-021	99.00
TC-001	0.40
TC-132	0.40
TC-153	0.10
TC-218	0.1

PANTONE 5315 C	Formula
TC-021	99.65
TC-001	0.20
TC-132	0.15

PANTONE 532 C	Formula
TC-021	65.40
TC-001	21.10
TC-132	6.30
TC-218	5.10
TC-153	2.1

PANTONE 533 C	Formula
TC-021	52.40
TC-218	24.20
TC-132	15.30
TC-001	8.10

PANTONE 534 C	Formula
TC-021	60.70
TC-218	22.00
TC-132	13.40
TC-001	3.90

PANTONE 535 C	Formula
TC-021	95.60
TC-218	2.10
TC-132	1.40
TC-001	0.90

PANTONE 536 C	Formula
TC-021	97.70
TC-218	1.00
TC-132	0.70
TC-001	0.60

PANTONE 537 C	Formula
TC-021	98.90
TC-218	0.50
TC-132	0.30
TC-001	0.30

PANTONE 538 C	Formula
TC-021	99.60
TC-218	0.20
TC-132	0.10
TC-001	0.10

PANTONE 539 C	Formula
TC-218	45.00
TC-381	45.00
TC-001	5.00
TC-153	3.00
TC-316	2

PANTONE 540 C	Formula
TC-218	59.40
TC-381	37.00
TC-001	2.20
TC-153	0.70
TC-316	0.7

PANTONE 541 C	Formula
TC-218	98.76
TC-057	1.24

PANTONE 542 C	Formula
TC-021	91.30
TC-218	7.10
TC-132	1.30
TC-001	0.30

PANTONE 543 C	Formula
TC-021	96.70
TC-218	2.50
TC-132	0.50
TC-001	0.20
TC-316	0.1

Texcharge TC

PANTONE 544 C	Formula
TC-021 98.80	
TC-218 1.00	
TC-132 0.10	
TC-001 0.10	

PANTONE 545 C	Formula
TC-021 99.48	
TC-218 0.32	
TC-132 0.10	
TC-001 0.10	

PANTONE 5395 C	Formula
TC-218 85.40	
TC-001 9.40	
TC-316 3.80	
TC-132 1.40	

PANTONE 5405 C	Formula
TC-021 79.00	
TC-218 15.00	
TC-132 3.00	
TC-001 3.00	

PANTONE 5415 C	Formula
TC-021 82.50	
TC-218 12.00	
TC-001 3.20	
TC-132 2.30	

PANTONE 5425 C	Formula
TC-021 93.90	
TC-218 3.80	
TC-001 1.40	
TC-132 0.90	

PANTONE 5435 C	Formula
TC-021 97.70	
TC-218 1.30	
TC-001 0.70	
TC-132 0.30	

PANTONE 5445 C	Formula
TC-021 99.20	
TC-218 0.50	
TC-001 0.20	
TC-132 0.10	

PANTONE 5455 C	Formula
TC-021 99.80	
TC-218 0.10	
TC-001 0.10	

PANTONE 546 C	Formula
TC-218 65.00	
TC-316 24.00	
TC-001 11.00	

PANTONE 547 C	Formula
TC-218 80.00	
TC-316 15.00	
TC-001 5.00	

PANTONE 548 C	Formula
TC-218 78.00	
TC-316 20.00	
TC-001 2.00	

PANTONE 549 C	Formula
TC-021 86.00	
TC-218 12.00	
TC-316 1.00	
TC-001 1.00	

PANTONE 550 C	Formula
TC-021 96.10	
TC-218 3.20	
TC-001 0.50	
TC-316 0.20	

PANTONE 551 C	Formula
TC-021 98.40	
TC-218 1.30	
TC-001 0.20	
TC-316 0.10	

PANTONE 552 C	Formula
TC-021 99.50	
TC-218 0.40	
TC-001 0.10	

Texcharge TC

PANTONE 5463 C	Formula
TC-316	49.80
TC-218	26.19
TC-381	18.68
TC-001	5.33

PANTONE 5473 C	Formula
TC-021	64.10
TC-316	19.70
TC-218	12.80
TC-001	3.40

PANTONE 5483 C	Formula
TC-021	86.90
TC-316	6.60
TC-218	4.20
TC-001	2.30

PANTONE 5493 C	Formula
TC-021	95.60
TC-316	2.30
TC-218	1.30
TC-001	0.80

PANTONE 5503 C	Formula
TC-021	98.20
TC-316	0.90
TC-218	0.50
TC-001	0.40

PANTONE 5513 C	Formula
TC-021	99.30
TC-316	0.30
TC-218	0.20
TC-001	0.20

PANTONE 5523 C	Formula
TC-021	99.70
TC-316	0.10
TC-046	0.10
TC-001	0.10

PANTONE 5467 C	Formula
TC-316	77.70
TC-001	12.60
TC-057	9.70

PANTONE 5477 C	Formula
TC-021	69.90
TC-316	19.80
TC-001	6.30
TC-057	4.00

PANTONE 5487 C	Formula
TC-021	88.70
TC-316	6.50
TC-001	3.20
TC-057	1.60

PANTONE 5497 C	Formula
TC-021	96.50
TC-316	1.60
TC-001	1.30
TC-057	0.60

PANTONE 5507 C	Formula
TC-021	98.70
TC-001	0.60
TC-316	0.50
TC-057	0.20

PANTONE 5517 C	Formula
TC-021	99.40
TC-316	0.20
TC-057	0.20
TC-001	0.20

PANTONE 5527 C	Formula
TC-021	99.70
TC-316	0.10
TC-057	0.10
TC-001	0.10

PANTONE 553 C	Formula
TC-316	56.30
TC-103	14.80
TC-057	14.10
TC-021	11.30
TC-001	3.5

PANTONE 554 C	Formula
TC-316	49.80
TC-021	25.10
TC-057	19.30
TC-103	4.80
TC-001	1

Texcharge TC

PANTONE 555 C	Formula
TC-316 50.10	
TC-021 25.10	
TC-057 19.30	
TC-103 4.80	
TC-001 0.7	

PANTONE 556 C	Formula
TC-021 91.90	
TC-316 4.90	
TC-057 3.00	
TC-001 0.20	

PANTONE 557 C	Formula
TC-021 97.50	
TC-316 1.20	
TC-057 1.00	
TC-001 0.30	

PANTONE 558 C	Formula
TC-021 99.10	
TC-316 0.40	
TC-057 0.30	
TC-001 0.20	

PANTONE 559 C	Formula
TC-021 99.50	
TC-057 0.20	
TC-316 0.20	
TC-001 0.10	

PANTONE 5535 C	Formula
TC-316 69.15	
TC-046 21.28	
TC-001 5.32	
TC-122 4.25	

PANTONE 5545 C	Formula
TC-021 70.80	
TC-316 18.00	
TC-103 9.00	
TC-001 2.20	

PANTONE 5555 C	Formula
TC-021 90.10	
TC-316 5.50	
TC-103 3.30	
TC-001 1.10	

PANTONE 5565 C	Formula
TC-021 95.40	
TC-316 2.30	
TC-103 1.50	
TC-001 0.80	

PANTONE 5575 C	Formula
TC-021 97.90	
TC-316 0.90	
TC-103 0.50	
TC-057 0.40	
TC-001 0.3	

PANTONE 5585 C	Formula
TC-021 99.10	
TC-316 0.50	
TC-103 0.20	
TC-057 0.10	
TC-001 0.1	

PANTONE 5595 C	Formula
TC-021 99.52	
TC-316 0.17	
TC-001 0.16	
TC-046 0.15	

PANTONE 560 C	Formula
TC-316 28.93	
TC-381 28.00	
TC-021 26.17	
TC-046 9.42	
TC-001 7.48	

PANTONE 561 C	Formula
TC-021 40.91	
TC-381 32.73	
TC-316 20.91	
TC-001 3.64	
TC-046 1.81	

PANTONE 562 C	Formula
TC-021 48.80	
TC-381 28.58	
TC-316 20.10	
TC-001 1.66	
TC-046 0.86	

PANTONE 563 C	Formula
TC-021 56.00	
TC-381 40.34	
TC-316 3.17	
TC-001 0.31	
TC-046 0.18	

Texcharge TC

PANTONE 564 C	Formula
TC-021	58.10
TC-381	40.10
TC-316	1.50
TC-001	0.20
TC-046	0.1

PANTONE 565 C	Formula
TC-021	75.00
TC-381	24.16
TC-316	0.58
TC-001	0.16
TC-046	0.1

PANTONE 566 C	Formula
TC-381	59.97
TC-021	39.18
TC-316	0.50
TC-001	0.20
TC-046	0.15

PANTONE 5605 C	Formula
TC-218	39.29
TC-046	39.28
TC-154	21.43

PANTONE 5615 C	Formula
TC-381	66.81
TC-021	12.93
TC-046	8.45
TC-218	6.90
TC-132	4.91

PANTONE 5625 C	Formula
TC-381	43.66
TC-021	43.14
TC-046	5.50
TC-218	4.50
TC-132	3.2

PANTONE 5635 C	Formula
TC-021	96.39
TC-218	1.21
TC-046	1.20
TC-001	1.20

PANTONE 5645 C	Formula
TC-021	98.22
TC-218	0.62
TC-046	0.62
TC-001	0.54

PANTONE 5655 C	Formula
TC-021	99.40
TC-218	0.20
TC-046	0.20
TC-001	0.20

PANTONE 5665 C	Formula
TC-021	99.70
TC-218	0.10
TC-046	0.10
TC-001	0.10

PANTONE 567 C	Formula
TC-316	54.43
TC-046	33.67
TC-021	7.78
TC-122	3.34
TC-001	0.78

PANTONE 568 C	Formula
TC-381	45.66
TC-021	27.40
TC-316	21.92
TC-046	3.65
TC-001	1.37

PANTONE 569 C	Formula
TC-381	63.89
TC-316	19.50
TC-021	15.37
TC-046	0.83
TC-001	0.41

PANTONE 570 C	Formula
TC-021	98.70
TC-316	1.00
TC-218	0.20
TC-046	0.10

PANTONE 571 C	Formula
TC-021	99.16
TC-316	0.62
TC-218	0.12
TC-046	0.10

PANTONE 572 C	Formula
TC-021	99.51
TC-316	0.39
TC-218	0.10

Texcharge TC

PANTONE 573 C	Formula
TC-021	99.57
TC-316	0.33
TC-046	0.10

PANTONE 574 C	Formula
TC-046	41.13
TC-021	32.26
TC-316	13.71
TC-103	9.68
TC-001	3.22

PANTONE 575 C	Formula
TC-021	53.71
TC-046	31.33
TC-316	11.64
TC-103	2.24
TC-001	1.08

PANTONE 576 C	Formula
TC-021	56.27
TC-046	33.90
TC-316	9.15
TC-001	0.68

PANTONE 577 C	Formula
TC-021	96.08
TC-046	2.92
TC-316	0.83
TC-001	0.17

PANTONE 578 C	Formula
TC-021	97.10
TC-046	2.16
TC-316	0.61
TC-001	0.13

PANTONE 579 C	Formula
TC-021	98.49
TC-046	1.11
TC-316	0.30
TC-001	0.10

PANTONE 580 C	Formula
TC-021	98.91
TC-046	0.78
TC-316	0.21
TC-001	0.10

PANTONE 5743 C	Formula
TC-046	74.34
TC-021	9.72
TC-316	8.73
TC-001	7.21

PANTONE 5753 C	Formula
TC-046	58.39
TC-021	32.48
TC-316	5.13
TC-001	4.00

PANTONE 5763 C	Formula
TC-021	80.66
TC-046	14.15
TC-001	2.83
TC-316	2.36

PANTONE 5773 C	Formula
TC-021	92.00
TC-046	5.32
TC-001	1.53
TC-316	1.15

PANTONE 5783 C	Formula
TC-021	97.64
TC-046	1.36
TC-001	0.55
TC-316	0.45

PANTONE 5793 C	Formula
TC-021	98.70
TC-046	0.70
TC-316	0.30
TC-001	0.30

PANTONE 5803 C	Formula
TC-021	99.39
TC-046	0.31
TC-001	0.17
TC-316	0.13

PANTONE 5747 C	Formula
TC-057	59.00
TC-021	18.00
TC-046	14.00
TC-001	7.00
TC-316	2

Texcharge TC

PANTONE 5757 C	Formula
TC-021	58.13
TC-057	30.41
TC-046	7.16
TC-001	3.58
TC-316	0.72

PANTONE 5767 C	Formula
TC-021	83.88
TC-057	13.05
TC-001	1.85
TC-046	1.12
TC-316	0.1

PANTONE 5777 C	Formula
TC-021	91.40
TC-057	6.88
TC-001	1.18
TC-046	0.43
TC-316	0.11

PANTONE 5787 C	Formula
TC-021	96.96
TC-057	2.36
TC-001	0.51
TC-046	0.17

PANTONE 5797 C	Formula
TC-021	98.70
TC-057	1.00
TC-001	0.20
TC-046	0.10

PANTONE 5807 C	Formula
TC-021	99.00
TC-057	0.80
TC-046	0.10
TC-001	0.10

PANTONE 581 C	Formula
TC-057	96.15
TC-001	3.30
TC-046	0.55

PANTONE 582 C	Formula
TC-057	98.26
TC-001	0.79
TC-218	0.55
TC-046	0.40

PANTONE 583 C	Formula
TC-057	80.00
TC-046	18.18
TC-218	1.82

PANTONE 584 C	Formula
TC-021	82.82
TC-057	16.57
TC-046	0.41
TC-218	0.10
TC-001	0.1

PANTONE 585 C	Formula
TC-021	88.82
TC-057	9.98
TC-046	1.00
TC-316	0.20

PANTONE 586 C	Formula
TC-021	94.40
TC-057	5.00
TC-046	0.50
TC-316	0.10

PANTONE 587 C	Formula
TC-021	97.10
TC-057	2.50
TC-046	0.30
TC-316	0.10

PANTONE 5815 C	Formula
TC-046	54.54
TC-103	27.28
TC-218	18.18

PANTONE 5825 C	Formula
TC-021	52.08
TC-046	29.17
TC-103	10.42
TC-218	8.33

PANTONE 5835 C	Formula
TC-021	83.33
TC-046	11.11
TC-103	2.78
TC-218	2.78

Texcharge TC

PANTONE 5845 C	Formula
TC-021	92.67
TC-046	4.03
TC-103	1.61
TC-218	1.37
TC-001	0.32

PANTONE 5855 C	Formula
TC-021	97.12
TC-046	1.55
TC-103	0.47
TC-218	0.47
TC-001	0.39

PANTONE 5865 C	Formula
TC-021	98.36
TC-046	0.73
TC-218	0.45
TC-103	0.36
TC-001	0.1

PANTONE 5875 C	Formula
TC-021	98.77
TC-046	0.53
TC-103	0.30
TC-218	0.30
TC-001	0.1

PANTONE 600 C	Formula
TC-021	99.40
TC-057	0.40
TC-046	0.20

PANTONE 601 C	Formula
TC-021	98.70
TC-057	1.00
TC-046	0.30

PANTONE 602 C	Formula
TC-021	96.62
TC-057	2.98
TC-046	0.40

PANTONE 603 C	Formula
TC-021	91.67
TC-057	7.84
TC-046	0.49

PANTONE 604 C	Formula
TC-021	84.00
TC-057	15.00
TC-046	1.00

PANTONE 605 C	Formula
TC-021	67.90
TC-057	30.00
TC-046	2.00
TC-001	0.10

PANTONE 606 C	Formula
TC-057	99.80
TC-001	0.20

PANTONE 607 C	Formula
TC-021	99.17
TC-057	0.66
TC-046	0.17

PANTONE 608 C	Formula
TC-021	98.90
TC-057	0.90
TC-046	0.20

PANTONE 609 C	Formula
TC-021	98.00
TC-057	1.40
TC-046	0.50
TC-001	0.10

PANTONE 610 C	Formula
TC-021	96.79
TC-057	2.72
TC-046	0.39
TC-001	0.10

PANTONE 611 C	Formula
TC-021	86.60
TC-057	10.82
TC-046	1.55
TC-316	0.93
TC-001	0.1

Texcharge TC

PANTONE 612 C	Formula
TC-021	73.52
TC-046	12.50
TC-057	12.50
TC-316	0.74
TC-001	0.74

PANTONE 613 C	Formula
TC-021	67.36
TC-057	20.60
TC-046	11.09
TC-001	0.79
TC-316	0.16

PANTONE 614 C	Formula
TC-021	99.40
TC-046	0.25
TC-057	0.25
TC-001	0.10

PANTONE 615 C	Formula
TC-021	99.25
TC-046	0.33
TC-057	0.25
TC-001	0.17

PANTONE 616 C	Formula
TC-021	98.90
TC-057	0.50
TC-046	0.40
TC-001	0.20

PANTONE 617 C	Formula
TC-021	97.90
TC-057	1.40
TC-046	0.50
TC-001	0.20

PANTONE 618 C	Formula
TC-021	92.05
TC-057	5.68
TC-046	1.82
TC-001	0.45

PANTONE 619 C	Formula
TC-021	74.37
TC-046	15.75
TC-057	7.00
TC-001	2.62
TC-316	0.26

PANTONE 620 C	Formula
TC-021	74.89
TC-046	16.74
TC-057	6.17
TC-001	1.76
TC-316	0.44

PANTONE 621 C	Formula
TC-021	99.55
TC-046	0.22
TC-001	0.13
TC-218	0.10

PANTONE 622 C	Formula
TC-021	99.35
TC-218	0.29
TC-046	0.22
TC-001	0.14

PANTONE 623 C	Formula
TC-021	98.48
TC-001	0.51
TC-218	0.41
TC-046	0.30
TC-316	0.3

PANTONE 624 C	Formula
TC-021	94.64
TC-316	2.42
TC-001	1.05
TC-046	1.05
TC-218	0.84

PANTONE 625 C	Formula
TC-021	92.07
TC-316	3.40
TC-001	1.84
TC-046	1.56
TC-218	1.13

PANTONE 626 C	Formula
TC-021	57.05
TC-316	17.11
TC-046	11.74
TC-001	8.73
TC-218	5.37

PANTONE 627 C	Formula
TC-316	54.83
TC-381	19.35
TC-046	12.91
TC-001	12.91

Texcharge TC

PANTONE 628 C	Formula
TC-021	99.59
TC-218	0.31
TC-057	0.10

PANTONE 629 C	Formula
TC-021	99.09
TC-218	0.61
TC-057	0.20
TC-001	0.10

PANTONE 630 C	Formula
TC-021	97.54
TC-218	2.05
TC-057	0.31
TC-001	0.10

PANTONE 631 C	Formula
TC-021	95.39
TC-218	3.93
TC-057	0.45
TC-001	0.23

PANTONE 632 C	Formula
TC-021	90.58
TC-218	8.45
TC-057	0.61
TC-001	0.36

PANTONE 633 C	Formula
TC-381	73.40
TC-218	14.68
TC-021	11.01
TC-001	0.73
TC-316	0.18

PANTONE 634 C	Formula
TC-381	54.55
TC-218	36.36
TC-316	9.09

PANTONE 635 C	Formula
TC-021	99.12
TC-218	0.68
TC-316	0.10
TC-046	0.10

PANTONE 636 C	Formula
TC-021	98.67
TC-218	1.00
TC-316	0.33

PANTONE 637 C	Formula
TC-021	97.68
TC-218	2.02
TC-316	0.30

PANTONE 638 C	Formula
TC-021	92.35
TC-218	6.60
TC-316	1.05

PANTONE 639 C	Formula
TC-021	82.47
TC-218	15.47
TC-316	2.06

PANTONE 640 C	Formula
TC-021	68.29
TC-218	29.27
TC-316	2.44

PANTONE 641 C	Formula
TC-381	65.98
TC-218	30.85
TC-316	3.17

PANTONE 642 C	Formula
TC-021	99.52
TC-218	0.38
TC-001	0.10

PANTONE 643 C	Formula
TC-021	98.85
TC-218	0.95
TC-132	0.10
TC-001	0.10

Texcharge TC

PANTONE 644 C	Formula
TC-021 97.82	
TC-218 1.09	
TC-132 0.67	
TC-001 0.42	

PANTONE 645 C	Formula
TC-021 94.60	
TC-218 3.50	
TC-132 1.10	
TC-001 0.80	

PANTONE 646 C	Formula
TC-021 87.80	
TC-218 8.34	
TC-132 2.63	
TC-001 1.23	

PANTONE 647 C	Formula
TC-021 60.41	
TC-218 29.85	
TC-132 7.11	
TC-001 2.13	
TC-057 0.5	

PANTONE 648 C	Formula
TC-218 77.15	
TC-154 16.74	
TC-132 2.90	
TC-057 1.75	
TC-001 1.46	

PANTONE 649 C	Formula
TC-021 99.20	
TC-218 0.50	
TC-154 0.20	
TC-001 0.10	

PANTONE 650 C	Formula
TC-021 98.70	
TC-218 0.70	
TC-154 0.50	
TC-001 0.10	

PANTONE 651 C	Formula
TC-021 97.00	
TC-218 1.50	
TC-154 1.10	
TC-001 0.40	

PANTONE 652 C	Formula
TC-021 88.57	
TC-218 6.67	
TC-154 3.81	
TC-001 0.95	

PANTONE 653 C	Formula
TC-021 68.85	
TC-218 18.93	
TC-154 10.33	
TC-001 1.89	

PANTONE 654 C	Formula
TC-218 76.19	
TC-154 19.05	
TC-001 2.86	
TC-132 1.90	

PANTONE 655 C	Formula
TC-218 63.14	
TC-154 26.32	
TC-132 5.27	
TC-001 5.27	

PANTONE 656 C	Formula
TC-021 99.48	
TC-154 0.27	
TC-218 0.25	

PANTONE 657 C	Formula
TC-021 98.40	
TC-218 0.90	
TC-154 0.60	
TC-001 0.10	

PANTONE 658 C	Formula
TC-021 95.45	
TC-218 2.67	
TC-154 1.78	
TC-001 0.10	

PANTONE 659 C	Formula
TC-021 90.80	
TC-218 5.68	
TC-154 3.41	
TC-001 0.11	

Texcharge TC

PANTONE 660 C	Formula
TC-021	76.00
TC-218	16.48
TC-154	7.34
TC-001	0.18

PANTONE 661 C	Formula
TC-218	50.00
TC-021	30.00
TC-154	20.00

PANTONE 662 C	Formula
TC-132	60.00
TC-218	40.00

PANTONE 663 C	Formula
TC-021	99.70
TC-132	0.20
TC-001	0.10

PANTONE 664 C	Formula
TC-021	99.40
TC-132	0.40
TC-001	0.20

PANTONE 665 C	Formula
TC-021	98.74
TC-132	0.84
TC-001	0.42

PANTONE 666 C	Formula
TC-021	96.53
TC-132	2.89
TC-001	0.58

PANTONE 667 C	Formula
TC-021	87.80
TC-132	9.76
TC-001	2.44

PANTONE 668 C	Formula
TC-021	78.57
TC-132	18.37
TC-001	3.06

PANTONE 669 C	Formula
TC-021	66.67
TC-132	27.78
TC-001	5.55

PANTONE 670 C	Formula
TC-021	99.19
TC-154	0.52
TC-057	0.19
TC-218	0.10

PANTONE 671 C	Formula
TC-021	98.81
TC-154	0.89
TC-057	0.20
TC-218	0.10

PANTONE 672 C	Formula
TC-021	97.49
TC-154	2.09
TC-057	0.28
TC-218	0.14

PANTONE 673 C	Formula
TC-021	92.08
TC-154	7.37
TC-057	0.37
TC-218	0.18

PANTONE 674 C	Formula
TC-021	84.59
TC-154	14.09
TC-057	1.04
TC-218	0.28

PANTONE 675 C	Formula
TC-021	59.93
TC-154	37.45
TC-057	2.25
TC-218	0.37

Texcharge TC

PANTONE 676 C	Formula
TC-381	49.17
TC-154	40.66
TC-153	9.45
TC-218	0.72

PANTONE 677 C	Formula
TC-021	99.42
TC-154	0.38
TC-046	0.10
TC-001	0.10

PANTONE 678 C	Formula
TC-021	99.15
TC-154	0.55
TC-153	0.10
TC-046	0.10
TC-001	0.1

PANTONE 679 C	Formula
TC-021	98.65
TC-154	1.11
TC-046	0.12
TC-001	0.12

PANTONE 680 C	Formula
TC-021	97.19
TC-154	2.16
TC-153	0.43
TC-001	0.22

PANTONE 681 C	Formula
TC-021	91.17
TC-154	7.01
TC-153	1.40
TC-001	0.42

PANTONE 682 C	Formula
TC-021	79.24
TC-154	15.85
TC-153	3.96
TC-001	0.95

PANTONE 683 C	Formula
TC-021	56.18
TC-154	28.09
TC-153	14.04
TC-001	1.69

PANTONE 684 C	Formula
TC-021	99.00
TC-154	0.60
TC-057	0.30
TC-001	0.10

PANTONE 685 C	Formula
TC-021	98.59
TC-154	1.01
TC-057	0.30
TC-001	0.10

PANTONE 686 C	Formula
TC-021	97.39
TC-154	2.01
TC-057	0.50
TC-001	0.10

PANTONE 687 C	Formula
TC-021	94.44
TC-154	4.20
TC-057	1.05
TC-218	0.21
TC-001	0.1

PANTONE 688 C	Formula
TC-021	85.76
TC-154	12.01
TC-057	1.72
TC-218	0.34
TC-001	0.17

PANTONE 689 C	Formula
TC-021	67.95
TC-154	27.18
TC-057	3.85
TC-218	0.68
TC-001	0.34

PANTONE 690 C	Formula
TC-154	92.59
TC-057	3.70
TC-132	2.78
TC-001	0.93

PANTONE 691 C	Formula
TC-021	99.33
TC-153	0.48
TC-046	0.19

Texcharge TC

PANTONE 692 C		Formula
TC-021	98.65	
TC-153	0.72	
TC-046	0.45	
TC-001	0.18	

PANTONE 693 C		Formula
TC-021	96.42	
TC-154	2.39	
TC-046	0.64	
TC-153	0.37	
TC-001	0.18	

PANTONE 694 C		Formula
TC-021	94.58	
TC-154	3.03	
TC-153	1.26	
TC-046	0.88	
TC-001	0.25	

PANTONE 695 C		Formula
TC-021	83.68	
TC-154	8.37	
TC-153	4.18	
TC-046	2.93	
TC-001	0.84	

PANTONE 696 C		Formula
TC-021	56.79	
TC-154	18.93	
TC-153	15.77	
TC-046	6.62	
TC-001	1.89	

PANTONE 697 C		Formula
TC-021	46.33	
TC-154	23.17	
TC-153	20.08	
TC-046	8.11	
TC-001	2.31	

PANTONE 698 C		Formula
TC-021	99.55	
TC-153	0.25	
TC-103	0.20	

PANTONE 699 C		Formula
TC-021	99.00	
TC-153	0.70	
TC-103	0.30	

PANTONE 700 C		Formula
TC-021	98.86	
TC-153	0.74	
TC-103	0.40	

PANTONE 701 C		Formula
TC-021	96.20	
TC-153	2.50	
TC-103	1.20	
TC-001	0.10	

PANTONE 702 C		Formula
TC-021	86.45	
TC-153	9.62	
TC-103	3.83	
TC-001	0.10	

PANTONE 703 C		Formula
TC-021	57.97	
TC-153	28.99	
TC-103	12.56	
TC-001	0.48	

PANTONE 704 C		Formula
TC-153	61.07	
TC-103	26.72	
TC-021	11.45	
TC-001	0.76	

PANTONE 705 C		Formula
TC-021	99.69	
TC-122	0.11	
TC-057	0.10	
TC-154	0.10	

PANTONE 706 C		Formula
TC-021	99.20	
TC-154	0.40	
TC-057	0.20	
TC-122	0.20	

PANTONE 707 C		Formula
TC-021	97.68	
TC-154	1.22	
TC-122	0.73	
TC-057	0.37	

Texcharge TC

PANTONE 708 C	Formula
TC-021	95.24
TC-154	2.38
TC-122	1.59
TC-057	0.79

PANTONE 709 C	Formula
TC-021	81.12
TC-154	9.44
TC-122	6.79
TC-057	2.65

PANTONE 710 C	Formula
TC-021	60.61
TC-122	21.21
TC-154	13.64
TC-057	4.54

PANTONE 711 C	Formula
TC-122	46.36
TC-381	31.14
TC-153	22.50

PANTONE 712 C	Formula
TC-021	99.46
TC-103	0.44
TC-046	0.10

PANTONE 713 C	Formula
TC-021	99.00
TC-103	0.80
TC-046	0.20

PANTONE 714 C	Formula
TC-021	96.80
TC-103	2.40
TC-046	0.70
TC-001	0.10

PANTONE 715 C	Formula
TC-021	91.17
TC-103	6.79
TC-046	1.94
TC-001	0.10

PANTONE 716 C	Formula
TC-021	85.40
TC-103	10.00
TC-046	4.50
TC-001	0.10

PANTONE 717 C	Formula
TC-021	56.39
TC-103	32.89
TC-046	10.34
TC-001	0.38

PANTONE 718 C	Formula
TC-103	47.12
TC-021	36.65
TC-046	15.71
TC-001	0.52

PANTONE 719 C	Formula
TC-021	98.50
TC-046	1.00
TC-122	0.40
TC-001	0.10

PANTONE 720 C	Formula
TC-021	98.25
TC-046	0.64
TC-103	0.58
TC-122	0.41
TC-001	0.12

PANTONE 721 C	Formula
TC-021	97.49
TC-046	2.00
TC-122	0.31
TC-001	0.20

PANTONE 722 C	Formula
TC-021	89.81
TC-103	5.61
TC-046	3.74
TC-001	0.84

PANTONE 723 C	Formula
TC-021	77.75
TC-103	13.75
TC-046	7.78
TC-001	0.72

Texcharge TC

PANTONE 724 C		Formula
TC-021	48.00	
TC-103	40.00	
TC-046	10.00	
TC-001	2.00	

PANTONE 725 C		Formula
TC-103	45.80	
TC-021	38.17	
TC-046	12.21	
TC-001	3.82	

PANTONE 726 C		Formula
TC-021	99.20	
TC-103	0.50	
TC-046	0.20	
TC-001	0.10	

PANTONE 727 C		Formula
TC-021	97.94	
TC-103	1.16	
TC-046	0.56	
TC-001	0.34	

PANTONE 728 C		Formula
TC-021	96.90	
TC-103	2.00	
TC-046	0.70	
TC-001	0.40	

PANTONE 729 C		Formula
TC-021	95.10	
TC-103	3.20	
TC-046	1.10	
TC-001	0.60	

PANTONE 730 C		Formula
TC-021	88.90	
TC-103	7.60	
TC-046	2.30	
TC-001	1.20	

PANTONE 731 C		Formula
TC-103	43.04	
TC-021	39.74	
TC-046	11.92	
TC-001	5.30	

PANTONE 732 C		Formula
TC-103	57.14	
TC-046	21.43	
TC-021	14.29	
TC-001	7.14	