

UVantage POP

Fujifilm Sericol Formulation Guide

Version 2.2

- SMS Base Colors



SERICOL
More than ink...Solutions.

FUJIFILM

UVantage POP

Fujifilm Sericol Formulation Guide

This booklet furnishes the necessary formulas to simulate all the colors in the PANTONE® Color Guide. Predictive simulations were performed via a spectrophotometer simulating Cool White Florescent (CWF) lighting, ink deposit of 380.34.PW on white substrate.

Each SMS Base Color has been carefully selected for its cleanliness of tone, resistance to fading, and suitability for intermixing. In addition, each ink has been formulated to be free of lead and other heavy metals. The SMS Base Colors are listed below and are available in single gallon containers.

Although every care is taken in producing these formulations, variations in substrates and printing conditions may affect the color achieved. Fujifilm Sericol USA Inc. assumes no responsibility for actual color achieved versus the Pantone standard print. For this reason, all formulations must be proofed prior to a production run to ensure color accuracy. Due to variations in ink film thickness, screen mesh, and other variables, some formulas may need adjustments.

All formulations are percentages by weight using the following UVantage POP Series SMS colors:

DESCRIPTION	
POP-064 SMS Yellow GS	POP-165 SMS Magenta
POP-066 SMS Yellow RS	POP-230 SMS Blue
POP-114 SMS Orange	POP-325 SMS Green
POP-121 SMS Red YS	POP-SB Shading Black
POP-127 SMS Violet	POP-MX Mixing Clear
POP-164 SMS Red BS	POP-TW Tinting White

Fujifilm Sericol USA Inc's color mixing ink formulations for screen process printing produce only simulations of PANTONE Colors in this color reproduction method due to differences in ink film, opacity and pigment selection. The selection used in blending inks may cause metamerism. Pantone, Inc. assumes no responsibility for formula accuracy.

*PANTONE® is the property of Pantone Inc.

UVantage POP

Starting Point YELLOW C POP-064 100.00	Formula	Starting Point YELLOW 012 POP-064 94.97 POP-MX 5.03	Formula	Starting Point ORANGE 021 C POP-114 49.71 POP-066 45.92 POP-MX 4.37	Formula	Starting Point WARM RED C POP-114 52.37 POP-TW 25.90 POP-121 21.73	Formula
Starting Point RED 032 C POP-114 48.76 POP-TW 29.37 POP-164 21.87	Formula	Starting Point RUBINE RED C POP-165 72.34 POP-121 15.61 POP-MX 12.05	Formula	Starting Point RHODAMINE RED C POP-165 57.84 POP-MX 42.16	Formula	Starting Point PURPLE C POP-165 35.41 POP-MX 56.12 POP-127 8.47	Formula
Starting Point VIOLET C POP-127 33.67 POP-MX 66.33	Formula	Starting Point BLUE 072 POP-230 70.00 POP-127 30.00	Formula	Starting Point REFLEX BLUE C POP-230 71.22 POP-127 28.78	Formula	Starting Point PROCESS BLUE C POP-230 61.12 POP-MX 38.88	Formula
Starting Point GREEN C POP-325 58.31 POP-MX 38.50 POP-230 3.19	Formula	Starting Point BLACK C POP-SB 95.11 POP-114 4.38 POP-127 0.51	Formula	Starting Point PROCESS YELLOW POP-064 80.30 POP-MX 19.70	Formula	Starting Point PROCESS MAGENT POP-165 76.74 POP-066 12.54 POP-MX 10.72	Formula

UVantage POP

Starting Point PROCESS CYAN C POP-MX 69.80 POP-230 30.20	Formula	Starting Point PROCESS BLACK C POP-SB 100.00	Formula	Starting Point 100 C POP-MX 83.99 POP-064 15.68 POP-325 0.33	Formula	Starting Point 101 C POP-MX 68.75 POP-064 30.75 POP-325 0.50	Formula
Starting Point 102 C POP-064 80.48 POP-MX 18.85 POP-325 0.67	Formula	Starting Point 103 C POP-064 92.88 POP-121 3.78 POP-325 3.34	Formula	Starting Point 104 C POP-064 88.52 POP-325 5.75 POP-114 3.43 POP-164 2.30	Formula	Starting Point 105 C POP-064 63.95 POP-SB 22.82 POP-MX 11.90 POP-325 1.33	Formula
Starting Point 106 C POP-MX 40.00 POP-TW 33.26 POP-064 26.52 POP-325 0.22	Formula	Starting Point 107 C POP-064 45.11 POP-MX 40.07 POP-TW 14.82	Formula	Starting Point 108 C POP-064 66.44 POP-MX 33.56	Formula	Starting Point 109 C POP-064 77.67 POP-MX 21.84 POP-165 0.49	Formula
Starting Point 110 C POP-064 93.55 POP-121 4.42 POP-325 2.03	Formula	Starting Point 111 C POP-064 87.07 POP-325 5.83 POP-121 5.17 POP-164 1.93	Formula	Starting Point 112 C POP-064 83.84 POP-121 10.45 POP-230 5.71	Formula	Starting Point 113 C POP-TW 59.46 POP-064 40.54	Formula

UVantage POP

Starting Point 114 C POP-064 52.00 POP-TW 48.00	Formula	Starting Point 115 C POP-064 52.13 POP-TW 47.76 POP-127 0.11	Formula	Starting Point 116 C POP-064 66.56 POP-TW 23.51 POP-MX 8.77 POP-121 1.16	Formula	Starting Point 117 C POP-064 90.29 POP-121 6.66 POP-325 3.05	Formula
Starting Point 118 C POP-064 84.15 POP-121 10.02 POP-325 5.83	Formula	Starting Point 119 C POP-064 78.15 POP-121 14.04 POP-230 7.81	Formula	Starting Point 120 C POP-TW 75.87 POP-064 23.85 POP-164 0.28	Formula	Starting Point 121 C POP-TW 69.15 POP-064 30.17 POP-165 0.68	Formula
Starting Point 122 C POP-TW 56.93 POP-064 42.07 POP-165 1.00	Formula	Starting Point 123 C POP-064 45.06 POP-TW 33.22 POP-MX 20.00 POP-121 1.72	Formula	Starting Point 124 C POP-066 71.13 POP-064 26.62 POP-SB 2.25	Formula	Starting Point 125 C POP-064 74.69 POP-MX 10.71 POP-121 10.06 POP-325 4.54	Formula
Starting Point 126 C POP-066 58.42 POP-064 27.78 POP-SB 13.80	Formula	Starting Point 1205 C POP-TW 86.97 POP-064 12.48 POP-165 0.55	Formula	Starting Point 1215 C POP-TW 79.35 POP-064 19.79 POP-165 0.86	Formula	Starting Point 1225 C POP-064 45.85 POP-TW 30.45 POP-MX 20.00 POP-114 3.70	Formula

UVantage POP

Starting Point	Formula	
1235 C		
POP-066	86.80	
POP-TW	13.20	

Starting Point	Formula	
1245 C		
POP-064	66.89	
POP-MX	20.00	
POP-121	9.51	
POP-325	3.60	

Starting Point	Formula	
1255 C		
POP-064	61.22	
POP-MX	20.00	
POP-SB	12.76	
POP-114	6.02	

Starting Point	Formula	
1265 C		
POP-064	66.18	
POP-121	22.60	
POP-230	6.61	
POP-325	4.61	

Starting Point	Formula	
127 C		
POP-TW	78.97	
POP-064	20.83	
POP-127	0.20	

Starting Point	Formula	
128 C		
POP-TW	63.97	
POP-064	35.68	
POP-127	0.35	

Starting Point	Formula	
129 C		
POP-064	41.67	
POP-TW	37.73	
POP-MX	20.00	
POP-164	0.60	

Starting Point	Formula	
130 C		
POP-064	94.86	
POP-165	4.61	
POP-325	0.53	

Starting Point	Formula	
131 C		
POP-064	93.11	
POP-164	4.99	
POP-325	1.90	

Starting Point	Formula	
132 C		
POP-064	77.27	
POP-SB	14.75	
POP-114	7.98	

Starting Point	Formula	
133 C		
POP-064	56.51	
POP-SB	39.81	
POP-114	3.68	

Starting Point	Formula	
134 C		
POP-TW	70.48	
POP-064	21.75	
POP-MX	6.25	
POP-121	1.52	

Starting Point	Formula	
135 C		
POP-TW	56.83	
POP-064	40.57	
POP-121	2.60	

Starting Point	Formula	
136 C		
POP-066	63.41	
POP-TW	21.18	
POP-MX	15.00	
POP-165	0.41	

Starting Point	Formula	
137 C		
POP-066	95.38	
POP-114	4.62	

Starting Point	Formula	
138 C		
POP-064	77.57	
POP-114	17.39	
POP-165	3.41	
POP-325	1.63	

UVantage POP

Starting Point	Formula
139 C	
POP-064	69.75
POP-114	20.61
POP-325	6.08
POP-164	3.56

Starting Point	Formula
140 C	
POP-064	52.00
POP-SB	36.18
POP-114	11.82

Starting Point	Formula
1345 C	
POP-TW	70.94
POP-066	28.08
POP-165	0.98

Starting Point	Formula
1355 C	
POP-TW	75.94
POP-064	21.27
POP-121	2.79

Starting Point	Formula
1365 C	
POP-066	49.42
POP-TW	28.50
POP-MX	20.00
POP-121	2.08

Starting Point	Formula
1375 C	
POP-066	74.74
POP-MX	18.15
POP-114	5.96
POP-121	1.15

Starting Point	Formula
1385 C	
POP-064	71.37
POP-114	24.28
POP-325	2.68
POP-164	1.67

Starting Point	Formula
1395 C	
POP-064	63.47
POP-121	27.55
POP-325	8.98

Starting Point	Formula
1405 C	
POP-064	42.69
POP-114	38.39
POP-230	14.24
POP-164	4.68

Starting Point	Formula
141 C	
POP-TW	53.52
POP-064	25.58
POP-MX	20.00
POP-164	0.90

Starting Point	Formula
142 C	
POP-064	42.05
POP-TW	35.24
POP-MX	20.00
POP-165	2.71

Starting Point	Formula
143 C	
POP-064	56.61
POP-TW	21.28
POP-MX	20.00
POP-164	2.11

Starting Point	Formula
144 C	
POP-064	94.30
POP-164	5.00
POP-SB	0.70

Starting Point	Formula
145 C	
POP-064	90.38
POP-164	7.69
POP-325	1.93

Starting Point	Formula
146 C	
POP-064	80.56
POP-SB	13.01
POP-164	6.43

Starting Point	Formula
147 C	
POP-064	69.10
POP-325	10.54
POP-164	10.25
POP-SB	10.11

UVantage POP

Starting Point 148 C POP-TW 67.68 POP-MX 16.15 POP-066 14.69 POP-121 1.48	Formula	Starting Point 149 C POP-TW 73.29 POP-066 24.62 POP-121 2.09	Formula	Starting Point 150 C POP-066 56.96 POP-TW 39.16 POP-121 3.88	Formula	Starting Point 151 C POP-064 72.00 POP-114 28.00	Formula
Starting Point 152 C POP-066 71.83 POP-114 27.14 POP-230 1.03	Formula	Starting Point 153 C POP-066 76.01 POP-114 17.60 POP-325 3.95 POP-164 2.44	Formula	Starting Point 154 C POP-064 55.69 POP-121 33.54 POP-325 10.77	Formula	Starting Point 1485 C POP-TW 62.31 POP-MX 18.74 POP-064 10.14 POP-114 8.81	Formula
Starting Point 1495 C POP-066 51.56 POP-TW 33.93 POP-114 14.51	Formula	Starting Point 1505 C POP-064 63.26 POP-114 36.74	Formula	Starting Point 1525 C POP-114 65.11 POP-064 32.20 POP-230 2.69	Formula	Starting Point 1535 C POP-114 70.29 POP-064 21.84 POP-230 7.87	Formula
Starting Point 1545 C POP-114 46.75 POP-SB 39.60 POP-325 13.65	Formula	Starting Point 155 C POP-TW 89.78 POP-064 9.16 POP-164 0.85 POP-230 0.21	Formula	Starting Point 156 C POP-TW 74.17 POP-064 23.65 POP-164 1.91 POP-230 0.27	Formula	Starting Point 157 C POP-064 41.99 POP-TW 31.28 POP-MX 20.00 POP-165 6.73	Formula

UVantage POP

Starting Point	Formula	
158 C		
POP-064	89.89	
POP-164	9.85	
POP-325	0.26	

Starting Point	Formula	
159 C		
POP-064	85.30	
POP-164	13.02	
POP-325	1.68	

Starting Point	Formula	
160 C		
POP-064	79.53	
POP-164	15.07	
POP-325	5.40	

Starting Point	Formula	
161 C		
POP-064	51.46	
POP-SB	39.82	
POP-164	8.72	

Starting Point	Formula	
1555 C		
POP-TW	72.27	
POP-MX	20.00	
POP-114	6.31	
POP-064	1.42	

Starting Point	Formula	
1565 C		
POP-TW	84.04	
POP-114	10.66	
POP-064	5.30	

Starting Point	Formula	
1575 C		
POP-TW	59.15	
POP-114	21.39	
POP-064	19.46	

Starting Point	Formula	
1585 C		
POP-114	37.90	
POP-064	32.30	
POP-TW	29.80	

Starting Point	Formula	
1595 C		
POP-066	48.71	
POP-114	45.85	
POP-SB	5.44	

Starting Point	Formula	
1605 C		
POP-066	47.33	
POP-114	35.04	
POP-165	10.02	
POP-325	7.61	

Starting Point	Formula	
1615 C		
POP-121	43.98	
POP-064	43.74	
POP-325	12.28	

Starting Point	Formula	
162 C		
POP-TW	93.24	
POP-114	6.12	
POP-064	0.64	

Starting Point	Formula	
163 C		
POP-TW	76.21	
POP-114	18.17	
POP-064	5.62	

Starting Point	Formula	
164 C		
POP-TW	45.76	
POP-114	34.32	
POP-064	19.92	

Starting Point	Formula	
165 C		
POP-114	63.98	
POP-064	36.02	

Starting Point	Formula	
166 C		
POP-114	60.26	
POP-066	36.69	
POP-SB	3.05	

UVantage POP

Starting Point	Formula
167 C	
POP-066	48.28
POP-114	41.13
POP-165	7.06
POP-325	3.53

Starting Point	Formula
168 C	
POP-114	86.17
POP-230	13.83

Starting Point	Formula
1625 C	
POP-TW	87.51
POP-114	9.17
POP-121	3.32

Starting Point	Formula
1635 C	
POP-TW	79.51
POP-114	17.47
POP-121	3.02

Starting Point	Formula
1645 C	
POP-114	50.00
POP-TW	50.00

Starting Point	Formula
1655 C	
POP-114	64.06
POP-TW	28.84
POP-064	7.10

Starting Point	Formula
1665 C	
POP-114	98.59
POP-325	1.41

Starting Point	Formula
1675 C	
POP-066	45.00
POP-114	34.25
POP-165	14.38
POP-325	6.37

Starting Point	Formula
1685 C	
POP-114	54.79
POP-064	26.04
POP-165	10.46
POP-230	8.71

Starting Point	Formula
169 C	
POP-TW	93.00
POP-121	4.96
POP-114	2.04

Starting Point	Formula
170 C	
POP-TW	77.79
POP-114	12.03
POP-121	10.18

Starting Point	Formula
171 C	
POP-TW	53.65
POP-114	37.22
POP-121	9.13

Starting Point	Formula
172 C	
POP-114	65.41
POP-TW	30.01
POP-121	4.58

Starting Point	Formula
173 C	
POP-114	71.93
POP-TW	23.58
POP-SB	4.49

Starting Point	Formula
174 C	
POP-114	50.46
POP-066	34.50
POP-165	9.86
POP-230	5.18

Starting Point	Formula
175 C	
POP-114	39.56
POP-066	37.57
POP-165	12.69
POP-230	10.18

UVantage POP

Starting Point 176 C POP-TW 91.47 POP-121 8.53	Formula	Starting Point 177 C POP-TW 78.90 POP-121 21.10	Formula	Starting Point 178 C POP-TW 53.80 POP-121 46.20	Formula	Starting Point 179 C POP-066 56.25 POP-121 43.14 POP-230 0.61	Formula
Starting Point 180 C POP-066 51.53 POP-121 46.14 POP-230 2.33	Formula	Starting Point 181 C POP-114 50.02 POP-066 26.06 POP-165 14.73 POP-230 9.19	Formula	Starting Point 1765 C POP-TW 88.56 POP-121 7.27 POP-165 4.17	Formula	Starting Point 1775 C POP-TW 62.85 POP-MX 19.99 POP-121 11.08 POP-165 6.08	Formula
Starting Point 1785 C POP-TW 54.52 POP-114 31.31 POP-164 14.17	Formula	Starting Point 1788 C POP-121 49.61 POP-TW 23.14 POP-MX 20.00 POP-114 7.25	Formula	Starting Point 1795 C POP-121 57.75 POP-066 21.38 POP-TW 20.00 POP-230 0.87	Formula	Starting Point 1805 C POP-121 59.18 POP-MX 20.00 POP-064 17.93 POP-230 2.89	Formula
Starting Point 1815 C POP-121 59.80 POP-064 32.02 POP-230 8.18	Formula	Starting Point 1767 C POP-TW 93.74 POP-121 3.75 POP-165 2.51	Formula	Starting Point 1777 C POP-TW 55.35 POP-MX 20.00 POP-121 17.41 POP-164 7.24	Formula	Starting Point 1787 C POP-121 52.62 POP-TW 47.38	Formula

UVantage POP

Starting Point	Formula
1797 C	
POP-121	35.47
POP-165	32.58
POP-066	31.28
POP-325	0.67

Starting Point	Formula
1807 C	
POP-121	49.21
POP-165	28.95
POP-066	16.53
POP-325	5.31

Starting Point	Formula
1817 C	
POP-121	50.36
POP-SB	40.70
POP-TW	8.94

Starting Point	Formula
182 C	
POP-TW	93.41
POP-165	3.92
POP-121	2.67

Starting Point	Formula
183 C	
POP-TW	82.83
POP-165	9.01
POP-121	8.16

Starting Point	Formula
184 C	
POP-TW	67.05
POP-121	19.95
POP-164	13.00

Starting Point	Formula
185 C	
POP-121	96.21
POP-165	3.79

Starting Point	Formula
186 C	
POP-121	88.14
POP-165	11.86

Starting Point	Formula
187 C	
POP-121	54.21
POP-165	42.84
POP-SB	2.95

Starting Point	Formula
188 C	
POP-066	39.14
POP-165	35.61
POP-121	25.25

Starting Point	Formula
189 C	
POP-TW	89.00
POP-165	7.54
POP-121	3.46

Starting Point	Formula
190 C	
POP-TW	81.47
POP-164	11.97
POP-121	6.56

Starting Point	Formula
191 C	
POP-TW	54.47
POP-164	27.45
POP-121	18.08

Starting Point	Formula
192 C	
POP-121	57.95
POP-164	22.05
POP-MX	20.00

Starting Point	Formula
193 C	
POP-164	52.07
POP-121	47.93

Starting Point	Formula
194 C	
POP-164	49.50
POP-121	43.37
POP-SB	7.13

UVantage POP

Starting Point 195 C POP-121 51.27 POP-164 26.45 POP-SB 22.28	Formula	Starting Point 1895 C POP-TW 94.00 POP-165 4.79 POP-121 1.21	Formula	Starting Point 1905 C POP-TW 85.69 POP-165 10.55 POP-121 3.76	Formula	Starting Point 1915 C POP-TW 64.67 POP-164 30.57 POP-121 4.76	Formula
Starting Point 1925 C POP-164 57.95 POP-066 42.05	Formula	Starting Point 1935 C POP-165 58.89 POP-066 26.24 POP-114 14.87	Formula	Starting Point 1945 C POP-165 45.96 POP-121 36.85 POP-066 14.05 POP-325 3.14	Formula	Starting Point 1955 C POP-121 51.42 POP-165 41.78 POP-325 6.80	Formula
Starting Point 196 C POP-TW 95.91 POP-164 2.32 POP-064 1.46 POP-325 0.31	Formula	Starting Point 197 C POP-TW 79.35 POP-165 13.04 POP-064 7.61	Formula	Starting Point 198 C POP-TW 52.26 POP-164 24.72 POP-121 23.02	Formula	Starting Point 199 C POP-121 69.53 POP-164 30.47	Formula
Starting Point 200 C POP-164 43.99 POP-066 34.94 POP-114 19.31 POP-325 1.76	Formula	Starting Point 201 C POP-066 38.80 POP-164 34.88 POP-114 22.46 POP-230 3.86	Formula	Starting Point 202 C POP-164 41.41 POP-064 29.63 POP-114 19.29 POP-325 9.67	Formula	Starting Point 203 C POP-TW 95.72 POP-164 4.12 POP-230 0.16	Formula

UVantage POP

Starting Point 204 C POP-TW 85.88 POP-164 14.12	Formula	Starting Point 205 C POP-TW 63.64 POP-164 36.36	Formula	Starting Point 206 C POP-164 61.49 POP-121 21.96 POP-MX 16.55	Formula	Starting Point 207 C POP-164 97.62 POP-MX 2.38	Formula
Starting Point 208 C POP-164 90.25 POP-SB 9.75	Formula	Starting Point 209 C POP-164 81.39 POP-SB 18.61	Formula	Starting Point 210 C POP-TW 87.51 POP-165 11.06 POP-121 1.43	Formula	Starting Point 211 C POP-TW 74.64 POP-165 22.50 POP-121 2.86	Formula
Starting Point 212 C POP-TW 49.75 POP-MX 20.00 POP-165 16.42 POP-164 13.83	Formula	Starting Point 213 C POP-TW 43.35 POP-164 36.65 POP-MX 20.00	Formula	Starting Point 214 C POP-TW 54.78 POP-164 45.22	Formula	Starting Point 215 C POP-165 48.97 POP-121 28.82 POP-MX 20.00 POP-230 2.21	Formula
Starting Point 216 C POP-165 51.70 POP-114 38.30 POP-230 10.00	Formula	Starting Point 217 C POP-TW 95.63 POP-165 4.05 POP-127 0.32	Formula	Starting Point 218 C POP-TW 72.96 POP-165 27.04	Formula	Starting Point 219 C POP-165 60.69 POP-MX 20.00 POP-TW 19.31	Formula

UVantage POP

Starting Point 220 C POP-165 78.63 POP-121 11.13 POP-066 8.52 POP-325 1.72	Formula	Starting Point 221 C POP-165 73.43 POP-121 22.49 POP-325 4.08	Formula	Starting Point 222 C POP-165 48.66 POP-121 41.00 POP-230 5.49 POP-325 4.85	Formula	Starting Point 223 C POP-TW 84.19 POP-165 15.81	Formula
Starting Point 224 C POP-TW 56.04 POP-165 23.96 POP-MX 20.00	Formula	Starting Point 225 C POP-165 80.00 POP-MX 20.00	Formula	Starting Point 226 C POP-165 100.00	Formula	Starting Point 227 C POP-165 90.28 POP-121 8.36 POP-325 1.36	Formula
Starting Point 228 C POP-165 71.07 POP-121 21.72 POP-325 7.21	Formula	Starting Point 229 C POP-165 47.45 POP-121 36.54 POP-325 16.01	Formula	Starting Point 230 C POP-TW 71.21 POP-MX 20.00 POP-165 8.79	Formula	Starting Point 231 C POP-TW 60.12 POP-MX 20.00 POP-165 19.88	Formula
Starting Point 232 C POP-165 80.00 POP-MX 20.00	Formula	Starting Point 233 C POP-165 100.00	Formula	Starting Point 234 C POP-165 76.83 POP-MX 15.94 POP-114 4.91 POP-325 2.32	Formula	Starting Point 235 C POP-165 81.35 POP-114 14.45 POP-230 4.20	Formula

UVantage POP

Starting Point 236 C POP-TW 92.94 POP-165 7.06	Formula	Starting Point 237 C POP-TW 77.10 POP-165 22.90	Formula	Starting Point 238 C POP-165 60.00 POP-MX 40.00	Formula	Starting Point 239 C POP-165 70.00 POP-MX 30.00	Formula
Starting Point 240 C POP-165 58.43 POP-MX 40.00 POP-127 1.57	Formula	Starting Point 241 C POP-165 60.95 POP-MX 36.76 POP-325 2.29	Formula	Starting Point 242 C POP-164 60.69 POP-121 16.18 POP-MX 13.18 POP-325 9.95	Formula	Starting Point 2365 C POP-TW 95.33 POP-165 4.41 POP-127 0.26	Formula
Starting Point 2375 C POP-TW 48.92 POP-MX 32.91 POP-165 16.29 POP-127 1.88	Formula	Starting Point 2385 C POP-MX 59.93 POP-165 36.99 POP-127 3.08	Formula	Starting Point 2395 C POP-165 98.27 POP-127 1.73	Formula	Starting Point 2405 C POP-165 96.13 POP-127 3.87	Formula
Starting Point 2415 C POP-165 97.32 POP-230 2.68	Formula	Starting Point 2425 C POP-165 80.34 POP-SB 17.96 POP-127 1.70	Formula	Starting Point 243 C POP-TW 94.11 POP-165 5.09 POP-127 0.80	Formula	Starting Point 244 C POP-TW 90.80 POP-165 8.14 POP-127 1.06	Formula

UVantage POP

Starting Point 245 C POP-TW 81.18 POP-165 17.40 POP-127 1.42	Formula	Starting Point 246 C POP-165 49.18 POP-MX 47.30 POP-127 3.52	Formula	Starting Point 247 C POP-165 53.00 POP-MX 42.71 POP-127 4.29	Formula	Starting Point 248 C POP-165 96.71 POP-230 3.29	Formula
Starting Point 249 C POP-165 47.95 POP-MX 29.54 POP-121 15.64 POP-230 6.87	Formula	Starting Point 250 C POP-TW 95.66 POP-165 3.33 POP-127 1.01	Formula	Starting Point 251 C POP-TW 88.29 POP-165 9.47 POP-127 2.24	Formula	Starting Point 252 C POP-MX 50.00 POP-165 46.78 POP-230 3.22	Formula
Starting Point 253 C POP-MX 50.00 POP-165 41.35 POP-127 8.65	Formula	Starting Point 254 C POP-165 89.20 POP-127 10.80	Formula	Starting Point 255 C POP-MX 39.68 POP-165 38.73 POP-SB 15.44 POP-127 6.15	Formula	Starting Point 256 C POP-TW 96.01 POP-165 3.34 POP-230 0.65	Formula
Starting Point 257 C POP-MX 50.00 POP-TW 42.60 POP-165 6.33 POP-230 1.07	Formula	Starting Point 258 C POP-MX 47.69 POP-165 36.37 POP-TW 11.30 POP-230 4.64	Formula	Starting Point 259 C POP-165 87.86 POP-325 9.22 POP-230 2.92	Formula	Starting Point 260 C POP-165 78.64 POP-325 16.49 POP-121 4.87	Formula

UVantage POP

Starting Point	Formula
261 C	
POP-165	70.77
POP-114	13.64
POP-325	7.87
POP-230	7.72

Starting Point	Formula
262 C	
POP-165	54.10
POP-114	28.84
POP-230	17.06

Starting Point	Formula
2562 C	
POP-TW	94.33
POP-165	4.65
POP-127	1.02

Starting Point	Formula
2572 C	
POP-TW	80.73
POP-165	16.93
POP-127	2.34

Starting Point	Formula
2582 C	
POP-MX	47.62
POP-TW	33.47
POP-127	14.15
POP-165	4.76

Starting Point	Formula
2592 C	
POP-MX	50.29
POP-TW	25.43
POP-127	17.16
POP-165	7.12

Starting Point	Formula
2602 C	
POP-165	52.80
POP-MX	34.93
POP-127	12.27

Starting Point	Formula
2612 C	
POP-MX	39.87
POP-165	38.11
POP-127	13.71
POP-SB	8.31

Starting Point	Formula
2622 C	
POP-066	43.59
POP-165	30.99
POP-127	20.09
POP-325	5.33

Starting Point	Formula
2563 C	
POP-TW	94.66
POP-165	2.72
POP-127	2.62

Starting Point	Formula
2573 C	
POP-TW	78.75
POP-165	16.31
POP-127	4.94

Starting Point	Formula
2583 C	
POP-MX	40.00
POP-TW	38.43
POP-165	13.31
POP-127	8.26

Starting Point	Formula
2593 C	
POP-MX	40.01
POP-165	26.40
POP-TW	20.96
POP-127	12.63

Starting Point	Formula
2603 C	
POP-165	75.42
POP-MX	15.00
POP-230	9.58

Starting Point	Formula
2613 C	
POP-MX	37.89
POP-165	37.78
POP-127	13.93
POP-SB	10.40

Starting Point	Formula
2623 C	
POP-121	32.13
POP-127	24.62
POP-165	19.32
POP-MX	15.00
POP-325	8.93

UVantage POP

Starting Point	Formula
2567 C	
POP-TW 95.30	
POP-127 3.63	
POP-165 1.07	

Starting Point	Formula
2577 C	
POP-TW 57.46	
POP-165 23.08	
POP-MX 11.54	
POP-127 7.92	

Starting Point	Formula
2587 C	
POP-TW 40.54	
POP-165 39.64	
POP-127 9.91	
POP-MX 9.91	

Starting Point	Formula
2597 C	
POP-165 61.45	
POP-127 22.03	
POP-MX 16.52	

Starting Point	Formula
2607 C	
POP-165 66.63	
POP-MX 15.01	
POP-127 9.43	
POP-230 8.93	

Starting Point	Formula
2617 C	
POP-165 58.02	
POP-127 26.26	
POP-MX 13.40	
POP-325 2.32	

Starting Point	Formula
2627 C	
POP-165 51.81	
POP-127 22.14	
POP-SB 14.16	
POP-MX 11.89	

Starting Point	Formula
263 C	
POP-TW 98.31	
POP-127 1.69	

Starting Point	Formula
264 C	
POP-TW 95.32	
POP-127 4.68	

Starting Point	Formula
265 C	
POP-TW 48.99	
POP-MX 40.00	
POP-127 10.64	
POP-230 0.37	

Starting Point	Formula
266 C	
POP-MX 39.99	
POP-165 33.56	
POP-127 18.31	
POP-230 8.14	

Starting Point	Formula
267 C	
POP-MX 67.64	
POP-165 21.28	
POP-127 11.08	

Starting Point	Formula
268 C	
POP-165 50.96	
POP-127 15.54	
POP-MX 15.00	
POP-230 9.85	
POP-066 8.65	

Starting Point	Formula
269 C	
POP-066 30.64	
POP-165 29.36	
POP-127 17.99	
POP-MX 14.39	
POP-230 7.62	

Starting Point	Formula
2635 C	
POP-TW 97.01	
POP-127 2.61	
POP-230 0.38	

Starting Point	Formula
2645 C	
POP-TW 95.06	
POP-127 4.50	
POP-230 0.44	

UVantage POP

Starting Point 2655 C POP-TW 70.31 POP-127 14.69 POP-MX 15.00	Formula	Starting Point 2665 C POP-MX 65.00 POP-127 25.18 POP-230 9.82	Formula	Starting Point 2685 C POP-127 50.82 POP-230 34.18 POP-MX 15.00	Formula	Starting Point 2695 C POP-127 37.73 POP-165 21.61 POP-114 17.09 POP-MX 15.00 POP-325 8.57	Formula
Starting Point 270 C POP-TW 91.61 POP-165 5.62 POP-230 2.77	Formula	Starting Point 271 C POP-MX 65.00 POP-TW 29.10 POP-127 3.64 POP-230 2.26	Formula	Starting Point 272 C POP-MX 64.99 POP-TW 25.58 POP-127 5.92 POP-230 3.51	Formula	Starting Point 273 C POP-165 59.57 POP-127 19.69 POP-230 14.80 POP-MX 5.94	Formula
Starting Point 274 C POP-165 53.58 POP-127 21.10 POP-230 13.49 POP-121 11.83	Formula	Starting Point 275 C POP-165 48.36 POP-SB 23.93 POP-127 23.47 POP-230 4.24	Formula	Starting Point 276 C POP-164 43.38 POP-121 29.66 POP-230 26.96	Formula	Starting Point 2705 C POP-TW 93.26 POP-127 4.98 POP-230 1.76	Formula
Starting Point 2715 C POP-TW 90.70 POP-127 6.76 POP-230 2.54	Formula	Starting Point 2725 C POP-MX 65.00 POP-127 18.90 POP-230 16.10	Formula	Starting Point 2735 C POP-230 46.94 POP-127 38.06 POP-MX 15.00	Formula	Starting Point 2745 C POP-127 54.50 POP-230 45.50	Formula

UVantage POP

Starting Point	Formula
2755 C	
POP-127	48.29
POP-165	24.21
POP-MX	15.01
POP-325	12.49

Starting Point	Formula
2765 C	
POP-127	62.73
POP-SB	37.27

Starting Point	Formula
2706 C	
POP-TW	98.15
POP-127	1.07
POP-230	0.78

Starting Point	Formula
2716 C	
POP-TW	93.02
POP-127	3.97
POP-230	3.01

Starting Point	Formula
2726 C	
POP-MX	65.00
POP-230	17.67
POP-127	17.33

Starting Point	Formula
2736 C	
POP-230	54.02
POP-127	30.98
POP-MX	15.00

Starting Point	Formula
2746 C	
POP-230	51.94
POP-127	33.06
POP-MX	15.00

Starting Point	Formula
2756 C	
POP-165	27.50
POP-127	23.45
POP-230	17.42
POP-066	16.63
POP-MX	15

Starting Point	Formula
2766 C	
POP-066	44.78
POP-127	34.15
POP-230	12.75
POP-165	8.32

Starting Point	Formula
2707 C	
POP-TW	97.32
POP-230	1.59
POP-127	1.09

Starting Point	Formula
2717 C	
POP-TW	95.08
POP-230	3.04
POP-127	1.88

Starting Point	Formula
2727 C	
POP-MX	65.00
POP-230	26.96
POP-127	8.04

Starting Point	Formula
2747 C	
POP-165	44.95
POP-230	27.61
POP-127	15.38
POP-MX	12.06

Starting Point	Formula
2757 C	
POP-230	33.20
POP-164	30.95
POP-127	25.31
POP-MX	10.54

Starting Point	Formula
2767 C	
POP-SB	60.92
POP-127	37.23
POP-MX	1.85

Starting Point	Formula
2708 C	
POP-TW	96.44
POP-230	2.02
POP-127	1.54

UVantage POP

Starting Point	Formula
2718 C	
POP-TW 81.03	
POP-230 12.33	
POP-127 6.64	

Starting Point	Formula
2728 C	
POP-230 64.79	
POP-127 20.21	
POP-MX 15.00	

Starting Point	Formula
2738 C	
POP-230 52.77	
POP-127 32.23	
POP-MX 15.00	

Starting Point	Formula
2748 C	
POP-165 60.54	
POP-230 22.21	
POP-127 15.69	
POP-325 1.56	

Starting Point	Formula
2758 C	
POP-165 67.11	
POP-230 20.85	
POP-SB 12.04	

Starting Point	Formula
2768 C	
POP-165 54.77	
POP-230 14.75	
POP-SB 30.48	

Starting Point	Formula
277 C	
POP-TW 96.19	
POP-230 2.43	
POP-127 1.38	

Starting Point	Formula
278 C	
POP-TW 94.20	
POP-230 4.24	
POP-127 1.56	

Starting Point	Formula
279 C	
POP-TW 82.39	
POP-230 13.60	
POP-127 4.01	

Starting Point	Formula
280 C	
POP-230 59.33	
POP-165 32.44	
POP-SB 4.21	
POP-127 4.02	

Starting Point	Formula
281 C	
POP-230 67.22	
POP-127 20.63	
POP-SB 12.15	

Starting Point	Formula
282 C	
POP-230 65.66	
POP-SB 29.95	
POP-127 4.39	

Starting Point	Formula
283 C	
POP-TW 95.71	
POP-230 3.21	
POP-127 1.08	

Starting Point	Formula
284 C	
POP-TW 89.74	
POP-230 7.63	
POP-127 2.63	

Starting Point	Formula
285 C	
POP-MX 65.00	
POP-230 28.28	
POP-127 6.72	

Starting Point	Formula
286 C	
POP-230 82.40	
POP-127 17.60	

UVantage POP

Starting Point 287 C POP-230 68.69 POP-127 23.39 POP-MX 7.92	Formula	Starting Point 288 C POP-230 57.85 POP-127 32.32 POP-SB 9.83	Formula	Starting Point 289 C POP-230 36.67 POP-127 19.67 POP-SB 43.66	Formula	Starting Point 290 C POP-TW 98.12 POP-230 1.88	Formula
Starting Point 291 C POP-TW 96.43 POP-230 2.74 POP-127 0.83	Formula	Starting Point 292 C POP-TW 90.34 POP-230 7.83 POP-127 1.83	Formula	Starting Point 293 C POP-MX 49.01 POP-230 34.35 POP-127 16.64	Formula	Starting Point 294 C POP-230 73.37 POP-127 15.93 POP-SB 10.70	Formula
Starting Point 295 C POP-230 55.37 POP-SB 25.91 POP-127 18.72	Formula	Starting Point 296 C POP-SB 60.85 POP-230 20.51 POP-127 18.64	Formula	Starting Point 2905 C POP-TW 95.28 POP-230 3.87 POP-127 0.85	Formula	Starting Point 2915 C POP-TW 90.23 POP-230 8.38 POP-127 1.39	Formula
Starting Point 2925 C POP-TW 75.06 POP-230 20.82 POP-165 4.12	Formula	Starting Point 2935 C POP-230 51.60 POP-MX 38.59 POP-TW 4.92 POP-127 4.89	Formula	Starting Point 2945 C POP-230 91.58 POP-127 6.92 POP-SB 1.50	Formula	Starting Point 2955 C POP-230 66.62 POP-SB 22.75 POP-127 10.63	Formula

UVantage POP

Starting Point	Formula
2965 C	
POP-230	45.03
POP-SB	42.88
POP-127	12.09

Starting Point	Formula
297 C	
POP-TW	93.19
POP-230	6.21
POP-127	0.60

Starting Point	Formula
298 C	
POP-TW	87.06
POP-230	12.15
POP-127	0.79

Starting Point	Formula
299 C	
POP-TW	74.41
POP-230	24.79
POP-127	0.80

Starting Point	Formula
300 C	
POP-230	86.37
POP-MX	11.62
POP-127	2.01

Starting Point	Formula
301 C	
POP-230	90.00
POP-MX	4.10
POP-127	3.18
POP-SB	2.72

Starting Point	Formula
302 C	
POP-230	71.70
POP-SB	22.91
POP-127	5.39

Starting Point	Formula
303 C	
POP-SB	46.99
POP-230	46.52
POP-127	6.49

Starting Point	Formula
2975 C	
POP-TW	96.98
POP-230	2.72
POP-127	0.30

Starting Point	Formula
2985 C	
POP-TW	89.19
POP-230	10.47
POP-127	0.34

Starting Point	Formula
2995 C	
POP-TW	72.10
POP-230	27.90

Starting Point	Formula
3005 C	
POP-230	85.34
POP-MX	14.66

Starting Point	Formula
3015 C	
POP-230	96.57
POP-SB	3.43

Starting Point	Formula
3025 C	
POP-230	70.66
POP-SB	27.03
POP-127	2.31

Starting Point	Formula
3035 C	
POP-230	58.61
POP-SB	41.39

Starting Point	Formula
304 C	
POP-MX	60.00
POP-TW	37.61
POP-230	2.39

UVantage POP

Starting Point 305 C POP-TW 68.23 POP-MX 25.56 POP-230 6.21	Formula	Starting Point 306 C POP-MX 60.00 POP-TW 25.85 POP-230 14.15	Formula	Starting Point 307 C POP-230 96.41 POP-325 3.59	Formula	Starting Point 308 C POP-230 79.21 POP-SB 16.16 POP-MX 4.63	Formula
Starting Point 309 C POP-230 50.40 POP-SB 49.60	Formula	Starting Point 310 C POP-TW 93.77 POP-230 4.94 POP-325 1.29	Formula	Starting Point 311 C POP-TW 51.53 POP-MX 39.38 POP-230 7.70 POP-325 1.39	Formula	Starting Point 312 C POP-MX 56.25 POP-TW 22.25 POP-230 18.43 POP-325 3.07	Formula
Starting Point 313 C POP-MX 60.00 POP-230 34.30 POP-325 5.70	Formula	Starting Point 314 C POP-230 62.22 POP-MX 22.69 POP-325 15.09	Formula	Starting Point 315 C POP-230 51.33 POP-MX 25.99 POP-SB 12.29 POP-325 10.39	Formula	Starting Point 316 C POP-230 43.31 POP-325 41.21 POP-MX 15.48	Formula
Starting Point 3105 C POP-TW 93.09 POP-230 5.37 POP-325 1.54	Formula	Starting Point 3115 C POP-TW 51.03 POP-MX 39.37 POP-230 6.68 POP-325 2.92	Formula	Starting Point 3125 C POP-MX 57.19 POP-TW 23.04 POP-230 13.77 POP-325 6.00	Formula	Starting Point 3135 C POP-MX 50.56 POP-230 34.98 POP-325 14.46	Formula

UVantage POP

Starting Point 3145 C POP-230 42.31 POP-MX 34.98 POP-325 17.09 POP-SB 5.62	Formula	Starting Point 3155 C POP-230 45.92 POP-MX 22.35 POP-325 18.20 POP-SB 13.53	Formula	Starting Point 3165 C POP-230 49.33 POP-SB 27.90 POP-325 22.77	Formula	Starting Point 317 C POP-TW 98.07 POP-230 1.43 POP-325 0.50	Formula
Starting Point 318 C POP-TW 97.06 POP-230 2.20 POP-325 0.74	Formula	Starting Point 319 C POP-TW 70.97 POP-MX 21.50 POP-230 4.31 POP-325 3.22	Formula	Starting Point 320 C POP-TW 50.28 POP-230 26.42 POP-325 23.30	Formula	Starting Point 321 C POP-MX 37.47 POP-230 32.52 POP-325 27.77 POP-SB 2.24	Formula
Starting Point 322 C POP-MX 32.36 POP-230 30.78 POP-325 24.80 POP-SB 12.06	Formula	Starting Point 323 C POP-230 30.33 POP-SB 25.77 POP-325 23.78 POP-MX 20.12	Formula	Starting Point 324 C POP-TW 51.06 POP-MX 45.00 POP-230 2.68 POP-064 1.26	Formula	Starting Point 325 C POP-MX 60.00 POP-TW 33.57 POP-230 3.52 POP-325 2.91	Formula
Starting Point 326 C POP-MX 60.00 POP-TW 22.97 POP-325 9.54 POP-230 7.49	Formula	Starting Point 327 C POP-325 48.02 POP-230 28.16 POP-TW 23.82	Formula	Starting Point 328 C POP-325 60.71 POP-230 27.06 POP-SB 12.23	Formula	Starting Point 329 C POP-325 51.33 POP-230 27.01 POP-SB 21.66	Formula

UVantage POP

Starting Point	Formula
330 C	
POP-SB	44.24
POP-325	33.76
POP-230	22.00

Starting Point	Formula
3242 C	
POP-TW	93.24
POP-325	4.32
POP-230	2.44

Starting Point	Formula
3252 C	
POP-TW	73.29
POP-MX	17.16
POP-325	6.92
POP-230	2.63

Starting Point	Formula
3262 C	
POP-MX	47.70
POP-TW	30.92
POP-325	15.29
POP-230	6.09

Starting Point	Formula
3272 C	
POP-MX	46.99
POP-325	37.80
POP-230	15.21

Starting Point	Formula
3282 C	
POP-325	39.98
POP-MX	35.95
POP-230	18.26
POP-SB	5.81

Starting Point	Formula
3292 C	
POP-325	46.69
POP-SB	33.30
POP-230	20.01

Starting Point	Formula
3302 C	
POP-SB	50.99
POP-325	35.01
POP-230	14.00

Starting Point	Formula
3245 C	
POP-TW	80.14
POP-MX	13.96
POP-325	4.88
POP-230	1.02

Starting Point	Formula
3255 C	
POP-TW	63.22
POP-MX	25.79
POP-325	9.26
POP-230	1.73

Starting Point	Formula
3265 C	
POP-TW	63.22
POP-MX	25.79
POP-325	9.26
POP-230	1.73

Starting Point	Formula
3275 C	
POP-MX	53.32
POP-325	38.42
POP-230	8.26

Starting Point	Formula
3285 C	
POP-MX	48.40
POP-325	37.35
POP-230	9.63
POP-SB	4.62

Starting Point	Formula
3295 C	
POP-325	41.83
POP-MX	35.26
POP-SB	12.30
POP-230	10.61

Starting Point	Formula
3305 C	
POP-SB	47.75
POP-325	42.70
POP-230	9.55

Starting Point	Formula
3248 C	
POP-TW	48.04
POP-MX	45.00
POP-230	3.57
POP-064	3.39

UVantage POP

Starting Point 3258 C POP-MX 60.00 POP-TW 25.50 POP-230 7.45 POP-064 7.05	Formula	Starting Point 3268 C POP-MX 60.00 POP-325 18.54 POP-066 10.97 POP-230 10.49	Formula	Starting Point 3278 C POP-MX 42.97 POP-325 26.61 POP-230 17.88 POP-064 12.54	Formula	Starting Point 3288 C POP-230 38.52 POP-064 36.31 POP-MX 21.43 POP-325 3.74	Formula
Starting Point 3298 C POP-230 36.89 POP-064 35.27 POP-MX 16.02 POP-SB 11.82	Formula	Starting Point 3308 C POP-SB 62.66 POP-325 26.99 POP-230 10.35	Formula	Starting Point 331 C POP-TW 96.68 POP-325 3.32	Formula	Starting Point 332 C POP-TW 65.62 POP-MX 29.54 POP-325 4.66 POP-SB 0.18	Formula
Starting Point 333 C POP-TW 84.80 POP-325 15.20	Formula	Starting Point 334 C POP-325 75.03 POP-MX 21.83 POP-230 3.14	Formula	Starting Point 335 C POP-325 82.63 POP-SB 17.37	Formula	Starting Point 336 C POP-325 70.31 POP-SB 29.69	Formula
Starting Point 337 C POP-TW 62.34 POP-MX 31.15 POP-064 3.78 POP-230 2.73	Formula	Starting Point 338 C POP-MX 60.00 POP-TW 29.06 POP-064 5.95 POP-230 4.99	Formula	Starting Point 339 C POP-MX 54.90 POP-325 25.60 POP-064 11.62 POP-230 7.88	Formula	Starting Point 340 C POP-325 37.75 POP-MX 25.14 POP-064 21.85 POP-230 15.26	Formula

UVantage POP

Starting Point 341 C POP-064 45.98 POP-230 34.86 POP-MX 14.69 POP-SB 4.47	Formula	Starting Point 342 C POP-064 39.03 POP-230 29.40 POP-MX 17.56 POP-SB 14.01	Formula	Starting Point 343 C POP-325 84.48 POP-SB 9.18 POP-064 6.34	Formula	Starting Point 3375 C POP-TW 90.22 POP-325 8.22 POP-064 1.56	Formula
Starting Point 3385 C POP-TW 78.84 POP-325 17.38 POP-064 3.78	Formula	Starting Point 3395 C POP-TW 53.65 POP-325 37.83 POP-064 8.52	Formula	Starting Point 3405 C POP-325 64.86 POP-MX 20.13 POP-064 15.01	Formula	Starting Point 3415 C POP-325 72.06 POP-SB 16.60 POP-064 11.34	Formula
Starting Point 3425 C POP-325 60.59 POP-SB 30.53 POP-064 8.88	Formula	Starting Point 3435 C POP-SB 52.39 POP-325 43.32 POP-064 4.29	Formula	Starting Point 344 C POP-TW 94.29 POP-325 3.66 POP-064 2.05	Formula	Starting Point 345 C POP-TW 90.10 POP-325 6.35 POP-064 3.55	Formula
Starting Point 346 C POP-TW 80.59 POP-325 12.29 POP-064 7.12	Formula	Starting Point 347 C POP-325 49.50 POP-064 26.73 POP-MX 17.00 POP-066 6.77	Formula	Starting Point 348 C POP-325 56.89 POP-064 33.31 POP-SB 9.80	Formula	Starting Point 349 C POP-325 47.22 POP-SB 30.65 POP-064 22.13	Formula

UVantage POP

Starting Point	Formula
350 C	
POP-SB	57.82
POP-325	27.05
POP-064	15.13

Starting Point	Formula
351 C	
POP-TW	91.76
POP-325	4.57
POP-064	3.67

Starting Point	Formula
352 C	
POP-TW	84.09
POP-325	8.54
POP-064	7.37

Starting Point	Formula
353 C	
POP-TW	77.73
POP-325	11.94
POP-064	10.33

Starting Point	Formula
354 C	
POP-325	55.93
POP-064	44.07

Starting Point	Formula
355 C	
POP-325	57.46
POP-064	39.72
POP-SB	2.82

Starting Point	Formula
356 C	
POP-325	50.50
POP-064	32.47
POP-SB	17.03

Starting Point	Formula
357 C	
POP-325	32.06
POP-SB	49.44
POP-064	18.50

Starting Point	Formula
358 C	
POP-TW	81.13
POP-064	14.72
POP-325	4.15

Starting Point	Formula
359 C	
POP-TW	74.36
POP-064	19.97
POP-325	5.67

Starting Point	Formula
360 C	
POP-064	50.04
POP-TW	34.78
POP-325	15.18

Starting Point	Formula
361 C	
POP-064	60.49
POP-325	25.70
POP-TW	13.81

Starting Point	Formula
362 C	
POP-064	63.97
POP-325	27.32
POP-SB	8.71

Starting Point	Formula
363 C	
POP-064	60.34
POP-325	26.03
POP-SB	13.63

Starting Point	Formula
364 C	
POP-064	51.05
POP-325	24.76
POP-SB	24.19

Starting Point	Formula
365 C	
POP-TW	86.57
POP-064	11.70
POP-325	1.73

UVantage POP

Starting Point 366 C POP-TW 79.50 POP-064 17.87 POP-325 2.63	Formula	Starting Point 367 C POP-TW 61.27 POP-064 34.02 POP-325 4.71	Formula	Starting Point 368 C POP-064 73.70 POP-MX 15.90 POP-325 9.00 POP-114 1.40	Formula	Starting Point 369 C POP-064 64.87 POP-325 18.98 POP-SB 3.38 POP-MX 12.77	Formula
Starting Point 370 C POP-064 63.42 POP-325 18.81 POP-SB 10.57 POP-MX 7.20	Formula	Starting Point 371 C POP-064 57.50 POP-SB 31.27 POP-325 11.23	Formula	Starting Point 372 C POP-TW 85.24 POP-064 13.37 POP-325 1.39	Formula	Starting Point 373 C POP-TW 73.50 POP-064 24.20 POP-325 2.30	Formula
Starting Point 374 C POP-TW 51.21 POP-064 44.93 POP-325 3.86	Formula	Starting Point 375 C POP-064 90.07 POP-325 9.93	Formula	Starting Point 376 C POP-064 86.64 POP-325 11.39 POP-SB 1.97	Formula	Starting Point 377 C POP-064 77.90 POP-325 11.66 POP-SB 10.44	Formula
Starting Point 378 C POP-064 55.74 POP-SB 35.17 POP-325 9.09	Formula	Starting Point 379 C POP-TW 64.02 POP-064 34.80 POP-325 1.18	Formula	Starting Point 380 C POP-064 53.48 POP-TW 24.08 POP-MX 20.00 POP-325 2.44	Formula	Starting Point 381 C POP-064 73.90 POP-MX 23.58 POP-325 2.52	Formula

UVantage POP

Starting Point	Formula	
382 C		
POP-064	75.46	
POP-MX	20.00	
POP-325	4.54	

Starting Point	Formula	
383 C		
POP-064	90.44	
POP-SB	5.61	
POP-325	3.95	

Starting Point	Formula	
384 C		
POP-064	83.85	
POP-SB	12.06	
POP-325	4.09	

Starting Point	Formula	
385 C		
POP-064	69.30	
POP-SB	27.64	
POP-325	3.06	

Starting Point	Formula	
386 C		
POP-TW	61.06	
POP-064	37.89	
POP-325	1.05	

Starting Point	Formula	
387 C		
POP-064	44.94	
POP-TW	33.56	
POP-MX	20.01	
POP-325	1.49	

Starting Point	Formula	
388 C		
POP-064	86.64	
POP-MX	11.24	
POP-325	2.12	

Starting Point	Formula	
389 C		
POP-064	96.75	
POP-325	3.25	

Starting Point	Formula	
390 C		
POP-064	93.58	
POP-325	3.44	
POP-SB	2.98	

Starting Point	Formula	
391 C		
POP-064	85.55	
POP-SB	11.51	
POP-325	2.94	

Starting Point	Formula	
392 C		
POP-064	78.54	
POP-SB	18.95	
POP-325	2.51	

Starting Point	Formula	
393 C		
POP-TW	77.73	
POP-064	21.83	
POP-325	0.44	

Starting Point	Formula	
394 C		
POP-064	49.21	
POP-TW	29.65	
POP-MX	20.00	
POP-325	1.14	

Starting Point	Formula	
395 C		
POP-064	89.41	
POP-MX	8.93	
POP-325	1.66	

Starting Point	Formula	
396 C		
POP-064	98.03	
POP-325	1.97	

Starting Point	Formula	
397 C		
POP-064	94.76	
POP-SB	3.38	
POP-325	1.86	

UVantage POP

Starting Point	Formula
398 C	
POP-064 91.09	
POP-SB 7.22	
POP-325 1.69	

Starting Point	Formula
399 C	
POP-064 87.05	
POP-SB 11.52	
POP-325 1.43	

Starting Point	Formula
3935 C	
POP-TW 57.18	
POP-064 22.29	
POP-MX 19.99	
POP-325 0.54	

Starting Point	Formula
3945 C	
POP-064 54.45	
POP-TW 24.67	
POP-MX 20.00	
POP-325 0.88	

Starting Point	Formula
3955 C	
POP-064 93.37	
POP-MX 5.40	
POP-325 1.23	

Starting Point	Formula
3965 C	
POP-064 99.03	
POP-325 0.97	

Starting Point	Formula
3975 C	
POP-064 92.66	
POP-SB 6.66	
POP-325 0.68	

Starting Point	Formula
3985 C	
POP-064 85.53	
POP-SB 13.99	
POP-325 0.48	

Starting Point	Formula
3995 C	
POP-064 65.42	
POP-SB 33.96	
POP-325 0.62	

Starting Point	Formula
400 C	
POP-TW 76.14	
POP-MX 20.00	
POP-SB 3.70	
POP-121 0.16	

Starting Point	Formula
401 C	
POP-TW 90.69	
POP-121 5.32	
POP-325 3.99	

Starting Point	Formula
402 C	
POP-TW 69.41	
POP-MX 20.00	
POP-SB 10.59	

Starting Point	Formula
403 C	
POP-TW 58.74	
POP-MX 20.00	
POP-SB 16.96	
POP-066 4.30	

Starting Point	Formula
404 C	
POP-TW 47.86	
POP-SB 30.55	
POP-MX 19.99	
POP-165 1.60	

Starting Point	Formula
405 C	
POP-SB 47.18	
POP-TW 21.43	
POP-MX 20.00	
POP-066 11.39	

Starting Point	Formula
406 C	
POP-TW 81.07	
POP-MX 14.23	
POP-SB 4.30	
POP-121 0.40	

UVantage POP

Starting Point	Formula
407 C	
POP-TW	77.77
POP-MX	12.94
POP-SB	8.45
POP-064	0.84

Starting Point	Formula
408 C	
POP-TW	66.39
POP-MX	20.00
POP-SB	12.22
POP-121	1.39

Starting Point	Formula
409 C	
POP-TW	77.28
POP-SB	19.36
POP-114	3.36

Starting Point	Formula
410 C	
POP-TW	46.84
POP-SB	28.99
POP-MX	20.00
POP-165	4.17

Starting Point	Formula
411 C	
POP-SB	46.04
POP-TW	43.67
POP-114	10.29

Starting Point	Formula
412 C	
POP-SB	80.78
POP-066	11.26
POP-165	7.96

Starting Point	Formula
413 C	
POP-TW	75.64
POP-MX	19.99
POP-SB	4.11
POP-325	0.26

Starting Point	Formula
414 C	
POP-TW	88.61
POP-SB	7.77
POP-MX	2.50
POP-064	1.12

Starting Point	Formula
415 C	
POP-TW	66.58
POP-MX	20.01
POP-SB	12.43
POP-325	0.98

Starting Point	Formula
416 C	
POP-TW	57.76
POP-SB	21.08
POP-MX	20.00
POP-325	1.16

Starting Point	Formula
417 C	
POP-TW	47.37
POP-SB	30.27
POP-MX	20.01
POP-325	2.35

Starting Point	Formula
418 C	
POP-SB	46.91
POP-TW	29.71
POP-MX	20.00
POP-325	3.38

Starting Point	Formula
419 C	
POP-SB	93.62
POP-230	6.38

Starting Point	Formula
420 C	
POP-TW	96.09
POP-SB	3.63
POP-230	0.28

Starting Point	Formula
421 C	
POP-TW	92.78
POP-SB	6.82
POP-230	0.40

Starting Point	Formula
422 C	
POP-TW	69.06
POP-MX	20.00
POP-SB	10.13
POP-230	0.81

UVantage POP

Starting Point	Formula
423 C	
POP-TW 63.89	
POP-MX 20.01	
POP-SB 15.17	
POP-230 0.93	

Starting Point	Formula
424 C	
POP-TW 53.65	
POP-SB 24.66	
POP-MX 20.00	
POP-230 1.69	

Starting Point	Formula
425 C	
POP-TW 51.12	
POP-SB 47.76	
POP-127 1.12	

Starting Point	Formula
426 C	
POP-SB 96.09	
POP-127 3.91	

Starting Point	Formula
427 C	
POP-TW 97.03	
POP-121 1.71	
POP-230 1.26	

Starting Point	Formula
428 C	
POP-TW 75.67	
POP-MX 20.00	
POP-121 2.51	
POP-230 1.82	

Starting Point	Formula
429 C	
POP-TW 72.05	
POP-MX 19.99	
POP-121 4.68	
POP-230 3.28	

Starting Point	Formula
430 C	
POP-TW 82.07	
POP-SB 16.47	
POP-230 1.46	

Starting Point	Formula
431 C	
POP-MX 59.49	
POP-121 20.50	
POP-230 15.82	
POP-064 4.19	

Starting Point	Formula
432 C	
POP-066 64.91	
POP-230 14.42	
POP-127 13.79	
POP-MX 6.88	

Starting Point	Formula
433 C	
POP-SB 88.73	
POP-127 11.27	

Starting Point	Formula
434 C	
POP-TW 96.22	
POP-121 2.77	
POP-230 1.01	

Starting Point	Formula
435 C	
POP-TW 94.44	
POP-121 4.10	
POP-230 1.46	

Starting Point	Formula
436 C	
POP-MX 60.00	
POP-TW 29.01	
POP-066 8.39	
POP-127 2.60	

Starting Point	Formula
437 C	
POP-TW 65.47	
POP-SB 23.25	
POP-121 11.28	

Starting Point	Formula
438 C	
POP-SB 56.34	
POP-TW 26.78	
POP-114 16.88	

UVantage POP

Starting Point	Formula
439 C	
POP-114	39.29
POP-325	26.80
POP-MX	21.56
POP-127	12.35

Starting Point	Formula
440 C	
POP-114	58.62
POP-230	28.33
POP-MX	6.74
POP-127	6.31

Starting Point	Formula
441 C	
POP-TW	96.57
POP-SB	3.14
POP-230	0.29

Starting Point	Formula
442 C	
POP-TW	93.02
POP-SB	6.45
POP-230	0.53

Starting Point	Formula
443 C	
POP-MX	60.00
POP-066	16.83
POP-165	12.23
POP-325	10.94

Starting Point	Formula
444 C	
POP-MX	58.53
POP-165	14.80
POP-066	13.38
POP-325	13.29

Starting Point	Formula
445 C	
POP-MX	50.02
POP-SB	45.30
POP-230	4.68

Starting Point	Formula
446 C	
POP-121	39.83
POP-325	26.82
POP-MX	25.00
POP-230	7.79
POP-127	0.56

Starting Point	Formula
447 C	
POP-325	37.72
POP-114	35.31
POP-MX	15.55
POP-127	11.42

Starting Point	Formula
WARM GRAY 1 C	
POP-TW	98.98
POP-SB	0.83
POP-127	0.19

Starting Point	Formula
WARM GRAY 2 C	
POP-TW	97.61
POP-SB	2.34
POP-127	0.05

Starting Point	Formula
WARM GRAY 3 C	
POP-TW	73.10
POP-MX	22.23
POP-SB	4.67

Starting Point	Formula
WARM GRAY 4 C	
POP-MX	52.69
POP-TW	40.36
POP-SB	6.95

Starting Point	Formula
WARM GRAY 5 C	
POP-MX	52.92
POP-TW	37.93
POP-SB	9.15

Starting Point	Formula
WARM GRAY 6 C	
POP-MX	52.10
POP-TW	37.50
POP-SB	10.40

Starting Point	Formula
WARM GRAY 7 C	
POP-MX	60.00
POP-TW	26.01
POP-SB	13.99

UVantage POP

Starting Point	Formula
WARM GRAY 8 C	
POP-MX 53.47	
POP-TW 27.64	
POP-SB 17.61	
POP-121 1.28	

Starting Point	Formula
WARM GRAY 9 C	
POP-MX 54.30	
POP-TW 22.67	
POP-SB 21.38	
POP-121 1.65	

Starting Point	Formula
WARM GRAY 10 C	
POP-MX 58.62	
POP-SB 28.40	
POP-066 11.11	
POP-127 1.87	

Starting Point	Formula
WARM GRAY 11 C	
POP-MX 55.90	
POP-SB 40.34	
POP-114 3.01	
POP-164 0.75	

Starting Point	Formula
COOL GRAY 1 C	
POP-TW 98.43	
POP-121 0.92	
POP-230 0.65	

Starting Point	Formula
COOL GRAY 2 C	
POP-TW 67.45	
POP-MX 30.00	
POP-121 1.66	
POP-230 0.89	

Starting Point	Formula
COOL GRAY 3 C	
POP-TW 66.47	
POP-MX 30.00	
POP-121 2.15	
POP-230 1.38	

Starting Point	Formula
COOL GRAY 4 C	
POP-TW 65.06	
POP-MX 30.00	
POP-121 3.06	
POP-230 1.88	

Starting Point	Formula
COOL GRAY 5 C	
POP-TW 63.45	
POP-MX 30.58	
POP-121 4.09	
POP-230 1.88	

Starting Point	Formula
COOL GRAY 6 C	
POP-TW 91.38	
POP-SB 8.07	
POP-127 0.55	

Starting Point	Formula
COOL GRAY 7 C	
POP-TW 88.23	
POP-SB 11.16	
POP-127 0.61	

Starting Point	Formula
COOL GRAY 8 C	
POP-TW 84.07	
POP-SB 15.24	
POP-127 0.69	

Starting Point	Formula
COOL GRAY 9 C	
POP-TW 78.29	
POP-SB 20.95	
POP-127 0.76	

Starting Point	Formula
COOL GRAY 10 C	
POP-TW 67.06	
POP-SB 32.50	
POP-127 0.44	

Starting Point	Formula
COOL GRAY 11 C	
POP-TW 56.32	
POP-SB 42.74	
POP-127 0.94	

Starting Point	Formula
448 C	
POP-SB 55.05	
POP-066 41.01	
POP-MX 3.94	

UVantage POP

Starting Point 449 C POP-SB 50.02 POP-064 35.17 POP-MX 14.81	Formula	Starting Point 450 C POP-SB 47.91 POP-064 39.76 POP-MX 12.33	Formula	Starting Point 451 C POP-MX 60.00 POP-066 26.54 POP-325 6.79 POP-165 6.67	Formula	Starting Point 452 C POP-MX 60.00 POP-TW 27.85 POP-SB 6.57 POP-064 5.58	Formula
Starting Point 453 C POP-MX 60.00 POP-TW 32.59 POP-SB 4.07 POP-064 3.34	Formula	Starting Point 454 C POP-MX 60.00 POP-TW 35.70 POP-SB 2.56 POP-064 1.74	Formula	Starting Point 4485 C POP-064 50.86 POP-SB 47.06 POP-164 2.08	Formula	Starting Point 4495 C POP-064 65.96 POP-SB 12.02 POP-MX 10.54 POP-325 5.77 POP-164 5.71	Formula
Starting Point 4505 C POP-TW 37.30 POP-066 28.89 POP-MX 25.00 POP-SB 8.81	Formula	Starting Point 4515 C POP-066 41.93 POP-311 26.52 POP-MX 25.00 POP-165 3.67 POP-230 2.88	Formula	Starting Point 4525 C POP-MX 53.64 POP-066 38.35 POP-325 5.12 POP-164 2.89	Formula	Starting Point 4535 C POP-MX 54.42 POP-TW 36.50 POP-064 5.78 POP-SB 3.30	Formula
Starting Point 4545 C POP-TW 49.78 POP-MX 45.45 POP-064 2.80 POP-SB 1.97	Formula	Starting Point 455 C POP-064 58.48 POP-SB 41.52	Formula	Starting Point 456 C POP-064 79.54 POP-121 10.11 POP-230 5.40 POP-MX 4.95	Formula	Starting Point 457 C POP-064 76.36 POP-MX 13.07 POP-SB 9.53 POP-165 1.04	Formula

UVantage POP

Starting Point	Formula
458 C	
POP-TW	58.66
POP-064	38.68
POP-SB	2.66

Starting Point	Formula
459 C	
POP-MX	60.00
POP-TW	20.97
POP-064	17.01
POP-SB	2.02

Starting Point	Formula
460 C	
POP-MX	60.00
POP-TW	27.10
POP-064	11.54
POP-SB	1.36

Starting Point	Formula
461 C	
POP-MX	60.00
POP-TW	32.99
POP-064	6.30
POP-SB	0.71

Starting Point	Formula
462 C	
POP-064	48.78
POP-SB	41.15
POP-164	6.88
POP-325	3.19

Starting Point	Formula
463 C	
POP-064	59.90
POP-SB	33.78
POP-164	6.32

Starting Point	Formula
464 C	
POP-064	74.94
POP-164	14.40
POP-325	10.66

Starting Point	Formula
465 C	
POP-MX	60.00
POP-064	27.68
POP-SB	9.71
POP-165	2.61

Starting Point	Formula
466 C	
POP-MX	60.00
POP-TW	18.27
POP-066	15.76
POP-SB	5.97

Starting Point	Formula
467 C	
POP-MX	47.44
POP-TW	39.36
POP-066	9.51
POP-SB	3.69

Starting Point	Formula
468 C	
POP-TW	90.84
POP-066	6.72
POP-SB	2.44

Starting Point	Formula
4625 C	
POP-114	45.55
POP-SB	40.62
POP-325	13.83

Starting Point	Formula
4635 C	
POP-066	29.35
POP-MX	25.00
POP-SB	22.85
POP-114	22.80

Starting Point	Formula
4645 C	
POP-MX	57.26
POP-066	23.99
POP-SB	10.72
POP-121	8.03

Starting Point	Formula
4655 C	
POP-MX	59.99
POP-TW	24.55
POP-114	8.24
POP-SB	7.22

Starting Point	Formula
4665 C	
POP-MX	60.00
POP-066	28.28
POP-165	8.34
POP-325	3.38

UVantage POP

Starting Point	Formula
4675 C	
POP-MX	60.00
POP-TW	35.60
POP-SB	2.45
POP-114	1.95

Starting Point	Formula
4685 C	
POP-MX	58.05
POP-TW	36.49
POP-066	4.82
POP-127	0.64

Starting Point	Formula
469 C	
POP-SB	44.46
POP-064	28.43
POP-114	27.11

Starting Point	Formula
470 C	
POP-066	52.11
POP-114	39.73
POP-230	5.98
POP-164	2.18

Starting Point	Formula
471 C	
POP-114	43.95
POP-064	35.61
POP-SB	10.69
POP-MX	9.75

Starting Point	Formula
472 C	
POP-MX	56.78
POP-066	36.08
POP-165	6.55
POP-325	0.59

Starting Point	Formula
473 C	
POP-MX	60.01
POP-TW	32.43
POP-064	4.14
POP-121	3.42

Starting Point	Formula
474 C	
POP-MX	60.00
POP-TW	36.19
POP-114	3.49
POP-230	0.32

Starting Point	Formula
475 C	
POP-MX	52.00
POP-TW	45.29
POP-114	2.48
POP-230	0.23

Starting Point	Formula
4695 C	
POP-SB	54.16
POP-114	43.98
POP-127	1.86

Starting Point	Formula
4705 C	
POP-064	49.01
POP-164	20.98
POP-MX	17.79
POP-325	12.22

Starting Point	Formula
4715 C	
POP-TW	47.09
POP-MX	22.15
POP-SB	16.90
POP-114	13.86

Starting Point	Formula
4725 C	
POP-066	46.88
POP-MX	35.00
POP-165	13.48
POP-230	4.64

Starting Point	Formula
4735 C	
POP-MX	55.00
POP-TW	34.99
POP-121	6.70
POP-325	3.31

Starting Point	Formula
4745 C	
POP-MX	55.00
POP-TW	38.73
POP-064	4.94
POP-127	1.33

Starting Point	Formula
4755 C	
POP-MX	54.99
POP-TW	41.71
POP-SB	2.44
POP-121	0.86

UVantage POP

Starting Point 476 C POP-SB 56.65 POP-114 27.84 POP-MX 15.51	Formula	Starting Point 477 C POP-064 47.49 POP-SB 38.64 POP-164 13.87	Formula	Starting Point 478 C POP-064 55.54 POP-164 15.46 POP-SB 29.00	Formula	Starting Point 479 C POP-MX 55.01 POP-066 27.30 POP-064 12.04 POP-127 5.65	Formula
Starting Point 480 C POP-MX 55.00 POP-TW 33.08 POP-064 9.75 POP-127 2.17	Formula	Starting Point 481 C POP-MX 54.99 POP-TW 39.88 POP-121 3.38 POP-325 1.75	Formula	Starting Point 482 C POP-MX 54.99 POP-TW 41.52 POP-121 2.24 POP-325 1.25	Formula	Starting Point 483 C POP-114 46.70 POP-064 27.64 POP-164 13.88 POP-230 11.78	Formula
Starting Point 484 C POP-064 45.04 POP-114 24.68 POP-164 17.58 POP-SB 12.70	Formula	Starting Point 485 C POP-064 75.11 POP-164 24.65 POP-325 0.24	Formula	Starting Point 486 C POP-TW 79.49 POP-064 15.85 POP-164 4.66	Formula	Starting Point 487 C POP-TW 83.37 POP-064 12.38 POP-164 3.96 POP-325 0.29	Formula
Starting Point 488 C POP-TW 87.50 POP-064 7.95 POP-165 4.36 POP-325 0.19	Formula	Starting Point 489 C POP-TW 94.08 POP-064 4.18 POP-164 1.49 POP-325 0.25	Formula	Starting Point 490 C POP-114 62.53 POP-MX 17.39 POP-230 13.60 POP-127 6.48	Formula	Starting Point 491 C POP-121 65.13 POP-MX 18.67 POP-325 16.20	Formula

UVantage POP

Starting Point	Formula
492 C	
POP-121	61.48
POP-TW	24.43
POP-325	9.22
POP-MX	4.87

Starting Point	Formula
493 C	
POP-TW	76.49
POP-165	14.30
POP-114	8.60
POP-230	0.61

Starting Point	Formula
494 C	
POP-TW	94.66
POP-121	2.75
POP-165	2.59

Starting Point	Formula
495 C	
POP-TW	96.40
POP-164	1.81
POP-121	1.79

Starting Point	Formula
496 C	
POP-TW	95.51
POP-165	2.61
POP-121	1.88

Starting Point	Formula
497 C	
POP-121	54.79
POP-MX	22.98
POP-325	19.69
POP-066	2.54

Starting Point	Formula
498 C	
POP-121	54.69
POP-MX	17.24
POP-325	15.98
POP-066	12.09

Starting Point	Formula
499 C	
POP-121	53.88
POP-MX	18.52
POP-325	15.93
POP-066	11.67

Starting Point	Formula
500 C	
POP-MX	50.00
POP-066	26.58
POP-165	20.27
POP-325	3.15

Starting Point	Formula
501 C	
POP-MX	50.00
POP-TW	44.50
POP-121	4.43
POP-127	1.07

Starting Point	Formula
502 C	
POP-MX	50.00
POP-TW	46.81
POP-121	2.53
POP-127	0.66

Starting Point	Formula
503 C	
POP-TW	53.50
POP-MX	44.34
POP-121	1.70
POP-127	0.46

Starting Point	Formula
4975 C	
POP-SB	69.55
POP-114	30.45

Starting Point	Formula
4985 C	
POP-TW	43.55
POP-121	32.65
POP-SB	23.80

Starting Point	Formula
4995 C	
POP-TW	64.31
POP-121	30.63
POP-230	5.06

Starting Point	Formula
5005 C	
POP-MX	50.00
POP-066	24.93
POP-165	20.23
POP-325	4.84

UVantage POP

Starting Point	Formula
5015 C	
POP-TW	90.21
POP-121	8.17
POP-230	1.62

Starting Point	Formula
5025 C	
POP-TW	93.92
POP-121	5.06
POP-230	1.02

Starting Point	Formula
5035 C	
POP-TW	95.06
POP-121	4.02
POP-230	0.92

Starting Point	Formula
504 C	
POP-114	65.37
POP-MX	12.61
POP-230	12.51
POP-127	9.51

Starting Point	Formula
505 C	
POP-121	43.03
POP-SB	31.87
POP-TW	25.10

Starting Point	Formula
506 C	
POP-121	44.32
POP-TW	29.85
POP-SB	25.83

Starting Point	Formula
507 C	
POP-TW	70.78
POP-MX	20.00
POP-121	6.98
POP-127	2.24

Starting Point	Formula
508 C	
POP-TW	92.45
POP-165	5.12
POP-121	2.18
POP-230	0.25

Starting Point	Formula
509 C	
POP-TW	94.36
POP-165	4.35
POP-114	1.03
POP-325	0.26

Starting Point	Formula
510 C	
POP-TW	96.16
POP-165	2.62
POP-121	1.11
POP-230	0.11

Starting Point	Formula
511 C	
POP-165	39.46
POP-121	34.35
POP-MX	14.00
POP-230	12.19

Starting Point	Formula
512 C	
POP-165	71.44
POP-TW	20.92
POP-325	7.64

Starting Point	Formula
513 C	
POP-165	70.95
POP-MX	25.00
POP-230	4.05

Starting Point	Formula
514 C	
POP-TW	87.43
POP-165	11.47
POP-127	1.10

Starting Point	Formula
515 C	
POP-TW	90.61
POP-165	8.70
POP-127	0.69

Starting Point	Formula
516 C	
POP-TW	94.69
POP-165	4.91
POP-127	0.40

UVantage POP

Starting Point 517 C POP-TW 96.66 POP-165 3.34	Formula	Starting Point 5115 C POP-121 57.35 POP-165 19.19 POP-230 18.26 POP-MX 5.20	Formula	Starting Point 5125 C POP-165 43.04 POP-066 34.87 POP-MX 12.42 POP-230 9.67	Formula	Starting Point 5135 C POP-TW 58.64 POP-165 22.31 POP-SB 19.05	Formula
Starting Point 5145 C POP-TW 77.80 POP-SB 11.64 POP-165 10.56	Formula	Starting Point 5155 C POP-TW 90.24 POP-SB 5.31 POP-165 4.45	Formula	Starting Point 5165 C POP-TW 79.92 POP-MX 17.08 POP-164 1.77 POP-325 1.23	Formula	Starting Point 5175 C POP-TW 84.01 POP-MX 13.45 POP-165 1.80 POP-325 0.74	Formula
Starting Point 518 C POP-165 44.63 POP-SB 38.80 POP-325 8.32 POP-066 8.25	Formula	Starting Point 519 C POP-165 66.59 POP-325 16.99 POP-066 9.93 POP-SB 6.49	Formula	Starting Point 520 C POP-165 65.38 POP-MX 17.66 POP-325 15.69 POP-064 1.27	Formula	Starting Point 521 C POP-TW 78.45 POP-165 16.82 POP-325 4.73	Formula
Starting Point 522 C POP-TW 68.60 POP-MX 20.00 POP-165 8.60 POP-325 2.80	Formula	Starting Point 523 C POP-TW 92.70 POP-165 5.45 POP-325 1.85	Formula	Starting Point 524 C POP-TW 95.84 POP-165 3.03 POP-325 1.13	Formula	Starting Point 5185 C POP-066 41.44 POP-SB 28.78 POP-MX 16.89 POP-127 12.89	Formula

UVantage POP

Starting Point	Formula
5195 C	
POP-SB	38.22
POP-165	25.87
POP-TW	20.00
POP-MX	15.91

Starting Point	Formula
5205 C	
POP-TW	49.30
POP-SB	18.73
POP-MX	18.69
POP-165	13.28

Starting Point	Formula
5215 C	
POP-TW	80.19
POP-SB	8.08
POP-MX	6.22
POP-165	5.51

Starting Point	Formula
5225 C	
POP-TW	92.21
POP-SB	4.72
POP-165	3.07

Starting Point	Formula
5235 C	
POP-TW	95.13
POP-SB	2.94
POP-165	1.93

Starting Point	Formula
5245 C	
POP-TW	76.70
POP-MX	20.01
POP-SB	2.21
POP-165	1.08

Starting Point	Formula
525 C	
POP-165	38.96
POP-066	33.27
POP-127	17.87
POP-325	9.90

Starting Point	Formula
526 C	
POP-165	52.31
POP-MX	25.00
POP-127	14.27
POP-325	8.42

Starting Point	Formula
527 C	
POP-165	54.52
POP-MX	24.99
POP-127	14.86
POP-230	5.63

Starting Point	Formula
528 C	
POP-TW	69.66
POP-MX	20.00
POP-127	6.54
POP-165	3.80

Starting Point	Formula
529 C	
POP-TW	95.80
POP-127	2.89
POP-165	1.31

Starting Point	Formula
530 C	
POP-TW	96.71
POP-127	2.02
POP-165	1.27

Starting Point	Formula
531 C	
POP-TW	98.02
POP-127	1.17
POP-165	0.81

Starting Point	Formula
5255 C	
POP-SB	51.06
POP-127	27.21
POP-TW	21.73

Starting Point	Formula
5265 C	
POP-TW	42.81
POP-SB	29.37
POP-127	27.82

Starting Point	Formula
5275 C	
POP-TW	60.90
POP-SB	22.65
POP-127	16.45

UVantage POP

Starting Point	Formula
5285 C	
POP-TW 84.98	
POP-SB 10.20	
POP-127 4.82	

Starting Point	Formula
5295 C	
POP-TW 93.74	
POP-SB 4.26	
POP-127 2.00	

Starting Point	Formula
5305 C	
POP-TW 73.81	
POP-MX 20.00	
POP-165 3.79	
POP-325 2.40	

Starting Point	Formula
5315 C	
POP-TW 96.36	
POP-165 2.25	
POP-325 1.39	

Starting Point	Formula
532 C	
POP-SB 37.29	
POP-325 29.99	
POP-164 24.30	
POP-MX 8.42	

Starting Point	Formula
533 C	
POP-325 39.89	
POP-164 33.45	
POP-MX 23.00	
POP-230 3.66	

Starting Point	Formula
534 C	
POP-165 51.26	
POP-325 34.53	
POP-MX 9.65	
POP-230 4.56	

Starting Point	Formula
535 C	
POP-TW 84.75	
POP-165 8.53	
POP-325 6.72	

Starting Point	Formula
536 C	
POP-TW 88.50	
POP-165 6.28	
POP-325 5.22	

Starting Point	Formula
537 C	
POP-TW 47.72	
POP-MX 50.00	
POP-230 1.24	
POP-164 1.04	

Starting Point	Formula
538 C	
POP-MX 49.99	
POP-TW 48.36	
POP-230 0.87	
POP-164 0.78	

Starting Point	Formula
539 C	
POP-SB 40.36	
POP-230 26.84	
POP-164 22.91	
POP-MX 9.89	

Starting Point	Formula
540 C	
POP-230 51.38	
POP-164 30.90	
POP-064 12.39	
POP-MX 5.33	

Starting Point	Formula
541 C	
POP-230 49.85	
POP-165 39.47	
POP-064 10.68	

Starting Point	Formula
542 C	
POP-TW 88.79	
POP-230 8.26	
POP-164 2.95	

Starting Point	Formula
543 C	
POP-TW 93.01	
POP-230 4.02	
POP-165 2.97	

UVantage POP

Starting Point	Formula
544 C	
POP-TW	97.71
POP-230	1.55
POP-127	0.74

Starting Point	Formula
545 C	
POP-TW	98.24
POP-230	1.15
POP-127	0.61

Starting Point	Formula
5395 C	
POP-SB	62.57
POP-164	24.38
POP-230	13.05

Starting Point	Formula
5405 C	
POP-TW	48.48
POP-325	27.20
POP-165	24.32

Starting Point	Formula
5415 C	
POP-TW	42.71
POP-MX	25.00
POP-325	17.15
POP-165	15.14

Starting Point	Formula
5425 C	
POP-TW	57.66
POP-MX	25.00
POP-325	9.11
POP-165	8.23

Starting Point	Formula
5435 C	
POP-TW	91.75
POP-325	4.25
POP-165	4.00

Starting Point	Formula
5445 C	
POP-TW	73.03
POP-MX	25.00
POP-230	1.20
POP-164	0.77

Starting Point	Formula
5455 C	
POP-TW	98.64
POP-230	0.82
POP-164	0.54

Starting Point	Formula
546 C	
POP-230	35.92
POP-114	31.78
POP-164	17.05
POP-325	15.25

Starting Point	Formula
547 C	
POP-230	38.87
POP-064	36.57
POP-164	22.29
POP-MX	2.27

Starting Point	Formula
548 C	
POP-230	50.27
POP-064	31.04
POP-164	18.69

Starting Point	Formula
549 C	
POP-TW	51.40
POP-MX	35.79
POP-230	8.45
POP-121	4.36

Starting Point	Formula
550 C	
POP-TW	92.37
POP-230	4.89
POP-121	2.74

Starting Point	Formula
551 C	
POP-TW	57.08
POP-MX	40.00
POP-230	2.10
POP-164	0.82

Starting Point	Formula
552 C	
POP-TW	58.03
POP-MX	40.00
POP-230	1.37
pop-164	0.60

UVantage POP

Starting Point	Formula
5463 C	
POP-SB	64.92
POP-230	30.10
POP-127	4.98

Starting Point	Formula
5473 C	
POP-230	30.46
POP-TW	28.24
POP-MX	26.31
POP-114	14.99

Starting Point	Formula
5483 C	
POP-TW	42.08
POP-MX	40.00
POP-SB	10.40
POP-230	7.52

Starting Point	Formula
5493 C	
POP-TW	84.70
POP-SB	5.93
POP-MX	5.69
POP-230	3.68

Starting Point	Formula
5503 C	
POP-TW	94.00
POP-SB	3.66
POP-230	2.34

Starting Point	Formula
5513 C	
POP-TW	80.15
POP-MX	17.21
POP-230	1.60
POP-121	1.04

Starting Point	Formula
5523 C	
POP-TW	98.22
POP-230	1.07
POP-121	0.71

Starting Point	Formula
5467 C	
POP-SB	58.49
POP-064	21.72
POP-230	13.62
POP-164	6.17

Starting Point	Formula
5477 C	
POP-066	50.07
POP-MX	19.97
POP-230	19.33
POP-164	10.63

Starting Point	Formula
5487 C	
POP-TW	68.87
POP-SB	22.42
POP-325	8.71

Starting Point	Formula
5497 C	
POP-TW	49.71
POP-MX	40.00
POP-SB	8.52
POP-230	1.77

Starting Point	Formula
5507 C	
POP-TW	54.53
POP-MX	40.01
POP-SB	4.38
POP-230	1.08

Starting Point	Formula
5517 C	
POP-TW	56.22
POP-MX	40.00
POP-SB	2.99
POP-230	0.79

Starting Point	Formula
5527 C	
POP-TW	61.00
POP-MX	36.82
POP-121	1.16
POP-230	1.02

Starting Point	Formula
553 C	
POP-SB	55.79
POP-064	32.11
POP-230	12.10

Starting Point	Formula
554 C	
POP-064	57.90
POP-230	22.36
POP-165	15.69
POP-MX	4.05

UVantage POP

Starting Point	Formula
555 C	
POP-064	52.52
POP-230	22.69
POP-MX	13.89
POP-165	10.90

Starting Point	Formula
556 C	
POP-TW	39.53
POP-MX	40.00
POP-325	14.42
POP-121	6.05

Starting Point	Formula
557 C	
POP-TW	50.07
POP-MX	40.01
POP-325	6.69
POP-121	3.23

Starting Point	Formula
558 C	
POP-TW	53.96
POP-MX	40.00
POP-SB	3.32
POP-325	2.72

Starting Point	Formula
559 C	
POP-TW	56.50
POP-MX	39.99
POP-SB	2.15
POP-325	1.36

Starting Point	Formula
5535 C	
POP-114	47.78
POP-230	42.36
POP-325	9.86

Starting Point	Formula
5545 C	
POP-MX	33.57
POP-SB	28.09
POP-TW	24.47
POP-325	13.87

Starting Point	Formula
5555 C	
POP-TW	39.37
POP-MX	38.99
POP-SB	15.11
POP-325	6.53

Starting Point	Formula
5565 C	
POP-TW	58.84
POP-MX	28.76
POP-SB	8.90
POP-325	3.50

Starting Point	Formula
5575 C	
POP-TW	81.21
POP-MX	11.22
POP-SB	5.52
POP-325	2.05

Starting Point	Formula
5585 C	
POP-TW	92.77
POP-SB	3.13
POP-MX	2.87
POP-325	1.23

Starting Point	Formula
5595 C	
POP-TW	98.20
POP-SB	1.44
POP-325	0.36

Starting Point	Formula
560 C	
POP-SB	54.20
POP-325	23.26
POP-MX	20.49
POP-127	2.05

Starting Point	Formula
561 C	
POP-325	54.84
POP-MX	20.00
POP-121	16.35
POP-165	8.81

Starting Point	Formula
562 C	
POP-325	43.76
POP-TW	43.31
POP-121	12.93

Starting Point	Formula
563 C	
POP-TW	86.30
POP-325	8.33
POP-SB	5.37

UVantage POP

Starting Point	Formula
564 C	
POP-TW	92.03
POP-066	4.98
POP-230	2.99

Starting Point	Formula
565 C	
POP-TW	76.71
POP-MX	20.00
POP-325	2.75
POP-164	0.54

Starting Point	Formula
566 C	
POP-TW	77.62
POP-MX	19.99
POP-325	2.02
POP-164	0.37

Starting Point	Formula
5605 C	
POP-SB	63.20
POP-325	20.11
POP-114	16.69

Starting Point	Formula
5615 C	
POP-066	55.70
POP-MX	17.95
POP-230	14.33
POP-165	12.02

Starting Point	Formula
5625 C	
POP-MX	40.00
POP-TW	35.82
POP-SB	17.84
POP-325	6.34

Starting Point	Formula
5635 C	
POP-TW	48.81
POP-MX	40.00
POP-SB	8.77
POP-325	2.42

Starting Point	Formula
5645 C	
POP-TW	53.49
POP-MX	40.00
POP-SB	5.18
POP-325	1.33

Starting Point	Formula
5655 C	
POP-TW	55.09
POP-MX	40.00
POP-SB	3.92
POP-325	0.99

Starting Point	Formula
5665 C	
POP-TW	56.52
POP-MX	40.00
POP-SB	2.78
POP-325	0.70

Starting Point	Formula
567 C	
POP-SB	57.78
POP-325	19.22
POP-MX	18.74
POP-230	4.26

Starting Point	Formula
568 C	
POP-325	42.95
POP-MX	27.90
POP-SB	26.94
POP-127	2.21

Starting Point	Formula
569 C	
POP-TW	46.37
POP-325	41.69
POP-SB	11.94

Starting Point	Formula
570 C	
POP-TW	88.85
POP-325	8.19
POP-SB	2.96

Starting Point	Formula
571 C	
POP-TW	75.69
POP-MX	20.00
POP-325	3.94
POP-127	0.37

Starting Point	Formula
572 C	
POP-TW	97.38
POP-325	2.33
POP-164	0.29

UVantage POP

Starting Point 573 C POP-SB 47.03 POP-064 42.41 POP-325 10.56	Formula	Starting Point 574 C POP-064 80.60 POP-230 13.64 POP-164 5.76	Formula	Starting Point 575 C POP-064 69.59 POP-MX 14.66 POP-230 10.98 POP-165 4.77	Formula	Starting Point 576 C POP-066 82.27 POP-230 9.98 POP-MX 7.75	Formula
Starting Point 577 C POP-TW 53.46 POP-066 24.30 POP-MX 19.43 POP-230 2.81	Formula	Starting Point 578 C POP-TW 84.13 POP-066 14.22 POP-230 1.65	Formula	Starting Point 579 C POP-TW 69.94 POP-MX 16.15 POP-066 12.44 POP-230 1.47	Formula	Starting Point 580 C POP-TW 83.78 POP-MX 8.18 POP-066 7.15 POP-230 0.89	Formula
Starting Point 5743 C POP-SB 52.63 POP-064 39.22 POP-325 8.15	Formula	Starting Point 5753 C POP-064 61.44 POP-SB 15.00 POP-230 9.22 POP-165 9.01 POP-MX 5.33	Formula	Starting Point 5763 C POP-066 73.91 POP-MX 10.94 POP-230 10.19 POP-164 4.96	Formula	Starting Point 5773 C POP-066 48.20 POP-MX 40.00 POP-230 6.50 POP-165 5.30	Formula
Starting Point 5783 C POP-TW 51.78 POP-066 23.39 POP-MX 19.21 POP-230 3.12 POP-165 2.5	Formula	Starting Point 5793 C POP-TW 50.64 POP-MX 40.00 POP-SB 4.82 POP-064 4.54	Formula	Starting Point 5803 C POP-TW 58.37 POP-MX 36.48 POP-114 2.76 POP-325 2.39	Formula	Starting Point 5747 C POP-SB 50.98 POP-064 40.39 POP-325 8.63	Formula

UVantage POP

Starting Point	Formula	
5757 C		
POP-064	71.69	
POP-325	13.76	
POP-121	5.12	
POP-127	4.87	
POP-MX	4.56	

Starting Point	Formula	
5767 C		
POP-066	53.19	
POP-MX	33.72	
POP-325	9.80	
POP-164	3.29	

Starting Point	Formula	
5777 C		
POP-066	38.76	
POP-MX	32.30	
POP-TW	22.61	
POP-230	3.94	
POP-165	2.39	

Starting Point	Formula	
5787 C		
POP-TW	49.57	
POP-MX	40.00	
POP-064	6.68	
POP-SB	3.75	

Starting Point	Formula	
5797 C		
POP-TW	52.63	
POP-MX	40.00	
POP-064	4.71	
POP-SB	2.66	

Starting Point	Formula	
5807 C		
POP-TW	55.16	
POP-MX	40.00	
POP-064	2.95	
POP-SB	1.89	

Starting Point	Formula	
581 C		
POP-064	57.98	
POP-SB	38.19	
POP-325	3.83	

Starting Point	Formula	
582 C		
POP-064	83.40	
POP-SB	13.66	
POP-230	2.94	

Starting Point	Formula	
583 C		
POP-064	83.65	
POP-MX	11.54	
POP-230	3.45	
POP-165	1.36	

Starting Point	Formula	
584 C		
POP-MX	40.00	
POP-064	29.33	
POP-066	27.01	
POP-325	3.66	

Starting Point	Formula	
585 C		
POP-MX	40.01	
POP-TW	37.12	
POP-064	22.04	
POP-230	0.83	

Starting Point	Formula	
586 C		
POP-TW	43.42	
POP-MX	40.01	
POP-064	15.96	
POP-230	0.61	

Starting Point	Formula	
587 C		
POP-TW	48.15	
POP-MX	40.00	
POP-064	11.42	
POP-230	0.43	

Starting Point	Formula	
5815 C		
POP-SB	52.49	
POP-064	43.89	
POP-325	3.62	

Starting Point	Formula	
5825 C		
POP-064	65.68	
POP-121	13.12	
POP-MX	12.07	
POP-230	9.13	

Starting Point	Formula	
5835 C		
POP-066	62.39	
POP-MX	29.37	
POP-230	4.82	
POP-165	3.42	

UVantage POP

Starting Point 5845 C POP-066 52.75 POP-MX 40.00 POP-230 4.16 POP-165 3.09	Formula	Starting Point 5855 C POP-TW 47.34 POP-MX 40.01 POP-064 8.43 POP-SB 4.22	Formula	Starting Point 5865 C POP-TW 50.67 POP-MX 40.00 POP-064 6.28 POP-SB 3.05	Formula	Starting Point 5875 C POP-TW 53.93 POP-MX 39.99 POP-064 3.93 POP-SB 2.15	Formula
Starting Point 600 C POP-TW 53.46 POP-MX 40.00 POP-064 6.30 POP-325 0.24	Formula	Starting Point 601 C POP-TW 50.59 POP-MX 40.00 POP-064 9.12 POP-325 0.29	Formula	Starting Point 602 C POP-TW 44.48 POP-MX 40.00 POP-064 15.14 POP-325 0.38	Formula	Starting Point 603 C POP-MX 40.00 POP-TW 26.15 POP-064 33.26 POP-325 0.59	Formula
Starting Point 604 C POP-064 61.92 POP-MX 37.57 POP-230 0.51	Formula	Starting Point 605 C POP-064 98.36 POP-325 1.19 POP-164 0.45	Formula	Starting Point 606 C POP-064 95.01 POP-114 2.85 POP-325 2.14	Formula	Starting Point 607 C POP-TW 72.48 POP-MX 20.00 POP-064 7.31 POP-230 0.21	Formula
Starting Point 608 C POP-TW 70.56 POP-MX 20.00 POP-064 9.19 POP-230 0.25	Formula	Starting Point 609 C POP-TW 80.55 POP-064 19.01 POP-230 0.44	Formula	Starting Point 610 C POP-064 43.00 POP-TW 34.48 POP-MX 20.00 POP-SB 2.52	Formula	Starting Point 611 C POP-066 63.05 POP-MX 19.99 POP-064 13.33 POP-325 3.63	Formula

UVantage POP

Starting Point	Formula
612 C	
POP-064	89.98
POP-325	3.44
POP-MX	3.31
POP-165	3.27

Starting Point	Formula
613 C	
POP-064	89.27
POP-114	7.14
POP-230	3.59

Starting Point	Formula
614 C	
POP-TW	89.48
POP-066	9.99
POP-230	0.53

Starting Point	Formula
615 C	
POP-TW	72.08
POP-MX	19.99
POP-064	6.26
POP-SB	1.67

Starting Point	Formula
616 C	
POP-TW	68.27
POP-MX	20.00
POP-064	9.20
POP-SB	2.53

Starting Point	Formula
617 C	
POP-TW	51.08
POP-066	25.53
POP-MX	20.00
POP-SB	3.39

Starting Point	Formula
618 C	
POP-064	74.80
POP-MX	19.99
POP-230	3.81
POP-165	1.40

Starting Point	Formula
619 C	
POP-064	66.53
POP-MX	17.43
POP-SB	6.33
POP-165	5.01
POP-325	4.7

Starting Point	Formula
620 C	
POP-064	76.90
POP-SB	22.19
POP-325	0.91

Starting Point	Formula
621 C	
POP-TW	87.58
POP-MX	9.91
POP-SB	1.68
POP-325	0.83

Starting Point	Formula
622 C	
POP-TW	75.67
POP-MX	20.01
POP-SB	2.70
POP-325	1.62

Starting Point	Formula
623 C	
POP-TW	71.55
POP-MX	20.00
POP-SB	5.30
POP-325	3.15

Starting Point	Formula
624 C	
POP-TW	63.17
POP-MX	20.00
POP-SB	10.28
POP-325	6.55

Starting Point	Formula
625 C	
POP-TW	47.57
POP-MX	20.00
POP-SB	18.08
POP-325	14.35

Starting Point	Formula
626 C	
POP-SB	39.74
POP-325	29.70
POP-MX	20.00
POP-TW	10.56

Starting Point	Formula
627 C	
POP-SB	79.57
POP-230	20.43

UVantage POP

Starting Point	Formula
628 C	
POP-TW	85.25
POP-MX	12.91
POP-230	1.41
POP-SB	0.43

Starting Point	Formula
629 C	
POP-TW	97.46
POP-230	2.19
POP-121	0.35

Starting Point	Formula
630 C	
POP-TW	79.19
POP-MX	15.49
POP-230	4.20
POP-SB	1.12

Starting Point	Formula
631 C	
POP-TW	69.98
POP-MX	20.01
POP-230	8.12
POP-SB	1.89

Starting Point	Formula
632 C	
POP-TW	61.34
POP-MX	20.00
POP-230	15.73
POP-SB	2.93

Starting Point	Formula
633 C	
POP-TW	40.05
POP-230	34.62
POP-MX	19.99
POP-SB	5.34

Starting Point	Formula
634 C	
POP-230	66.67
POP-MX	20.00
POP-SB	9.11
POP-066	4.22

Starting Point	Formula
635 C	
POP-TW	97.89
POP-230	2.11

Starting Point	Formula
636 C	
POP-TW	96.22
POP-230	3.78

Starting Point	Formula
637 C	
POP-TW	78.17
POP-MX	14.04
POP-230	7.79

Starting Point	Formula
638 C	
POP-TW	72.17
POP-MX	13.53
POP-230	13.47
POP-325	0.83

Starting Point	Formula
639 C	
POP-TW	50.38
POP-230	29.62
POP-MX	20.00

Starting Point	Formula
640 C	
POP-230	45.42
POP-TW	34.58
POP-MX	20.00

Starting Point	Formula
641 C	
POP-230	96.41
POP-325	3.59

Starting Point	Formula
642 C	
POP-TW	98.67
POP-230	0.75
POP-127	0.58

Starting Point	Formula
643 C	
POP-TW	98.37
POP-230	1.00
POP-127	0.63

UVantage POP

Starting Point	Formula
644 C	
POP-TW	69.59
POP-MX	25.00
POP-230	3.52
POP-164	1.89

Starting Point	Formula
645 C	
POP-TW	65.14
POP-MX	25.00
POP-230	6.47
POP-164	3.39

Starting Point	Formula
646 C	
POP-TW	81.96
POP-230	12.00
POP-164	6.04

Starting Point	Formula
647 C	
POP-TW	49.37
POP-230	36.32
POP-164	14.31

Starting Point	Formula
648 C	
POP-230	44.59
POP-164	35.73
POP-MX	10.86
POP-064	8.82

Starting Point	Formula
649 C	
POP-TW	98.75
POP-230	0.64
POP-127	0.61

Starting Point	Formula
650 C	
POP-TW	73.31
POP-MX	25.00
POP-230	0.95
POP-127	0.74

Starting Point	Formula
651 C	
POP-TW	71.62
POP-MX	25.00
POP-230	2.04
POP-127	1.34

Starting Point	Formula
652 C	
POP-TW	92.76
POP-230	4.67
POP-127	2.57

Starting Point	Formula
653 C	
POP-TW	55.26
POP-230	29.27
POP-164	15.47

Starting Point	Formula
654 C	
POP-230	46.62
POP-164	30.10
POP-MX	15.44
POP-064	7.84

Starting Point	Formula
655 C	
POP-230	40.46
POP-SB	38.54
POP-127	21.00

Starting Point	Formula
656 C	
POP-TW	98.88
POP-230	0.59
POP-127	0.53

Starting Point	Formula
657 C	
POP-TW	98.10
POP-230	1.10
POP-127	0.80

Starting Point	Formula
658 C	
POP-TW	96.34
POP-230	2.22
POP-127	1.44

Starting Point	Formula
659 C	
POP-TW	66.49
POP-MX	25.00
POP-230	5.59
POP-127	2.92

UVantage POP

Starting Point 660 C POP-TW 72.93 POP-230 20.25 POP-127 6.82	Formula	Starting Point 661 C POP-230 83.10 POP-127 16.90	Formula	Starting Point 662 C POP-230 46.91 POP-165 43.27 POP-127 9.82	Formula	Starting Point 663 C POP-TW 99.09 POP-127 0.76 POP-230 0.15	Formula
Starting Point 664 C POP-TW 99.07 POP-127 0.75 POP-230 0.18	Formula	Starting Point 665 C POP-TW 97.19 POP-SB 1.43 POP-127 1.38	Formula	Starting Point 666 C POP-TW 91.71 POP-SB 5.01 POP-127 3.28	Formula	Starting Point 667 C POP-TW 56.14 POP-MX 25.00 POP-SB 10.97 POP-127 7.89	Formula
Starting Point 668 C POP-TW 45.09 POP-MX 25.00 POP-SB 15.88 POP-127 14.03	Formula	Starting Point 669 C POP-SB 29.32 POP-127 28.11 POP-MX 25.00 POP-TW 17.57	Formula	Starting Point 670 C POP-TW 98.41 POP-165 1.21 POP-127 0.38	Formula	Starting Point 671 C POP-TW 71.31 POP-MX 25.00 POP-165 3.46 POP-230 0.23	Formula
Starting Point 672 C POP-TW 68.47 POP-MX 25.01 POP-165 6.26 POP-230 0.26	Formula	Starting Point 673 C POP-TW 67.24 POP-MX 17.93 POP-165 12.90 POP-SB 1.93	Formula	Starting Point 674 C POP-TW 44.66 POP-165 27.47 POP-MX 25.00 POP-SB 2.87	Formula	Starting Point 675 C POP-165 66.52 POP-MX 20.00 POP-066 11.35 POP-325 2.13	Formula

UVantage POP

Starting Point	Formula
676 C	
POP-165	77.85
POP-121	18.63
POP-325	3.52

Starting Point	Formula
677 C	
POP-TW	98.49
POP-164	1.21
POP-230	0.30

Starting Point	Formula
678 C	
POP-TW	97.93
POP-164	1.67
POP-230	0.40

Starting Point	Formula
679 C	
POP-TW	77.21
POP-MX	20.00
POP-164	2.25
POP-230	0.54

Starting Point	Formula
680 C	
POP-TW	72.61
POP-MX	20.00
POP-164	5.61
POP-325	1.78

Starting Point	Formula
681 C	
POP-TW	55.86
POP-MX	20.01
POP-165	17.14
POP-SB	6.99

Starting Point	Formula
682 C	
POP-TW	60.12
POP-164	36.04
POP-230	3.84

Starting Point	Formula
683 C	
POP-165	55.75
POP-SB	26.58
POP-121	17.67

Starting Point	Formula
684 C	
POP-TW	97.25
POP-121	1.88
POP-127	0.87

Starting Point	Formula
685 C	
POP-TW	76.71
POP-MX	20.00
POP-121	2.17
POP-127	1.12

Starting Point	Formula
686 C	
POP-TW	94.88
POP-164	3.16
POP-SB	1.96

Starting Point	Formula
687 C	
POP-TW	68.46
POP-MX	19.99
POP-121	7.88
POP-127	3.67

Starting Point	Formula
688 C	
POP-TW	51.68
POP-MX	20.00
POP-165	20.59
POP-SB	7.73

Starting Point	Formula
689 C	
POP-165	51.50
POP-066	21.95
POP-MX	20.00
POP-325	6.55

Starting Point	Formula
690 C	
POP-165	38.73
POP-121	32.64
POP-325	14.70
POP-MX	13.93

Starting Point	Formula
691 C	
POP-TW	98.71
POP-164	0.87
POP-SB	0.42

UVantage POP

Starting Point	Formula
692 C	
POP-TW	77.43
POP-MX	20.01
POP-SB	1.29
POP-164	1.27

Starting Point	Formula
693 C	
POP-TW	94.26
POP-114	4.06
POP-127	1.68

Starting Point	Formula
694 C	
POP-TW	85.71
POP-121	12.30
POP-230	1.99

Starting Point	Formula
695 C	
POP-MX	40.00
POP-066	28.29
POP-165	26.98
POP-325	4.73

Starting Point	Formula
696 C	
POP-MX	30.92
POP-165	29.49
POP-066	26.44
POP-SB	13.15

Starting Point	Formula
697 C	
POP-165	42.66
POP-114	30.56
POP-MX	16.40
POP-325	10.38

Starting Point	Formula
698 C	
POP-TW	98.69
POP-164	0.88
POP-114	0.43

Starting Point	Formula
699 C	
POP-TW	57.79
POP-MX	39.99
POP-164	1.15
POP-121	1.07

Starting Point	Formula
700 C	
POP-TW	50.33
POP-MX	40.00
POP-165	5.33
POP-066	4.34

Starting Point	Formula
701 C	
POP-TW	80.30
POP-165	11.87
POP-064	7.83

Starting Point	Formula
702 C	
POP-MX	40.00
POP-165	30.03
POP-066	28.68
POP-325	1.29

Starting Point	Formula
703 C	
POP-165	35.58
POP-066	23.41
POP-MX	20.00
POP-121	18.68
POP-325	2.33

Starting Point	Formula
704 C	
POP-121	57.96
POP-165	30.34
POP-MX	6.52
POP-325	5.18

Starting Point	Formula
705 C	
POP-TW	98.01
POP-165	1.22
POP-121	0.77

Starting Point	Formula
706 C	
POP-TW	96.26
POP-165	2.17
POP-121	1.57

Starting Point	Formula
707 C	
POP-TW	93.40
POP-121	3.69
POP-165	2.91

UVantage POP

Starting Point	Formula
708 C	
POP-TW	86.32
POP-121	7.90
POP-165	5.78

Starting Point	Formula
709 C	
POP-TW	76.43
POP-121	15.38
POP-164	8.19

Starting Point	Formula
710 C	
POP-MX	40.01
POP-165	27.18
POP-121	16.81
POP-066	16.00

Starting Point	Formula
711 C	
POP-121	46.15
POP-MX	40.00
POP-164	12.71
POP-325	1.14

Starting Point	Formula
712 C	
POP-TW	52.91
POP-MX	40.01
POP-066	4.01
POP-114	3.07

Starting Point	Formula
713 C	
POP-TW	49.56
POP-MX	40.00
POP-066	6.10
POP-114	4.34

Starting Point	Formula
714 C	
POP-TW	65.84
POP-066	29.56
POP-121	4.60

Starting Point	Formula
715 C	
POP-066	44.11
POP-MX	40.00
POP-114	14.11
POP-SB	1.78

Starting Point	Formula
716 C	
POP-066	50.64
POP-114	28.20
POP-MX	20.00
POP-325	1.16

Starting Point	Formula
717 C	
POP-114	50.37
POP-064	47.72
POP-325	1.91

Starting Point	Formula
718 C	
POP-114	60.14
POP-064	37.20
POP-325	2.66

Starting Point	Formula
719 C	
POP-TW	55.50
POP-MX	40.00
POP-114	3.73
POP-325	0.77

Starting Point	Formula
720 C	
POP-TW	52.93
POP-MX	40.00
POP-114	5.89
POP-325	1.18

Starting Point	Formula
721 C	
POP-TW	52.50
POP-MX	40.00
POP-114	7.50

Starting Point	Formula
722 C	
POP-066	46.98
POP-MX	40.00
POP-121	11.17
POP-230	1.85

Starting Point	Formula
723 C	
POP-066	46.31
POP-114	23.81
POP-MX	19.99
POP-SB	9.89

UVantage POP

Starting Point	Formula
724 C	
POP-114	88.99
POP-325	11.01

Starting Point	Formula
725 C	
POP-114	79.91
POP-325	11.53
POP-SB	8.56

Starting Point	Formula
726 C	
POP-TW	94.37
POP-114	4.36
POP-325	1.27

Starting Point	Formula
727 C	
POP-TW	77.40
POP-MX	12.92
POP-114	7.54
POP-325	2.14

Starting Point	Formula
728 C	
POP-TW	61.23
POP-MX	23.31
POP-114	12.13
POP-325	3.33

Starting Point	Formula
729 C	
POP-066	45.82
POP-MX	40.00
POP-SB	7.88
POP-165	6.30

Starting Point	Formula
730 C	
POP-066	36.47
POP-MX	28.67
POP-114	18.50
POP-SB	16.36

Starting Point	Formula
731 C	
POP-114	88.20
POP-230	11.80

Starting Point	Formula
732 C	
POP-114	85.10
POP-230	14.90

Starting Point	Formula
7401 C	
POP-TW	93.99
POP-064	5.67
POP-164	0.34

Starting Point	Formula
7402 C	
POP-TW	69.72
POP-MX	20.00
POP-064	9.90
POP-164	0.38

Starting Point	Formula
7403 C	
POP-TW	60.51
POP-MX	20.00
POP-064	18.12
POP-165	1.37

Starting Point	Formula
7404 C	
POP-064	58.15
POP-TW	21.37
POP-MX	20.00
POP-165	0.48

Starting Point	Formula
7405 C	
POP-064	92.97
POP-MX	4.85
POP-165	1.52
POP-325	0.66

Starting Point	Formula
7406 C	
POP-064	95.93
POP-121	3.19
POP-325	0.88

Starting Point	Formula
7407 C	
POP-066	72.09
POP-MX	20.00
POP-SB	6.41
POP-165	1.50

UVantage POP

Starting Point	Formula
7408 C	
POP-064	75.60
POP-MX	19.80
POP-121	4.17
POP-325	0.43

Starting Point	Formula
7409 C	
POP-064	84.17
POP-MX	12.83
POP-164	2.63
POP-325	0.37

Starting Point	Formula
7410 C	
POP-TW	58.91
POP-066	34.32
POP-121	6.77

Starting Point	Formula
7411 C	
POP-066	72.92
POP-MX	20.00
POP-165	5.96
POP-230	1.12

Starting Point	Formula
7412 C	
POP-066	79.93
POP-121	16.93
POP-325	3.14

Starting Point	Formula
7413 C	
POP-064	87.87
POP-164	10.76
POP-325	1.37

Starting Point	Formula
7414 C	
POP-064	55.52
POP-114	34.19
POP-SB	10.29

Starting Point	Formula
7415 C	
POP-TW	70.51
POP-MX	20.00
POP-064	7.29
POP-164	2.20

Starting Point	Formula
7416 C	
POP-064	53.88
POP-165	26.12
POP-MX	20.00

Starting Point	Formula
7417 C	
POP-066	80.62
POP-164	19.38

Starting Point	Formula
7418 C	
POP-121	49.75
POP-TW	48.38
POP-230	1.87

Starting Point	Formula
7419 C	
POP-066	39.87
POP-165	32.98
POP-MX	20.00
POP-SB	7.15

Starting Point	Formula
7420 C	
POP-066	56.26
POP-164	37.38
POP-325	6.36

Starting Point	Formula
7421 C	
POP-SB	36.69
POP-114	35.59
POP-164	27.72

Starting Point	Formula
7422 C	
POP-TW	80.92
POP-MX	16.40
POP-165	1.73
POP-114	0.95

Starting Point	Formula
7423 C	
POP-TW	70.65
POP-165	17.24
POP-121	12.11

UVantage POP

Starting Point	Formula
7424 C	
POP-TW 47.65	
POP-164 32.35	
POP-MX 20.00	

Starting Point	Formula
7425 C	
POP-165 54.05	
POP-066 34.98	
POP-MX 8.34	
POP-SB 2.63	

Starting Point	Formula
7426 C	
POP-121 40.89	
POP-165 37.04	
POP-MX 20.01	
POP-230 2.06	

Starting Point	Formula
7427 C	
POP-165 42.44	
POP-114 37.76	
POP-MX 10.59	
POP-SB 9.21	

Starting Point	Formula
7428 C	
POP-165 43.78	
POP-066 30.94	
POP-SB 25.28	

Starting Point	Formula
7429 C	
POP-TW 96.34	
POP-165 2.46	
POP-SB 1.20	

Starting Point	Formula
7430 C	
POP-TW 96.08	
POP-164 2.40	
POP-SB 1.52	

Starting Point	Formula
7431 C	
POP-TW 71.56	
POP-MX 20.00	
POP-164 5.20	
POP-SB 3.24	

Starting Point	Formula
7432 C	
POP-TW 50.49	
POP-165 22.39	
POP-MX 20.00	
POP-SB 7.12	

Starting Point	Formula
7433 C	
POP-165 49.33	
POP-066 27.06	
POP-MX 19.99	
POP-325 3.62	

Starting Point	Formula
7434 C	
POP-165 47.57	
POP-066 23.97	
POP-MX 18.48	
POP-SB 9.98	

Starting Point	Formula
7435 C	
POP-165 52.78	
POP-066 21.87	
POP-SB 13.89	
POP-MX 11.46	

Starting Point	Formula
7436 C	
POP-TW 99.05	
POP-127 0.59	
POP-164 0.36	

Starting Point	Formula
7437 C	
POP-TW 95.84	
POP-164 3.05	
POP-230 1.11	

Starting Point	Formula
7438 C	
POP-TW 92.53	
POP-165 5.48	
POP-127 1.99	

Starting Point	Formula
7439 C	
POP-TW 91.23	
POP-164 6.58	
POP-230 2.19	

UVantage POP

Starting Point	Formula
7440 C	
POP-TW 66.54	
POP-MX 20.00	
POP-165 11.37	
POP-230 2.09	

Starting Point	Formula
7441 C	
POP-MX 50.00	
POP-165 34.20	
POP-127 15.80	

Starting Point	Formula
7442 C	
POP-MX 50.00	
POP-165 28.99	
POP-127 21.01	

Starting Point	Formula
7443 C	
POP-TW 97.76	
POP-165 1.48	
POP-230 0.76	

Starting Point	Formula
7444 C	
POP-TW 94.55	
POP-165 3.67	
POP-230 1.78	

Starting Point	Formula
7445 C	
POP-TW 73.26	
POP-MX 20.00	
POP-164 3.74	
POP-230 3.00	

Starting Point	Formula
7446 C	
POP-TW 81.45	
POP-165 13.00	
POP-230 5.55	

Starting Point	Formula
7447 C	
POP-MX 49.82	
POP-066 27.99	
POP-127 16.37	
POP-230 5.82	

Starting Point	Formula
7448 C	
POP-MX 47.87	
POP-SB 36.42	
POP-127 11.16	
POP-064 4.55	

Starting Point	Formula
7449 C	
POP-SB 72.76	
POP-164 20.47	
POP-127 6.77	

Starting Point	Formula
7450 C	
POP-TW 78.37	
POP-MX 20.00	
POP-127 0.87	
POP-230 0.76	

Starting Point	Formula
7451 C	
POP-TW 94.69	
POP-230 3.22	
POP-127 2.09	

Starting Point	Formula
7452 C	
POP-TW 91.27	
POP-127 4.55	
POP-230 4.18	

Starting Point	Formula
7453 C	
POP-TW 80.80	
POP-MX 12.60	
POP-230 4.23	
POP-127 2.37	

Starting Point	Formula
7454 C	
POP-TW 68.55	
POP-MX 20.00	
POP-230 7.82	
POP-164 3.63	

Starting Point	Formula
7455 C	
POP-TW 70.25	
POP-230 18.49	
POP-127 11.26	

UVantage POP

Starting Point	Formula
7456 C	
POP-TW	59.72
POP-MX	20.00
POP-165	12.60
POP-230	7.68

Starting Point	Formula
7457 C	
POP-TW	98.86
POP-230	0.90
POP-127	0.24

Starting Point	Formula
7458 C	
POP-TW	74.10
POP-MX	20.00
POP-230	4.85
POP-164	1.05

Starting Point	Formula
7459 C	
POP-TW	64.06
POP-MX	18.97
POP-230	13.18
POP-121	3.79

Starting Point	Formula
7460 C	
POP-TW	44.62
POP-230	35.38
POP-MX	20.00

Starting Point	Formula
7461 C	
POP-TW	53.01
POP-230	24.19
POP-MX	20.00
POP-164	2.80

Starting Point	Formula
7462 C	
POP-TW	47.03
POP-230	41.63
POP-164	11.34

Starting Point	Formula
7463 C	
POP-066	49.54
POP-230	25.58
POP-127	24.88

Starting Point	Formula
7464 C	
POP-TW	95.22
POP-066	2.49
POP-230	2.29

Starting Point	Formula
7465 C	
POP-TW	68.25
POP-MX	20.00
POP-064	5.24
POP-230	6.51

Starting Point	Formula
7466 C	
POP-TW	55.38
POP-MX	20.00
POP-325	12.71
POP-230	11.91

Starting Point	Formula
7467 C	
POP-TW	47.96
POP-MX	20.00
POP-325	16.23
POP-230	15.81

Starting Point	Formula
7468 C	
POP-TW	56.45
POP-230	34.52
POP-SB	9.03

Starting Point	Formula
7469 C	
POP-230	59.22
POP-TW	29.42
POP-SB	11.36

Starting Point	Formula
7470 C	
POP-230	34.94
POP-TW	25.05
POP-SB	20.01
POP-MX	20.00

Starting Point	Formula
7471 C	
POP-TW	96.01
POP-325	2.70
POP-230	1.29

UVantage POP

Starting Point 7472 C POP-TW 79.10 POP-066 7.78 POP-230 6.87 POP-MX 6.25	Formula	Starting Point 7473 C POP-TW 56.04 POP-325 21.08 POP-MX 20.00 POP-164 2.88	Formula	Starting Point 7474 C POP-TW 49.76 POP-230 31.44 POP-066 18.80	Formula	Starting Point 7475 C POP-TW 57.70 POP-MX 20.00 POP-SB 15.14 POP-230 7.16	Formula
Starting Point 7476 C POP-066 59.25 POP-230 33.40 POP-127 7.35	Formula	Starting Point 7477 C POP-TW 37.51 POP-SB 37.30 POP-230 25.19	Formula	Starting Point 7478 C POP-TW 93.19 POP-325 4.41 POP-064 2.40	Formula	Starting Point 7479 C POP-TW 54.08 POP-MX 20.00 POP-325 14.27 POP-064 11.65	Formula
Starting Point 7480 C POP-TW 38.10 POP-325 27.81 POP-MX 19.99 POP-064 14.10	Formula	Starting Point 7481 C POP-325 52.81 POP-064 47.19	Formula	Starting Point 7482 C POP-325 45.74 POP-066 28.73 POP-MX 20.00 POP-TW 5.53	Formula	Starting Point 7483 C POP-064 55.12 POP-325 36.29 POP-127 8.59	Formula
Starting Point 7484 C POP-325 50.71 POP-064 40.19 POP-127 9.10	Formula	Starting Point 7485 C POP-TW 95.07 POP-066 4.26 POP-230 0.67	Formula	Starting Point 7486 C POP-TW 70.17 POP-MX 19.99 POP-064 7.53 POP-325 2.31	Formula	Starting Point 7487 C POP-064 42.05 POP-TW 33.63 POP-MX 20.00 POP-230 4.32	Formula

UVantage POP

Starting Point	Formula
7488 C	
POP-064	51.77
POP-MX	34.25
POP-325	13.98

Starting Point	Formula
7489 C	
POP-064	47.59
POP-MX	42.12
POP-230	8.14
POP-SB	2.15

Starting Point	Formula
7490 C	
POP-064	49.41
POP-MX	33.08
POP-SB	10.81
POP-230	6.70

Starting Point	Formula
7491 C	
POP-064	57.75
POP-MX	21.37
POP-SB	15.40
POP-230	5.48

Starting Point	Formula
7492 C	
POP-TW	55.71
POP-066	22.56
POP-MX	19.99
POP-230	1.74

Starting Point	Formula
7493 C	
POP-TW	66.17
POP-MX	20.00
POP-064	9.26
POP-SB	4.57

Starting Point	Formula
7494 C	
POP-TW	81.29
POP-064	10.27
POP-SB	8.44

Starting Point	Formula
7495 C	
POP-066	91.25
POP-230	7.20
POP-MX	1.08
POP-165	0.47

Starting Point	Formula
7496 C	
POP-064	53.76
POP-325	24.88
POP-114	21.36

Starting Point	Formula
7497 C	
POP-SB	31.03
POP-TW	28.29
POP-064	20.67
POP-MX	20.01

Starting Point	Formula
7498 C	
POP-SB	55.15
POP-064	39.92
POP-325	4.93

Starting Point	Formula
7499 C	
POP-TW	96.21
POP-064	3.31
POP-SB	0.48

Starting Point	Formula
7500 C	
POP-TW	75.46
POP-MX	17.81
POP-066	5.22
POP-SB	1.51

Starting Point	Formula
7501 C	
POP-TW	78.48
POP-MX	12.51
POP-066	6.72
POP-SB	2.29

Starting Point	Formula
7502 C	
POP-TW	81.94
POP-066	14.26
POP-SB	3.80

Starting Point	Formula
7503 C	
POP-MX	50.00
POP-TW	21.68
POP-066	18.19
POP-SB	10.13

UVantage POP

Starting Point	Formula
7504 C	
POP-MX	47.83
POP-066	28.79
POP-SB	19.47
POP-165	3.91

Starting Point	Formula
7505 C	
POP-MX	40.65
POP-SB	29.29
POP-064	17.44
POP-114	12.62

Starting Point	Formula
7506 C	
POP-TW	70.61
POP-MX	25.00
POP-064	3.64
POP-165	0.75

Starting Point	Formula
7507 C	
POP-TW	91.29
POP-066	7.80
POP-121	0.91

Starting Point	Formula
7508 C	
POP-TW	74.80
POP-066	24.22
POP-127	0.98

Starting Point	Formula
7509 C	
POP-TW	54.01
POP-066	44.34
POP-127	1.65

Starting Point	Formula
7510 C	
POP-066	88.07
POP-165	8.42
POP-325	3.51

Starting Point	Formula
7511 C	
POP-064	62.94
POP-114	23.87
POP-SB	13.19

Starting Point	Formula
7512 C	
POP-064	52.23
POP-114	30.98
POP-SB	16.79

Starting Point	Formula
7513 C	
POP-TW	94.12
POP-114	3.65
POP-SB	2.23

Starting Point	Formula
7514 C	
POP-TW	88.31
POP-114	10.30
POP-230	1.39

Starting Point	Formula
7515 C	
POP-TW	78.76
POP-114	19.02
POP-230	2.22

Starting Point	Formula
7516 C	
POP-114	91.64
POP-325	8.36

Starting Point	Formula
7517 C	
POP-114	91.94
POP-325	8.06

Starting Point	Formula
7518 C	
POP-114	55.40
POP-230	16.16
POP-164	14.26
POP-064	14.18

Starting Point	Formula
7519 C	
POP-SB	60.24
POP-114	39.76

UVantage POP

Starting Point	Formula
7520 C	
POP-TW 94.67	
POP-114 3.35	
POP-SB 1.98	

Starting Point	Formula
7521 C	
POP-TW 78.35	
POP-MX 10.86	
POP-SB 5.19	
POP-114 3.95	
POP-230 1.65	

Starting Point	Formula
7522 C	
POP-TW 66.54	
POP-114 22.66	
POP-SB 10.80	

Starting Point	Formula
7523 C	
POP-TW 41.07	
POP-121 31.63	
POP-MX 21.08	
POP-325 6.22	

Starting Point	Formula
7524 C	
POP-066 47.72	
POP-MX 21.71	
POP-165 20.27	
POP-SB 10.30	

Starting Point	Formula
7525 C	
POP-066 48.32	
POP-MX 25.00	
POP-SB 16.23	
POP-165 10.45	

Starting Point	Formula
7526 C	
POP-114 57.07	
POP-SB 22.26	
POP-MX 20.67	

Starting Point	Formula
7527 C	
POP-TW 85.06	
POP-MX 11.71	
POP-114 2.27	
POP-230 0.96	

Starting Point	Formula
7528 C	
POP-TW 90.36	
POP-MX 5.02	
POP-SB 3.86	
POP-114 0.76	

Starting Point	Formula
7529 C	
POP-TW 89.22	
POP-114 7.88	
POP-230 2.76	
POP-164 0.14	

Starting Point	Formula
7530 C	
POP-TW 55.56	
POP-MX 20.01	
POP-SB 14.00	
POP-066 6.44	
POP-114 3.99	

Starting Point	Formula
7531 C	
POP-066 52.21	
POP-MX 25.00	
POP-165 15.27	
POP-230 7.52	

Starting Point	Formula
7532 C	
POP-114 69.33	
POP-230 19.86	
POP-064 10.81	

Starting Point	Formula
7533 C	
POP-SB 55.29	
POP-114 44.71	

Starting Point	Formula
7534 C	
POP-TW 71.97	
POP-MX 25.00	
POP-SB 2.53	
POP-064 0.50	

Starting Point	Formula
7535 C	
POP-TW 89.68	
POP-SB 5.93	
POP-066 4.39	

UVantage POP

Starting Point	Formula
7536 C	
POP-TW	67.14
POP-066	19.60
POP-SB	13.26

Starting Point	Formula
7537 C	
POP-TW	89.84
POP-121	5.28
POP-325	4.88

Starting Point	Formula
7538 C	
POP-TW	67.38
POP-MX	22.70
POP-SB	9.02
POP-325	0.90

Starting Point	Formula
7539 C	
POP-TW	69.00
POP-MX	16.72
POP-SB	13.45
POP-325	0.83

Starting Point	Formula
7540 C	
POP-TW	61.55
POP-SB	36.56
POP-127	1.89

Starting Point	Formula
7541 C	
POP-TW	99.26
POP-230	0.44
POP-127	0.30

Starting Point	Formula
7542 C	
POP-TW	69.21
POP-MX	25.00
POP-230	3.00
POP-121	2.79

Starting Point	Formula
7543 C	
POP-TW	66.52
POP-MX	25.00
POP-121	4.71
POP-230	3.77

Starting Point	Formula
7544 C	
POP-TW	80.57
POP-SB	14.45
POP-230	3.98
POP-127	1.00

Starting Point	Formula
7545 C	
POP-066	35.89
POP-MX	25.00
POP-165	21.69
POP-230	17.42

Starting Point	Formula
7546 C	
POP-SB	43.55
POP-MX	24.99
POP-165	16.37
POP-230	15.09

Starting Point	Formula
7547 C	
POP-SB	83.67
POP-127	13.37
POP-230	2.96